INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR INSPECTION REPORT

Nagpur regional office

Mine file No: MAH/BHD/KYA-22/NGP Mine code: 33MSH05021

(i) Name of the Inspecting : MQ17) ASHISH MISHRA

Officer and ID No.

(ii) Designation : Sr. Asst. Contrl. Mines

(iii) Accompaning mine : Shri Vinod Bhujade, Agent

Official with Designation

(iv) Date of Inspection : 14/01/2020
(v) Prev.inspection date : 07/06/2016

PART-I : GENERAL INFORMATION

1. (a) Mine Name : DIGORI KYANITE MINE

(b) Registration NO. : IBM/7256/2012

(c) Category : B Manual
(d) Type of Working : Opencast

(e) Postal address

State : MAHARASHTRA
District : BHANDARA

Village : DIGORI (MOTHI)
Taluka : LAKHANDUR

Post office : DIGORI (MOTHI)

Pin Code : FAX No. : E-mail :

Phone : (0712)-532200

(f) Police Station

(g) First opening date : 27/11/2001

(h) Weekly day of rest :

2. Address for : "GOKUL", BEHIND LABOUR COURT,

correspondance CIVIL LINES,

DISSTT. - NAGPUR-1, (M. S.) -440001

3. (a) Lease Number : MSH0226 (b) Lease area : 3.96 (c) Period of lease : 30

(d) Date of Expiry

4. Mineral worked : KYANITE Main

5. Name and Address of the

Lessee : PRADEEP M GOLCHHA

""GOKUL"", BEHIND LABOUR

COURT, CIVIL LINES, DISSTT.-NAGPUR NAGPUR

MAHARASHTRA

Phone: (0712)-532200

FAX :

Owner : SHRI PRADEEP M. GOLCHHA

"GOKUL", BEHIND LABOUR COURT, CIVIL LINES,

DISSTT.- NAGPUR-1,(M. S.)

NAGPUR MAHARASHTRA Phone: (0712)-532200

FAX :

6. Date of approval of Mining

Plan/Scheme of Mining

: Fresh under rule 22 MCR1960 04/10/2000 Mining Scheme rule 12 MCDR1988 27/11/2006 Mining Scheme rule 12 MCDR1988 23/07/2012 Mining Scheme rule 12 MCDR1988 19/01/2017

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	Nil	No drilling has been carried out. 1 trench of 10 m and 2 pits of approximate size 2 m X 2 m X 1 m each have been dug to ensure continuity of the ore zone within the working area. Approximate location of the pits and trench is at N1100 to N1200 & E100 to E200 (local grid).	Sillimanite, Quartzite, Pyrophyllite, and Corundum. The lease area is
1b	Exploration ove lease area for geological axis or 2		G-1 (for Sillimanite)	The area was extensively proved by DGM under propecting stage prior to grant of ML. Lessee has also done exploration in form of pitting and trenching. In 2011-12 to 2015-16 period, lessee has drilled 3 inclined core bore holes to prove the occurrence of Sillimanite upto 244 mRL level (General RL is around 270 m).

Location of Working was carried out 2a Working was development proposed as per the location w.r.t.lease area within the proposed. grid N1075 to N1150 & E200 to E300 (local grid) 2b Separate benches There is no Mineral and in topsoil, top soil in waste/overburden are overburden and the area. occurring in the same minerals (Rule Separate bench which are being 15) benches in seggregated after overburden and excavation. minerals is not possible as orebody has a steep dip of 65 to 70 degrees towards west. 2c Stripping ratio Approximately Around 1:7.14 (ROM=263 The variation is or ore to OB 1:1.4 T, Waste=1830 cum) due to lag in the ratio (ROM=2016 cum, actual production. Waste=2940 In the year 2016-17, waste was cum) proposed as 16366 cum and mineral production proposed was 2016 cum. However, actual production was around 110 T and actual waste removal was only 1100 cum. Further, in the last approved proposal period also, overall stripping ratio observed was 1:12 which was supposed to be increased with depth. 2d Quantity of NilNil The area is having topsoil only lateritic soil (Murrum) & no generation in m3 fertile top soil is occurring in the proposed working area. 2e Quantity of 2018-19: 2940 2018-19: 1800 cum

overburden

generation in m3

cum

2f General remarks of inspecting officers on development of pit w.r.t. type of deposit etc

The deposit is steeply dipping in the area that require huge development for exploitation of mineral. ALso, the shape of the lease area has restrictions for working in the hangwall or footwall directions. Due to low demand, the exploitation has been on lower side which has created a lag in development of the deposit due to which, higher waste removal is required to exploit the mineral occurring in the area.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	For major mineral occuring in the area (Sillimanite), there are 4 small existing pits. In the 5 years proposal period, working is proposed in 3 pits located in the noethern part and in the year 2018-19, working is proposed in second pit at location N1075 to N1150 & E200 to E300 (local grid).	Working has been carried out as per the proposed location.	Presently, working is limited only to two pits in the northern part of the lease area due to lag in the actual production.

3b	Quantity of ROM mineral production proposed	2018-19: 4757 T (Sillimanite)	2018-19: 263 T (Sillimanite)
3c	Recovery of sailable/usable mineral from ROM production	70% mineral recovery is proposed from ROM (ROM=2016 cum, Cleaned Ore=1411 cum)	Actual recovery is around 69% (ROM=263 T) Graded Ore Production=183 T)
3d	Quantity of mineral reject generation	2018-19: 1089 T	2018-19: 79 T
3e	Grade of mineral rejects generation and threshold value declared.	Grade of the Mineral rejects is below 35% of Alumina, threshold value is +30% Alumina	As per the proposals
3f	Quantity of sub grade mineral generation.	Nil	Nil
3g	Grade of sub grade mineral generation	Not applicable	Not Applicable
3h	Manual / Mechanised method adopted for segregating from ROM	Manual sorting of ROM	Manual sorting of the excavated ROM
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No such proposals	Nil
3 j	Provision of drilling and blasting in mineral benches	Drilling is carried out by jack hammer drills with 1.5 m hole depth and 34 mm dia. Blasting is carried out by outsourcing to a government authorized vendor.	As per the proposals.

3k Provision of Mining is done As per the proposals, mining by Manual there is no machineries in means and no mechanization and after mineral benches mechanization blasting, all the is there activities are carried except Jack out by manual means. hammer drill & compressor, pumps for dewatering and tractor mounted water tanker (outsourced). 31 Whether height Method of Bench height is as per of benches in mining the proposals. Average overburden and proposed is bench height is ~2 m mineral suitable manual and which is suitable for bench height working through manual for method of mining proposed proposed is means. in MP/SOM 1.5-3 m (asper the occurance of mineral deposit). 3m Total area As per the As on 31.03.2019, Actual covered under last approved area under pits: 1.175 excavation/pits SOM, Existing ha area under pits: 1.15 ha, Additional requirement: 0.20 ha, Total: 1.35 ha (proposal period 2016-17 to 2020-21) Ore to OB ratio Approximately Around 1:7.14 (ROM=263 As per the for the pit/mine 1:1.4 T, Waste=1830 cum) comments given during the year. (ROM=2016 cum, under item 2c. Waste=2940 cum) 30 Total area put Total area put Area under, Pits: 1.175 ha in use under to use under different heads Waste Disposal: 0.698 ha various heads at the end of as on Infrastructure: 0.08 ha 31.03.2020 is year Other Purpose (minerals furnished storage, roads, green under actual belt): 0.60 ha work details. Total: 2.553 ha

3p Production of 2017-18: 4757 2017-18: 361 T ROM mineral T 2016-17: 110 T during the last 2016-17: 4757 2015-16: 120 T five year period T 2014-15: 306 T as applicable 2015-16: 3920 T 2013-14: 450 T T 2013-14: 3920 T

3q General remarks of inspecting officers on method of mining etc.

Method of mining is manual which is as per the proposals. Production and development were on the lower side due to low demand.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	of topsoil, OB	available in the proposed		

4b Location of topsoil, OB and mineral reject dumps

Waste/OB: 9 As per the proposals dumps, 1 main

dump at N1200 to N1300 & E100 to E200, 1 dump at N975 to N1050 & E175 to E200, 2 dumps at N800 to N950 & E200 to E300, 1 Dump at N700 to N800 & E150 to E200, 3 small dumps at N450 to N600 & E200 to E300, 1 dump at N100 to N 250 & E200 to E300 (last 4 dumps for Minor mineral working) Mineral Rejects: 1 stack at N900 to N950 & E200 to E300 (all local grids) 9 Waste/OB

4c Number of dumps within lease area and outside mineral of lease area

dumps and 1 rejects stack, all are within the lease area.

All dumps/stacks are within the lease area.

Location of dumps w.r.t. ultimate pit limit (Rule 16)

4d

Main dump located in northern part of the lease area is outside pit limits. Other dumps (for ultimate pit limits.

As per the proposals. As the orebody is steeply dipping and manual working is proposed, old small dumps are lying within the ultimate pit limit. Presently dumping is being carried out at major mineral) main dump only which is are within the outside the pit limits.

4e Number of active One main dump As per the proposals. and alive dumps. located at northern part is active and alive dump for major mineral. 4 Minor mineral dumps are active. 4f Number of dead 4 dumps for As per the proposals. major mineral dumps. (except the main dump located in northern part) are inactive and dead dumps. These dumps are old dumps. Number of dumps Nil Nil No dumps have been 4q established. stabilized as one dump is main dump for major mineral where active dumping is being caried out. rest of the dump shall be re-handled as per the future requirements. 4h Whether Yes. Garland drains and Retaining wall retaining walls were or garland drain constructed all along the toe of the main all along dumps are there. dump. Other dumps are within the pit limits, thus, instead of retaining walls, bunds have not been constructed, but garland drain have been made all along the dumps. 4i Length of No specific Around 200 m of Retaining wall retaining wall and 500 ${\rm m}$ proposals. or garland drain of garland drain was all along dumps seen during the site inspection. Retaining wall and garland drains were formed all along the main dump. Apart from this, there were bunds along the other small dumps having

around 50-60 m length.

Nil

4ј

Number of

settling ponds

No such

proposals

4k Specific comments of inspecting officer on waste dump management

Waste dump management aspect was found satisfactory in the lease area. Main dump located in the northern part has been properly secured with retaining wall and garland drains. Other dumps are also secured from garland drains as these dumps are very small and are lying within the pit limits.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual wo	rk	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No backfilling is proposed, instead, the area is proposed to be converted into water reservoir at conceptual stage.	Nil		
5b	Area under backfilling of mined out area	No such proposals	Nil		
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No top soil is occuring in the proposed working area and no backfilling is proposed.	Nil		
5d	Total area fully reclaimed and rehabilitated	No such proposals	Nil		

5e General remarks of inspecting officers on backfilling and reclamation etc.

As the surrounding area is agricultural land, no backfilling is proposed. The area is proposed to be converted into water reservoir at conceptual stage.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	To be submitted on or before 30th June every year depicting work done under PMCP in the preceeding year	Yes.	
6b	Area available for rehabilitation (ha) .	Nil	Nil as the area is under active mining for major mineral (Sillimanite) & Minor mineral (Quartzite) both.	
6c	afforestation done (ha).	Plantation is proposed over 0.54 ha upto the conceptual stage	Actual plantation carried out is approximately over 0.30 ha area (Green belt)	
6d	No. of saplings planted during the year	25 saplings	100 Saplings	As the survival is low (~50%), number of saplings planted were high.
6e	Cumulative no .of plants	250 saplings	800 saplings were planted with 50% survival rate. Thus, around 400 saplings are surviving as on date.	
6f	Any other method of rehabilitation	No such proposals	Nil	
6g	Cost incurred on watch and care during the year	Rs 25000/- over plantation, environment monitoring & protective measures.	As per the proposals.	

6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	No such proposals	Nil	
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No such proposals	Nil	
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No such proposals	Nil	
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No such proposals	Nil	The area is proposed to be converted into water reservoir at conceptual stage.
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No such proposals	Nil	
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	is proposed over 0.0225 ha area every	Actual plantation carried out is around 100 saplings over 0.05 ha area near the office.	
бn	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	0.0225 ha	0.05 ha	

60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Plantation	Plantation	
6p	Compliance of environmental monitoring (core zone and buffer zone)	Environment monitoring is proposed and carried out within the core zone as method of working is of manual category only.	As per the proposals, environment monitoring carried out for Air, Water and noise within the core zone as per MoEF guidelines.	
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			PMCP compliance in the area is satisfactory. Protective measures over the dump are constructed and plantation is carried out over around 0.30 ha of non-mineralized land near the office. Environment monitoring is also being carried out by the lessee and all the parameters are within the standard limits prescribed.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual	work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Grade-wise sorting of ROM and then dispatch.	As per	the proposals.	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Manual sorting of ROM	Manual	sorting	

7c	Different grade of mineral sorted out at mines.	Sillimanite: +35% Alumina containing (cleaned ore) below 35% Alumine containing (MIneral rejects)	As per the proposals	
7d	Any beneficiation process at mines .	No such proposals	Nil	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			No beneficiation studies were proposed or carried out. More than 35% Alumina containing material is readily saleable and graded stacks are made accordingly after blending, however, below 35% Alumina containing material, which is mineral reject, is being stacked separately for future usage.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	existing in	Nil	
8b	Concurrent use or storage of topsoil	Not applicable	Nil	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	available in	Separate dumping of waste/OB and mineral rejects is being carried out as per the proposals.	

8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No such proposals	Nil	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No such proposals	Nil	
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	existing		
8g	Survival rate	~70-80%	~50%	Actual plantation carried out has been more to balance the survival rate. Actual survival was lower due to infertile soil, scarcity of water and damage due to cattles.
8h	Water sprinkling on roads to control airborne dust	Yes	Yes, water sprinkling is being done through tractor mounted water tabkers deployed on outsourcing basis (twice daily).	

8i General remarks
of inspecting
officer on
aesthetic beauty
in and around
mines area

Apart from normal degradations due to active minng, aesthetic beauty in and around the area is satisfactory. Plantation is also carried out by the lessee near the office which is in good condition.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	are required to be	MR submitted online upto Dec'2019	
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager		Correct and complete information furnished	

9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	current (O/C) Workings: 1.175 ha	Complete and correct information furnished
9d	Scrutiny of Annual return on afforestation		Complete and correct information furnished
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	For Sillimanite: a. Quantity: 79 T b. Grade: Below 30 % Al203	Complete and correct information furnished
9f	Scrutiny of Annual return on ROM stock and/or graded ore	ROM: Opening Stock &	Complete and correct information furnished. The stock position is also matching with the monthly returns.

9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	859643.80/- Ex. Mine Price: Rs 1902.42/- per T Production Cost: Rs	Complete and correct information furnished. The EMP reported is matching with the computed average sale price from the sale/dispatch data (451.86 T) and sale value furnished.
9h	Scrutiny of Annual return on fixed assets		Complete information furnished.
9k	Scrutiny of Annual return on mining machineries	Nil	No mechanization as per the approved SOM and method of working is Manual. hence, correct information furnished.

PAGE : 21

Details of violations observed during current inspection and compliance position of violation pointed out				
Violat	ion observed	Show couse position		
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on	

Date: (ASHISH MISHRA)

Indian Bureau of Mines