# INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

#### MCDR INSPECTION REPORT

#### Bhubaneshwar regional office

Mine file No : ORI/IRON/SNG/MCDR-20/BBS Mine code : 300RI13043

(i) Name of the Inspecting : U11 ) DAYANAND UPADHYAY

Officer and ID No.

(ii) Designation : Sr. Asst. Contrl. Mines

(iii) Accompaning mine : Shri B. Mohapatra, Geologist

Official with Designation

(iv) Date of Inspection : 10/01/2019

(v) Prev.inspection date : 05/06/2015

PART-I : GENERAL INFORMATION

1. (a) Mine Name : BHANJPALI

(b) Registration NO. : IBM / 8414 /2011

(c) Category : A Other than Fully Mech.

(d) Type of Working : Opencast

(e) Postal address

State : ORISSA
District : SUNDARGARH
Village : BHANJPALI

Taluka : BONAI
Post office : KOIRA
Pin Code : 758038

FAX No. : 06767 273727

E-mail : jnp\_joda@rediffmail.com Phone : 06625-235186 / 06767 2737:

(f) Police Station : Koira

(g) First opening date : 01/10/1997

(h) Weekly day of rest : SUN

2. Address for : VILL. BHANJAPALI, PO. KOIRA

correspondance DIST. SUNDARGARH, ORISSA

PIN. 770048

3. (a) Lease Number : ORIO615

(b) Lease area : 18 (c) Period of lease : 30

(d) Date of Expiry : 31/03/2027

4. Mineral worked : IRON ORE Main

5. Name and Address of the

Lessee : J.N.PATNAIK

BONAIKELA(JODA) KEONJHAR

ORISSA

Phone: 72001, 72101 (JODA), 3332 (KJR), 419734 (BBSR

FAX :72066

Owner : J.N.PATNAIK

BONAIKELA(JODA) KEONJHAR

ORISSA

Phone: 72001,72101JODA

FAX :

Mining Engineer

Name : RAJEEV THAKUR, Full Time

Qualification : B TECH MINING Appointment/ : 01/12/2002

Termination date

Mining Engineer

Name : A.K.PRADHAN, Full Time

Qualification : A.M.I.E
Appointment/ : 15/10/0002

Termination date

Geologist

Name : B.MOHAPATRA, Full Time

Qualification : M SC GEOLOGIST Appointment/ : 01/09/2002 Termination date

Geologist

Name : H.K.SAHU, Full Time

Qualification : MSC GEOLOGIST Appointment/ : 01/02/0002

Termination date

Manager

Name : P.K.SATPATHY

Qualification :

Appointment/ : 01/10/1997

Termination date

6. Date of approval of Mining Plan/Scheme of Mining Scheme rule 12 MCDR1988 15/07/2002 Mining Scheme rule 12 MCDR1988 15/02/2008 Modif.approved Mining Scheme 07/03/2011 Mining Scheme rule 12 MCDR1988 04/07/2014 MP review under 17(1) MCR 2016 31/08/2017

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

## Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	06 number of bore holes in 2016-17.	12 numbers of bore holes have been drilled by lessee in 2018-19 as the earlier mines was closed due to want of EC.	backlog.
1b	Exploration over lease area for geological axis 1 or 2	exploration.	12 numbers of bore holes have been drilled by lessee under G1 Level of exploration.	has been explored
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Not specified.	Exploration agency involved in drilling was M/s Gemco Kati Exploration. Cost incurred in drilling during the year was Rs 12.56 lakh/	Cost incurred in drilling during the year was Rs 12.56 lakh/
1d	Balance area to be explored to bring Geological axis in 1 or 2	9.2 ha during plan period.	About 8.8 ha area has been explored under G1 level by putting 42 nos. of bore holes of total 695meterage drilling.	About 8.8 ha area has been explored under G1 level by putting 42 nos. of bore holes of total 695meterage drilling.
le	Balance reserve as on 01/04/20	Balance reserve as per of review of mining plan approved on 31/08/2017 was: Iron ore- 2090830T under proved category and 507950T was under feasibility resources and 507950T was under feasibility resources.	Balance reserve as on 01/04/2018, Iron ore-2090830T under proved category and 507950T was under feasibility resources and 507950T was under feasibility resources.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

Development :

	Item	Propasals	Actual work	Remarks
	Location of development w.r.t.lease area	Pit-2, N 3170/3220 and E 5650/5700.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
j	Separate benches in topsoil, overburden and minerals (Rule 15)	benches in OB and ore with 6m height, top	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3	Stripping ratio or ore to OB ratio	1:0.42 T/cu.m	Nil.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
1	Quantity of topsoil generation in m3	Not proposed as working was proposed in broken up area,	Nil.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
(	Quantity of overburden generation in m3	16320 cu.m	Nil.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
c c	of inspecting officers on	proposed in	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
Explo	oitation:			
Sl.No.	Item	Propasals	Actual work	Remarks

V=1-0	Caracter Services and Services		m) where we not in	The mines was not
3a	Number of pit proposed for production	single pit	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3b	Quantity of ROM mineral production proposed	66640T	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3c	Recovery of sailable/usable mineral from ROM production	808	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3d	Quantity of mineral reject generation	13328T	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3e	Grade of mineral rejects generation and threshold value declared.	-55% to +45% Fe	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3f	Quantity of sub grade mineral generation.	13328T	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3g	Grade of sub grade mineral generation	-55% to +45% Fe	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3j	Provision of drilling and blasting in mineral benches	DTH drilling of 100mm dia. Blast hole with ANFO as coloumn charge and occasionally 32mm dia. of drill hole by jack hammer	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3k	Provision of mining machineries in mineral benches	JACK HAMMER-2, EXCAVATOR 09	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Bench height- 6m	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
3m	Total area covered under excavation/pits	10.716 ha proposed during approved plan period.	About 7.25 ha. has been covered under existing pit.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

The mines was not The mines was not in 3n Ore to OB ratio 1:0.42/cu.m, in operation since for the pit/mine operation since 13/08/2010 to 13/08/2010 to 2017-18 during the year. 2017-18 due to due to want of EC and want of EC and suspended by DDM Koira. suspended by DDM Koira. The mines was not 3o Total area put Total area Total area exist under proposed under different heads are in operation since in use under 13/08/2010 to different heads different Pit-7.25 ha, waste dump-2017-18 due to 1.901 ha, at the end of heads are want of EC and Pit-10.716 ha, Infrastructure-0.849, year suspended by DDM waste dump- roads-0.12 ha & Mineral Koira. 2.579 ha, storage-0.423, Infrastructure plantation & others --0.849, 1.343 ha. roads-0.12 ha & Mineral storage-0.423, plantation & others -3.313 ha. 2013-14: Nil Nil. The mines was not 3p Production of ROM mineral 2014-15: in operation since during the last 53269T 13/08/2010 to five year period 2015-16: 2017-18 due to want of EC and as applicable 150126T suspended by DDM 2016-17: 186086T Koira. 2017-18: 66640T 3q General remarks Excavation of The mines was not in The mines was not in operation since of inspecting ROM has been operation since proposed in 13/08/2010 to 2017-18 13/08/2010 to officers on method of mining single pit i.e due to want of EC and 2017-18 due to etc. Pit-2 suspended by DDM Koira. want of EC and suspended by DDM Koira.

Actual work

Remarks

Solid Waste Management - Dumping:

Propasals

Sl.No.

Item

4 a	Separate dumping	Separate	The mines was not in	
	of topsoil, OB and mineral rejects (Rule 32,33)	dumping for	operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4b	Location of topsoil, OB and mineral reject dumps	OB Dump- N3620/3730 & E5720/5800, MR Dump- N3550/3600 & E5700/5740.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4c	Number of dumps within lease area and outside of lease area	OB Dump- N3620/3730 & E5720/5800, MR Dump- N3550/3600 & E5700/5740.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	OB Dump- N3620/3730 & E5720/5800, MR Dump- N3550/3600 & E5700/5740.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4 e	Number of active and alive dumps.	N3620/3730 &	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4 f	Number of dead dumps.	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4 g	Number of dumps established.	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

4h	Whether Retaining wall or garland drain all along dumps are there.	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4i	Length of Retaining wall or garland drain all along dumps		The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4j	Number of settling ponds	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
4 k	Specific comments of inspecting officer on waste dump management	Dump-	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

# Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
5b	Area under backfilling of mined out area	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

5e	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Not proposed as pits are not fully exhausted.		The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
5d	Total area fully reclaimed and rehabilitated	Not proposed as pits are not fully exhausted.		용장이 되어 되어 그렇게 하는 기에 되어 있다면 하다는 그 사람이 있다.
5e	General remarks of inspecting officers on backfilling and reclamation etc.	exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	

# Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Not specfied.	Annual return on PMCP has been submitted.	Annual return on PMCP has been submitted.
6b	Area available for rehabilitation (ha) .	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	
6c	afforestation done (ha).	0.362ha.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	

6d	No. of saplings planted during the year	: 580 saplings.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6e	Cumulative no .of plants	Not specified.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6f	Any other method of rehabilitation	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6g	Cost incurred on watch and care during the year	Not specified.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area		The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
61	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
60	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	Not proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6p	Compliance of environmental monitoring (core zone and buffer zone)	Quarterly monitoring	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	580 saplings in 0.362 ha area.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

### Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Gradewise sorting.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Mechanised.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
7c	Different grade of mineral sorted out at mines.	45% to 55% Fe and +55% Fe.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
7d	Any beneficiation process at mines .	N ot proposed.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	Cut off grade of iron ore for the mine is +55%. :Gradewise sorting of ore is proposed.	operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	as working is	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

8b	Concurrent use or storage of topsoil	Not aproposed as working is proposed in broken area.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Separate dumping for overburden and mineral reject.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not proposed as pits are not fully exhausted.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	580 saplings in 0.362 ha area.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
8g	Survival rate	Not specified.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

8h	Water sprinkling on roads to control airborne dust	Water Tanker.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	580 nos. of plantation in 2017-18	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira.

#### Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Monthly & Annual returns are being regularly submitted by lessee.	Monthly & Annual returns are being regularly submitted by lessee.	Monthly & Annual returns are being regularly submitted by lessee.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Graduate Mining Engineer-1, Geologist-1, Surveyor-1	Graduate Mining Engineer-1, Geologist-1, Surveyor-1	Graduate Mining Engineer-1, Geologist-1, Surveyor-1
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	in AR under different heads are Pit-7.25 ha,	Land use pattern not furnished correctly. Shortcomings pointed out through letter	Land use pattern not furnished correctly. Shortcomings pointed out through letter
9d	Scrutiny of Annual return on afforestation	Nil.	Nil.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira

9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Nil.	Nil.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira
9f	Scrutiny of Annual return on ROM stock and/or graded ore	8958.59T, 62-	Closing stock- 8958.59T, 62-65% Fe	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	not in operation since	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira
9h	Scrutiny of Annual return on fixed assets		Fixed asset as furnished in AR is Rs 42203.154/-	Fixed asset as furnished in AR is Rs 42203.154/-
9k	Scrutiny of Annual return on mining machineries	Nil.	Nil.	The mines was not in operation since 13/08/2010 to 2017-18 due to want of EC and suspended by DDM Koira

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed		Show couse position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on
MCDR17 Rule 20	25/01/2019		
Rule 45(5)	25/01/2019		
Rule 46	25/01/2019		
Rule 47	25/01/2019		

Date : 09.04.19

Degonand upochyay

(DAYANAND UPADHYAY)

Indian Bureau of Mines