INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR INSPECTION REPORT

Bhubaneshwar regional office

Mine file No : ORI/IRON-MN/SNG/MCDR-9/BBS Mine code : 300RI13009

(i) Name of the Inspecting: U11) DAYANAND UPADHYAY

Officer and ID No.

(ii) Designation : Sr. Asst. Contrl. Mines

(iii) Accompaning mine : Shri Kathi Pradhan, Mines Manager

Official with Designation

(iv) Date of Inspection : 18/03/2019
(v) Prev.inspection date : 09/03/2016

PART-I : GENERAL INFORMATION

1. (a) Mine Name : KURMITAR(KHANDADHAR)

(b) Registration NO. : IBM/4269/2011

(c) Category : A Fully Mechanised

(d) Type of Working : Opencast

(e) Postal address

State : ORISSA

District : SUNDARGARH
Village : RANTHA
Taluka : BONAIGARH
Post office : BARSUAN
Pin Code : 770041

FAX No. : 06625235228

E-mail : omckurmitarmines@gmail.com

Phone : 06767-275253

(f) Police Station : BARSUAN
(g) First opening date : 29/04/1965

(h) Weekly day of rest : SUN

2. Address for : VILL:SAREIKELA,PO.BARSUAN correspondance : POLICE STATION : BARSUAN

DIST> SUNDARGARH, ORISSA, PIN 770041

3. (a) Lease Number : ORI0039 (b) Lease area : 408.87

(c) Period of lease :

(d) Date of Expiry : 30/12/2038

4. Mineral worked : IRON ORE Main

5. Name and Address of the

Lessee : O.M.C.LTD.

SRI.G.K.DHAL,MD OMC House, P.B.No.34 BHUBANESWAR

KHURDA ORISSA

Phone:

FAX :0674-401629(BBSR),06767-30257

Owner : m/s ORISSA MINING CORPORATION LTD

OMC HOUSE P.B.No.34 BHUBNESHWAR ORISSA Phone: 2393431 FAX: 2391629

Agent : P. K. SWAIN

REGIONAL OFFICE, O.M.C. LTD. PO- KOIRA, DIST-SUNDARGARH SUNDARGARH

ORISSA

Phone: 9437366390 FAX: 06625235228

Geologist

Name : S.MISHRA, Full Time
Qualification : M.Sc (APPLIED GEOLOGY)

Appointment/ : 25/08/2010

Termination date

Manager

Name : KATHI PRADHAN
Qualification : BE(Mining)
Appointment/ : 10/12/2014

Termination date

6. Date of approval of Mining Plan/Scheme of Mining

: Renewal under rule 24 MCR1960 10/03/2006 Mining Scheme rule 12 MCDR1988 23/10/2006 Modif.of approved Mining Plan 25/09/2008 Mining Scheme rule 12 MCDR1988 05/03/2009 Mining Scheme rule 12 MCDR1988 06/04/2010 Modif.approved Mining Scheme 29/11/2010 FMCP under 23C(1) 08/06/2012 Modif.of approved Mining Plan 24/11/2014 08/05/2015 Mining Scheme rule 12 MCDR1988

PAGE : 3

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration:

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	21 number of bore holes in 2017-18	Nil.	As per approved scheme of mining since 2015-16 to 2017-18, 35 bore holes were proposed. Due to want of forest clearance proposed bore holes not carried out. Shortcoming is pointed through violation letter no. ORI/Iron-MN/SNG/MCDR-9/BBS, dated 29/03/2019.
1b	Exploration over lease area for geological axis 1 or 2	G1/G2 level of exploration.	Due to want of forest clearance proposed bore holes not carried out.	Shortcoming is pointed through violation letter no. ORI/Iron-MN/SNG/MCDR-9/BBS, dated 29/03/2019.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Not specified.	Due to want of forest clearance proposed bore holes not carried out.	Shortcoming is pointed through violation letter no. ORI/Iron-MN/SNG/MCDR-9/BBS, dated 29/03/2019.
1d	Balance area to be explored to bring Geological axis in 1 or 2	237.41 ha.	Due to want of forest clearance proposed bore holes not carried out.	Shortcoming is pointed through violation letter no. ORI/Iron-MN/SNG/MCDR-9/BBS, dated 29/03/2019.
1e	Balance reserve as on 01/04/20	As per SOM aprroved on 08/05/2015, proved reserve under 111-107.4MT, 121- 32.74MT, 122-4.87MT and total resources-41.3MT	Balance reserve as on 01/04/2018 under 111-100MT, 121-32.74MT, 122-4.87MT and total resources-41.3MT	Balance reserve as on 01/04/2018 under 111-100MT, 121- 32.74MT, 122-4.87MT and total resources-41.3MT

1f	General remarks
	of inspecting
	officers on
	geology,
	exploration etc

2017-18

21 number of Due to want of forest bore holes in clearance proposed bore holes not carried out.

As per approved scheme of mining since 2015-16 to 2017-18, 35 bore holes were proposed. Due to want of forest clearance proposed bore holes not carried out. Shortcoming is pointed through violation letter no. ORI/Iron-MN/SNG/MCDR-9/BBS, dated 29/03/2019.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area		QUARRY- VI, (2860E-3600 E & 2060N-2864N)	Development is as per proposal.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	_	Separate benches in OB and ore of 6m height have been maintained.	Separate benches in OB and ore of 6m height have been maintained.
2c	Stripping ratio or ore to OB ratio	1:8.56T/cu.m	1:1.6T/cu.m	Stripping ratio is due to less ROM prduction than proposed.
2d	Quantity of topsoil generation in m3	No top soil generation as the working is proposed in broken up area.	Nil.	There is no proposal of top soil as the working is proposed in broken up area.
2e	Quantity of overburden generation in m3	0.58 million cu.m	0.16 million cu.m	Less quantity of OB generated due to less production of ROM than proposed.

2f General remarks The of inspecting development officers on proposed in development of single pit is pit w.r.t. type QUARRY- VI. of deposit etc

The The development is development is proposed in single pit proposed in and bench height is single pit in maintained 6m as per QUARRY- VI. proposal.

The development is carried out within proposed limit.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	Single pit in QUARRY- VI.	Working is concentrated in single pit as proposed.	There are 02 pits. Working is concentrated in single pit as proposed.
3b	Quantity of ROM mineral production proposed	4.97 million T	2399999.890 Т	ROM Production is less due to low market demand.
3с	Recovery of sailable/usable mineral from ROM production	4.47 million T	22,99,700 T	Recovery of saleable ore is less due to less production of ROM.
3d	Quantity of mineral reject generation	0.50Million T	0.10 Million T	Recovery of mineral reject/sub grade generation is less due to less production of ROM.
3e	Grade of mineral rejects generation and threshold value declared.	+45 to 55% Fe	+45 to 55% Fe	Mineral reject/sub grade generated during 2017-18 is +45 to 55% Fe
3f	Quantity of sub grade mineral generation.	0.50Million T	0.10 Million T	Recovery of mineral reject/sub grade generation is less due to less production of ROM.
3g	Grade of sub grade mineral generation	+45 to 55% Fe	+45 to 55% Fe	Mineral reject/sub grade generated during 2017-18 is +45 to 55% Fe.

3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised.	Mechanised.	Mechanised.
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	Not proposed.	Only crushing and sreening is carried out.	Only crushing and sreening is carried out.
3j	Provision of drilling and blasting in mineral benches	DTH drilling of 110mm dia. Blast hole with using Nonel and Nitro compound Cartridge.	Drilling is carried out by 110 mm dia drill machine. Deep Hole blasting is carried out using Nonel and Nitro compound Cartridge.	Drilling is carried out by 110 mm dia drill machine. Deep Hole blasting is carried out using Nonel and Nitro compound Cartridge.
3k	Provision of mining machineries in mineral benches	Excavator-12 Nos., Dumper- 44 Nos., Drill- 6 Nos., Loader- 10 Nos., Crushing & Screen Plant- 3 Nos. Mobile Screen Plant- 4 Nos.	Excavator-10 Nos., Dumper-44 Nos., Drill- 2 Nos., Loader- 6 Nos., Crushing & Screen Plant- 2 Nos.	Excavator-10 Nos., Dumper-44 Nos., Drill- 2 Nos., Loader- 6 Nos., Crushing & Screen Plant- 2 Nos.
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Bench Height- 6 Mtr	Bench height is suitably matched with the excavator.	Bench height is suitably matched with the excavator.
3m	Total area covered under excavation/pits	84.027 ha proposed during approved plan period.	About 65.92 ha area has been covered under excavation pits.	About 65.92 ha area has been covered under excavation pits.
3n	Ore to OB ratio for the pit/mine during the year.	1:8.56T/cu.m	1:1.6T/cu.m	Stripping ratio is due to less ROM prduction than proposed.

Total area covered under Total area covered 30 Total area put Total area in use under proposed under different heads are under different different heads different Pit-65.92ha, Mineral heads are Pitat the end of heads are storage-21.08ha, 65.92ha, Mineral Pit-84.027 ha, Infrastructure-2.25ha, storage-21.08ha, year OB dump-18.74ha Infrastructurewaste dump-27.92 ha, 2.25ha, OB dump-Infrasructure-18.74ha 12.346, roads-4.788 ha, Mineral storage-12.80, sub grade & others -23.07 Production of 3p 2013-14-4.00 2013-14-1.27 MT ROM Production is ROM mineral 2014-15- 0.68 MT less due to low during the last 2014-15-3.74 2015-16-2.4 MT market demand. five year period MT 2016-17-2.4 MT 2017-18-2.4 MT as applicable 2015-16-3.14 МТ 2016-17-4.74 2017-18-4.97 General remarks Excavation of The ROM production has The ROM production has been carried of inspecting ROM has been been carried out in officers on proposed in single pit i.e quarryout in single pit method of mining single pit i.e VI. DTH drilling of i.e quarry-VI. DTH etc. quarry-VI. 110mm dia. Blast hole drilling of 110mm with using Nonel and dia. Blast hole Nitro compound Cartridge with using Nonel alongwith delay and Nitro compound detonator is being Cartridge practiced for drilling alongwith delay and blasting. detonator is being practiced for drilling and blasting.

Actual work

Remarks

Solid Waste Management - Dumping:

Propasals

Sl.No.

Item

4a Separate dumping Separate Separate dumping for There is no top of topsoil, OB dumping for overburden and mineral soil generation. and mineral overburden and reject are maintained. rejects (Rule mineral 32,33) reject. Top soil not proposed. 4b Location of New waste dump Proposed waste dump and Shortcomings are topsoil, OB and sub grade dumps are not in eastern pointed out mineral reject boundary of created are dumping are through violation letter ORI/Irondumps the lease area continued on existing between dumps. MN/SNG/MCDR-9/BBS, coordinate dated 29/03/2019. 1800N to 2200N. New sub grade dump in eastern boundary of the lease area between coordinate 4500E to 4850E and in western boundary of the lease area between coordinate 2300E to 2400E 4c Number of dumps One Waste dump Proposed waste dump and There are two sub within lease between sub grade dumps are not grade dumps and 02 area and outside coordinate created are dumping are waste dumps in the of lease area 1800N to continued on existing lease area. 2200N. Two Sub dumps. There are two sub grade dumps and 02 waste grade dump between dumps. coordinate 4500E to 4850E and between coordinate 2300E to 2400E.

letter.

4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Waste dump between coordinate 1800N to 2200N. Sub grade dump between coordinate 4500E to 4850E and between coordinate 2300E to 2400E.	There are two sub grade dumps in north central side of lease and eastern side of lease and two waste dumps eastern side of lease.	There are two sub grade dumps in north central side of lease and eastern side of lease and two waste dumps in eastern side of lease.
4e	Number of active and alive dumps.	waste dump between coordinate	Proposed waste dump and sub grade dumps are not created are dumping are continued on existing dumps. There are two sub grade dumps and 02 waste dumps.	Shortcomings are pointed out through violation letter ORI/Iron-MN/SNG/MCDR-9/BBS, dated 29/03/2019.
4f	Number of dead dumps.	One dead dump in eastern side of lease.	There is one dead dump in eastern side of lease.	There is one dead dump in eastern side of lease. Slope dump of the stabilised by plantation.
4g	Number of dumps established.	One dead dump in eastern side of lease.	There is one dead dump in eastern side of lease. Slope dump of the stabilised by plantation.	There is one dead dump in eastern side of lease. Slope dump of the stabilised by plantation.
4h	Whether Retaining wall or garland drain all along dumps are there.	and garland	Retaining wall and garland drain have been made along the existing dumps. Retaining wall and garland drain proposed in 2015-16 & 2016-17 are not made as proposed new dumps are not created.	Retaining wall and garland drain proposed in 2015-16 & 2016-17 are not made as proposed dumps are not created. Shortcomings are pointed out through violation

4i	Length of Retaining wall or garland drain all along dumps	and garland	Retaining wall and garland drain proposed in 2015-16 & 2016-17 are not made as proposed new dumps are not created.	Retaining wall and garland drain proposed in 2015-16 & 2016-17 are not made as proposed dumps are not created. Shortcomings are pointed out through violation letter.
4 j	Number of settling ponds	09 nos. of check dams	Check dams proposed are not made as proposed new dumps are not created.	Check dams proposed are not made as proposed new dumps are not created. Shortcomings are pointed out through violation letter.
4k	Specific comments of inspecting officer on waste dump management	between coordinate 1800N to	Proposed waste dump and sub grade dumps are not created are dumping are continued on existing dumps. There are two sub grade dumps and 02 waste dumps.	Shortcomings are pointed out through violation letter ORI/Iron-MN/SNG/MCDR-9/BBS, dated 29/03/2019.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	Not proposed as pits are not exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
5b	Area under backfilling of mined out area	Not proposed as pits are not exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.

5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
5d	Total area fully reclaimed and rehabilitated	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
5e	General remarks of inspecting officers on backfilling and reclamation etc.	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Not specified.	Annual return on PMCP has been submitted.	Annual return on PMCP has been submitted.
6b	Area available for rehabilitation (ha) .	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
6c	afforestation done (ha).	500 Nos. of plantation proposed in outside of lease. Area not specified.	In 2017-18, about 500 nos. of tree planted outside the lease in 0.5 ha area.	In 2017-18, about 500 nos. of tree planted outside the lease in 0.5 ha area.
6d	No. of saplings planted during the year	500 Nos. of plantation.	In 2017-18, about 500 nos. of tree planted outside the lease.	In 2017-18, about 500 nos. of tree planted outside the lease.
6e	Cumulative no .of plants	Not specified.	Cumulative nos. of saplings planted in the lease area is about 101800 nos.	umulative nos. of saplings planted in the lease area is about 101800 nos.

6f	Any other method of rehabilitation	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
6g	Cost incurred on watch and care during the year	Not specified.	Around Rs. 1,80,000/- cost incurred on watch and care.	Around Rs. 1,80,000/- cost incurred on watch and care.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area		Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	Not proposed.	Nil.	There is no proposal of waste land.

6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	Not proposed.	Nil.	There is no proposal of waste land.
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Not proposed.	Nil	There is no proposal of waste land.
6p	Compliance of environmental monitoring (core zone and buffer zone)	Quarterly monitoring	Quarterly monitoring of air, water and noise level are being carried out.	Quarterly monitoring of air, water and noise level are being carried out.
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	and	Pits are not matured for backfilling and reclamation and rehabilitation. Quarterly monitoring of air, water and noise level are being carried out.	Pits are not matured for backfilling and reclamation and rehabilitation.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Gradewise sorting.	Gradewise sorting is being practiced.	Gradewise sorting is being practiced.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Mechanised.	Mechanised.	Mechanised.
7c	Different grade of mineral sorted out at mines.		Different grades of minerals sorted out at mines are 45% to 55% Fe and +55% Fe.	Different grades of minerals sorted out at mines are 45% to 55% Fe and +55% Fe.

7d	Any beneficiation process at mines .	Not proposad.	Only crushing and screening Of ROM is being practiced.	Only crushing and screening Of ROM is being practiced.
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	Gradewise sorting of +45% to 55% Fe and +55% Fe.	Different grades of minerals sorted out at mines are 45% to 55% Fe and +55% Fe.	Different grades of minerals sorted out at mines are 45% to 55% Fe and +55% Fe.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Not proposed.	Nil.	No top top soil generation is proposed.
8b	Concurrent use or storage of topsoil	Not proposed.	Nil.	No top top soil generation is proposed.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Separate dumping for overburden and mineral reject.	Separate dumping for overburden and mineral reject are maintained.	Separate dumping for overburden and mineral reject are maintained.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not proposed as pits are exhausted.	Pits are not matured for backfilling and reclamation and rehabilitation.	Pits are not matured for backfilling and reclamation and rehabilitation.

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	_	In 2017-18, about 500 nos. of tree planted outside the lease.	Cumulative nos. of saplings planted in the lease area is about 101800 nos.
8g	Survival rate	Not specified.	As reported survival rate is 92%.	As reported survival rate is 92%.
8h	Water sprinkling on roads to control airborne dust	sprinkler	Water sprinkler 6 nos. (12 KL) are used to control air borne dust.	Water sprinkler 6 nos. (12 KL) are used to control air borne dust.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	plantation in 2017-18.	In 2017-18, total 500 nos of saplings have been planted by lessee. As reported cumulative no. of trees planted by lessee is about 101800 nos.	Aesthic beauty in and aroun mined area is maintained by plantation.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns		Monthly & Annual returns are being regularly submitted by lessee.	Monthly & Annual returns are being regularly submitted by lessee.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	status of mining engineer,	The employment status of mining engineer, geologist & mine manager have been furnished in the annual return submitted for the year 2017-18.	The employment status of mining engineer, geologist & mine manager have been furnished in the annual return submitted for the year 2017-18.

9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.		Pit-65.92ha, Plant building roads etc- 4.585ha, OB dump-18.74ha	Pit-65.92ha, Plant building roads etc-4.585ha, OB dump-18.74ha
9d	Scrutiny of Annual return on afforestation	500nos. of plantation.	500nos. of plantation.	500nos. of plantation.
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Nil.	Nil.	Closing stock of - 55 % Fe(Fines)- 61612.785T
9f	Scrutiny of Annual return on ROM stock and/or graded ore	58-60 %	Closing stock: 58-60 % Fe(Lump)- 16375.935T, 62-65 % Fe(Lump)-410115.345T, +65 % Fe(Lump)-1525.625T 51-55 % Fe(Fines)- 61612.785T, 55-58 % Fe(Fines)-93800.00T, 60- 62 % Fe(Fines)- 1513259.055T, 62-65 % Fe(Fines)- 6814.265T	Closing stock: 58-60 % Fe(Lump)- 16375.935T, 62-65 % Fe(Lump)- 410115.345T, +65 % Fe(Lump)-1525.625T 51-55 % Fe(Fines)- 61612.785T, 55-58 % Fe(Fines)- 93800.00T, 60-62 % Fe(Fines)- 1513259.055T, 62- 65 % Fe(Fines)- 6814.265T
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Price: 62-65 %	Ex- Mines Price: 62-65 % Fe (Lump) -Rs 3102.00/-, 60-62 % Fe (Fines) -Rs 1096.00/-	Ex- Mines Price: 62-65 % Fe (Lump) -Rs 3102.00/-, 60- 62 % Fe (Fines) - Rs 1096.00/-
9h	Scrutiny of Annual return on fixed assets	Fixed asset : Rs.1,82,74,806	Fixed asset : Rs.1,82,74,806/-	Fixed asset : Rs.1,82,74,806/-

9k	Annual return on mining	Nos., Dumper-40 Nos.,	1 Nos., Loader- 7 Nos.,	Excavator- 10 Nos., Dumper- 40 Nos., Drill- 1 Nos., Loader- 7
			2 Nos., Dozer- 1 No., Tanker- 6 Nos.	Nos., Crushing & Screen Plant- 2 Nos., Dozer- 1 No.,
		Dozer- 1 No., Tanker- 6 Nos.		Tanker- 6 Nos.

PAGE: 18

Details of violations observed during current inspection and compliance position of violation pointed out

Violation	n observed	Show couse position	
Rule NO.	Issued on Compliance or	Rule NO.	Issued on Compliance on
MCDR17 Rule 11(1)	29/03/2019		

Date:

(DAYANAND UPADHYAY)

Indian Bureau of Mines