

**REPORT ON CHECK UP INSPECTION OF UMSOO-MOOTANG BLOCK-V MINE OF
M/s ADHUNIK CEMENT LTD. SITUATED IN VILLAGE THANGSKAI, TEHSIL NARPUH,
DISTRICT JANTIA HILLS, STATE MEGHALAYA**

File No: IBM/GHY/MEG/JNH/Lst-14

Mine code/ Lease code: 38MEG03015

Name & Designation of the Inspecting Officer: PK Bhattacharjee, RCOM

Date of inspection: 30.1.2018

1. General Information about the Mine:

- (i). Mine Name: Umsoo Mootang Block-V
- (ii). Owner: M/s Adhunik Cement Ltd.
- (iii). Nominated owner: S/Shri. R.A.Krishna Kumar
- (iv). Mining Engineer: Shishupal Singh
- (v). Geologist: Neelabh Saxena
- (vi). Agent: Sanjay Kumar
- (vii). Mines Manager: Shishupal Singh
- (viii). Lease Area: 128.52 Ha.
- (ix). Location: Village-Thangskai, Tehsil-Narpuh, Distt. – Jaintia Hills, Meghalaya
- (x). Lease Period: 50 years
- (xi). Date of Expiry: 20.12.2066
- (xii). Date of Approval of Mining Plan: 29.4.2010 (from IBM Nagpur)
- (xiii). Date of Approval of Modification/Review of Mining Plan/Mining Scheme/FMCP etc. 29.8.2017 (from IBM Guwahati)
- (xiv). Period of Mining Plan/Mining scheme/FMCP: 2017-18 to 2020-21

2. Status of compliance of MCDR'2017 during the last 3 years:

SN	Date of Inspection	Name of Inspecting Officer	Violation of MCDR, 1988/2017 Observed & pointed out	Rectification of violation	Remarks
The mine has been opened on 12.7.17 and has not been inspected by any officer of IBM there after					

3. Observations/ remarks on the earlier inspection carried out by sub-ordinate officer(s) with specific thrust on systematic and scientific mining, mineral conservation and environmental protection and other sensitive/important aspects pertaining to the mine area or surroundings (CRZ/ Western Ghats/ Wildlife Sanctuaries etc.):

- 1) Name of inspecting officer: The mine has not been inspected by any officer of IBM after its opening on 12.7.17.
- 2) Date and Type of inspection: The mine has not been inspected by any officer of IBM after its opening on 12.7.17.
- 3) Observations/Remarks w.r.t. the inspection carried out by the sub-ordinate officer(s) and shortfalls in the inspection report, if any, thereof: The mine has not been inspected by any officer of IBM after its opening on 12.7.17.

4. Communication / Direction(s) issued to the concerned RCOM/ IO based on the check-up inspection for further necessary action accordingly: The mine has not been inspected by any officer of IBM after its opening on 12.7.17. However, the observations on the present inspection are given below:-
The lessee has signed a MDPA wherein the minimum production quantities differ from the modified mining plan. State Govt. to be apprised of the issue with information to IBM, HQ..

Place: Guwahati

Date: 8.2.18


Signature