

## भारत सरकार खान मंत्रालय

## भारतीय खान ब्यूरो, क्षेत्रीय कार्यालय रायपुर दूसरी मंजील, जीएसआई फील्ड प्रशिक्षण केन्द्र

महालेखाकार आफिस कोम्प्लेक्स, पोस्ट् -विधान सभा- रायपुर- (छ.ग)-492005 फोन- 0771--2282530/2285590/95 <u>मेल- ro.raipur.ibm@gmail.com</u>

## No- CHG/BBR/LST-01/NGP

दिनांक -19/02/2020

प्रेषिति- श्री विवेक गुप्ता,नामित खान मालिक M/S स्टील अथॉरिटी ऑफ इंडिया लिमिटेड इस्पात भवन,लोधी रोड,

न्यू दिल्ली-110003

न्यू दिल्ला-110003
विषय- छत्तीसगढ़ राज्य के रायपुर जिले मे स्थित आपकी राजहारा मेकेनाइस्ड आइरन ओर खान (Area 220.42 Ha.) ॰ मे खनिज सरक्षण एवं विकास नियमावली 2017 के नियमों के उलंघन के संबंध मे-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 04.02.2020 by undersigned accompanied by Shri P.M.Shirpurkar, Agent Mine and Shri Shamshad Raza, DGM geology

Shamshau Kaza,DGW geology					
Rule	Nature of Violation observed				
11(1)	Mining operations should have been undertaken in accordance with the approved Mining Plan/Review of Mining Plan.				
	The Review of Mining Plan was approved vide letter no. बलोद/ लौह /खयो-1146/2018-रायपुर dated 26.05.2018 and				
	following deviation was observed during inspection				
	1. There was a proposal of 05 boreholes in 2019-20 but till date the drilling not yet started neither any intimation regarding drilling/exploration given.				
	2. The backfilling was not done as per proposal and only 30% of the proposal is implemented.				
	3. The plantation is proposed 600 nos saplings in 2018-19 and 8725 nos in 2019-20 but negligible afforestation done				
	and for 2018-19 only 150 reported in annual return.				
37(2)	The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause				
	degradation of environment and to prevent causation of floods. It was observed that there is no proper terracing and				
	the OB/waste dump is near to lease boundary but still no proper retaining wall is constructed nor any control measures				
	for dump stability.				
45(5)(c)( i)	While scrutiny of Annual returns 2018-19 it was observed that				
	The Ex-mine price is given as Rs 1157/- for lump and 1190/- for fines and the cost of production is mentioned as				
	Rs1270/- As the mine is of captive used therefore Ex-mine price and cost of production should be same. There are				
	other deficiencies observed i.e. land use and reserve/resource is different w.r.t approved document. In the return it is				
	mentioned that the mine is having 9 benches and depth of working is 90 meter whereas actually the difference between				
	top and bottom RL is more150 meter.				
_					

- इस संदर्भ मे आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमो का उल्लंघन खिनज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंइनीय अपराध है1 एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खिनज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत
  - (क) खान की सारी खनन संक्रियाए बंद की जा सकती है1
  - (ख) आपके विरुध अभियोग दायर किया जा सकता है 1
  - (ग)खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है1
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंधनो का अतिशिघ्र सुधार करे एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करे1

भवदीय

(राजेश कुमार दास) वरिष्ठ सहायक खान नियंत्रक भारतीय खान ब्यूरो, रायपुर

## प्रतिलिपि – for information please

- 1 खान नियंत्रक(मध्य), भारतीय खान ब्यूरो , नागपुर
- 2 संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ, इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिटल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ

वरिष्ठ सहायक खान नियंत्रक भारतीय खान ब्यूरो, रायप्र