

VIOLATION LETTER REGD/AD

Hkkjr ljdkj
[kku ea-ky;
Hkkjr h; [kku C; jks
{ks-h; [kku fu; æ-d dk dk; k; y;
ibmbbsr@dataone.in



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines.

File No. ORI/IRON/KJR/MCDR-25/BBS	Mahani Complex, 2 nd Floor 308, District Centre, Chandrasekharpur Bhubaneswar-751 016 Ph-(0674)2742463 / Fax-0674 2744430
-----------------------------------	---

To,
Shri Bibani Prasad Mohanty, Partner
M/s Kalinga Mining Corporation.
Jaruri Iron Ore Mines
Samanta Niwas, Shaik Bazar
Po/Dist- Cuttack, Odisha 752052

Dated %04.06.2013

Sub: Violation of provisions of MCDR, 1988 in respect of Joruri Iron ore Mine (73.228 Ha) of M/s KMC., in Keonjhar District of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 03.05.2013 by the undersigned and accompanied by S/Shri Smruti Ranjan Behera, Mines Manager and D Manoharan, Geologist of your mine.

Rule No.	Nature of Violation
Rule 13(1)	<p>1. Mining operations are not being carried out in accordance with the Modification to the approved Scheme of Mining letter no 314(3)/2011MCCM(CZ)/MS/58dated 26.04.2012 to the extent indicated below:-</p> <p>I. Retaining wall along bottom periphery of Sub grade stock has not been maintained effectively to prevent escape off stocked material there from.</p> <p>II. Retaining wall along bottom periphery of Sub-grade ore stock near MI Pillar-A to L2 has not been maintained effectively to prevent wash off of ore there from.</p>
16(1)	<p>The overburden and waste material obtained during mining operations shall not be allowed to be mixed with non-sable or sub-grade minerals/ ores. They shall be dumped and stocked separately.</p> <p>During inspection of mines it was observed that, in Village pit, waste material has been dumped over sub-grade ore stock, they are not dumped/ stocked separately.</p>
Rule 27(4)	<p>Plans and sections required as per the provision of rule 28 of MCDR 1988 have not been maintained updated within three months.</p> <p>Surface plan maintained at the site is not matching with actual field conditions in respect of ore stocks, development of bench etc.</p>
45(5)(b)(i)	
45(5)(b)(i)	Annual return submitted for the year 2011-12, does not show the quantity of ROM ore mined at the mine head.
42(1)(b)(i)	A whole time Geologist having 10 (ten) years of professional experience has not been employed as require under the provision of amended rules.

Contd...page 2

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

इब्राहिम शरीफ / (IBRAHIM SHARIEF)

I gk; d [kku fu; æ-d/ Assistant Controller of Mines

ewy ifr ij ugh / Not on Original ifrfyfi fuEu dks l knj l pufkZ vxsf"kr

- (1) [kku fu; æ-d(e/; kpy)/The Controller of Mines (CZ), Hkkjrh; [kku C; jks@
Indian Bureau of Mines, ukxi j /Nagpur-440 001.
- (2) Mk; jDVj vkW ekbll /The Director of Mines, Mk; jDVksj/ vkW ekbll @Directorate of Mines, mMAt k l j dkj
/Government of Orissa, gMI vkW fmi kVz/ fcYMx /Heads of Department Building, U; w dsi Vy /New
Capital, Hkpus'oj /Bhubaneswar-751 001

(IBRAHIM SHARIEF)

I gk; d [kku fu; æ-d/ Assistant Controller of Mines

drs {ks-h; [kku fu; æ-d/For Regional Controller of Mines