

**VIOLATION LETTER REGD/AD**

Hkkjr ljdkj  
[kku ea-ky;  
Hkkjr h; [kku C; jks  
{ks-h; [kku fu; æ-d dk dk; k; y;  
[ibmbbsr@dataone.in](mailto:ibmbbsr@dataone.in)



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of Mines.

File No. ORI/IRON/KJR/MCDR-1/BBS	Mahani Complex, 2 <sup>nd</sup> Floor 308, District Centre, Chandrasekharpur Bhubaneswar-751 016 Ph-(0674)2742463 / Fax-0674 2744430
----------------------------------	---

To,  
The Managing Director  
M/s Odisha Mining Corporation Ltd.  
OMC House, Bhubaneswar, Odisha  
PIN - 751 001

Dated %06.05.2013

**Sub: Violation of provisions of MCDR, 1988 in respect of Khandband Iron ore Mine (366.311 Ha) of M/s OMC LTD., in Keonjhar District of Odisha State.**

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 04.05.2013 by the undersigned and accompanied by S/Shri Gourang Charan Rout, Mines Manager and D Manoharan, Geologist of your mine.

Rule No.	Nature of Violation
Rule 13(1)	1. Validity of the approved scheme of mining for your above mine has been expired on 31.03.2013. At present, there is no valid proposals in the form of Scheme of mining for carrying out mining operations in the lease area; there by attracting violation of rule 13(1) of MCDR'88. 2. Mining operations are not being carried out in accordance with the Modification to the approved Scheme of Mining letter no 314(3)/2011 MCCM(CZ)/MS/33dated 11.11.2011 to the extent indicated below:- <ul style="list-style-type: none"> <li>It was proposed to explore 47 no. of bore holes during the year 2011-12 &amp; 43 no. of bore holes during the year 2012-13, against which only 30 no. of bore holes were carried out so far.</li> </ul>
Rule 27(4)	Surface Plans maintained updated under the provision of rule 28 of MCDR 1988 at the site is not matching with actual field conditions in respect of sub grade ore stocks exists in the lease area.
33(2)	In deposit-VI, Retaining wall along bottom periphery of ore stock yard and dump yard has not been maintained effectively to prevent wash off of ore and waste material there from.
42(1)(b) (i)	A whole time Mining Engineering having 10 (ten) years of professional experience has not been employed as per the provision of amended rule.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

इब्राहिम शरीफ / (IBRAHIM SHARIEF)

I gk; d [kku fu; æ-d/ Assistant Controller of Mines

ey ifr ij ugh / Not on Original ifrfyfi fuEu dks l knj l pukFkz vxS"kr

- (1) [kku fu; æd(e/; lpy)/The Controller of Mines (CZ),Hkkjrh; [kku C; jks@  
Indian Bureau of Mines, ukxi j /Nagpur-440 001.
- (2) Mk; jDVj vkND ekbll /The Director of Mines,Mk; jDVkjv vkND ekbll @Directorate of Mines,mMM k l j dkj  
/Government of Orissa, gMI vkND fMi kVeV/ fcYMæ /Heads of Department Building, U; u dSi Vy /New  
Capital, Hkpus'oj /Bhubaneswar-751 001

(IBRAHIM SHARIEF)

I gk; d [kku fu; æd/ Assistant Controller of Mines  
drs {ks-h; [kku fu; æd/For Regional Controller of Mines