

VIOLATION LETTER**REGD/ A D**

Hkkjr ljdkj
[kku ea=ky;
Hkkjrh; [kku C;wjks
{ks=h; [kku fu;a=d dk
dk;kZy;



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines.
Ph-(0674)2742463 / Fax-0674 2744430

ibmbbsr@dataone.in

File No. ORI/IRON/KJR/MCDR-43/BBS	Mahani Complex, 2 nd Floor 308, District Centre, Chandrasekharpur Bhubaneswar-751 016 Ph-(0674)2742463 / Fax-0674 2744430
-----------------------------------	---

To,

Date : .09.2013

Shri Kamal Jeet Singh Ahluwalia, Mine Owner

NUAGAON IRON ORE MINE

Post Box No - 3,

At/po - Barbil- 758035

Dist Keonjhar, Odisha

Sub: Violation of provisions of MCDR, 1988 in respect of Nuagaon Iron Ore Mine (767.284 ha) of Shri K.J.S. Ahluwalia, in Keonjhar District of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 04.09.2013 by the undersigned accompanied by Shri A. K .Bhuyan, General Manager & Shri S. Mandal, Mines Manager of your mine.

Rule No.	Nature of Violation
33(2)	In Katasahi Block, Fines Stock/Sub-grade dump No. 20 (located near ML boundary pillar nos. 78 to 81) and Near MDH quarry, Fines Stock No. 31 A (located near ML boundary pillar nos. 31 to 32) have not been properly secured (by retaining wall, garland drain etc.) to prevent escape of material and surface wash-off there from in harmful quantities, which may cause degradation of environment.

03. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.

Besides, inability to comply the provision of Rule 13 (1) is also liable for suspension of mining operations under the provisions of rule 13 (2) of MCDR, 1988.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(PREM PRAKASH)
Sr. Assistant Controller of Mines

ewy izfr ij ugh / Not on Original izfrfyfi fuEu dks lknj lwpukFkZ vxzsf"kr

- (1) [kku fu;a=d(e;/kazpy)/The Controller of Mines (CZ),Hkkjrh; [kku C;wjks@ Indian Bureau of Mines, ukxiqj /Nagpur-440 001.
- (2) Mk;jsDVj vkWQ ekbUI /The Director of Mines,Mk;jsDVksjsV vkWQ ekbUI@Directorate of Mines,mM+hlk ljdkj /Government of Orissa, gsMI vkWQ fMikVZesaV fcfYMax /Heads of Department Building, U;w dSfiVy /New Capital, Hkqous'oj /Bhubaneswar-751 001 :
Safety zone area has been encroached by dumping between ML Boundary Pillars 106 to 110. Also, Safety Zone fencing & plantation have not been carried out between ML Boundary Pillars 10 to 29, 53 to 74 and 127 to 143 .

(PREM PRAKASH)

Sr. Assistant Controller of Mines

d`rs {ks=h; [kku fu;a=d/For Regional Controller of Mines