INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

Mining Plan Modification REPORT

Hyderabad regional office

Mine file No : AP/KNL/FE-58/HYD Mine code: 30APR11024

(i)Name of the Inspecting : RK13) A.V.Ramesh Kumar

Officer and ID No.

(ii) Designation : Assistant Mining Geologis

(iii) Accompaning mine : Sri Sripad Bhat Qualified Person

Official with Designation

(iv) Date of Inspection : 03/07/2021

(v) Prev.inspection date

PART-I : GENERAL INFORMATION

(a) Mine Name : RAMAKRISHNA(31.17 HA)

(b) Registration NO. : IBM/4404/2001

: A Other Mechanised (C) Category

(d) Type of Working Opencast

(e) Postal address

> State : ANDHRA PRADESH

District KURNOOL

Village SARPRAJPURAM

Taluka DHONE

Post office : SARPRAJPURAM

Pin Code : 518217

FAX No.

E-mail SRK.MINERALS@YAHOO.IN

Phone : 08516-275729

(f) Police Station : VELDURTHI First opening date : 01/01/1975 (g)

Weekly day of rest (h) : SUN

Address for : SMT T.VIJAYAGOWRI correspondance

NO.8/106, NEHRU NAGAR

KURNOOL DISTRICT, ANDHRA PRADESH

3. (a) Lease Number :

> (b) Lease area : Period of lease (C) (d) Date of Expiry

Mineral worked 4. : IRON ORE Main

PAGE : 2

5. Name and Address of the

Lessee : SREE RAMAKRISHNA MINERALS

8/106,NEHRU NAGAR VELDURTHI

MANDAL KURNOOL ANDHRA

PRADESH

Phone: 08516-275729

FAX :

6. Date of approval of Mining : Renewal under rule 24 MCR1960 02/03/2007

Plan/Scheme of Mining

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	There is no proposal for the year 2020-21	No exploration was carried out duirng the year 2020-21	The Mining operations are under suspension from 30.10.2017.
1b	Exploration over lease area for geological axis 1 or 2	 L	The area under G1 scale is 11 ha and G2 scale is 3 ha.	
1c	Exploration Agencies and Expenditure in lakh rupees during the year			
1d	Balance area to be explored to bring Geological axis in 1 or 2		26 ha to be explored for upgrading to G1 scale	. None
1e	Balance reserve as on 01/04/20		(111)-222651 tonnes (122) - 15,900 tonnes (222) - 275901 tonnes	None
1f	General remarks of inspecting officers on geology, exploration etc			

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area			The mining operations are under suspension from 30.10.2017
2b	Separate benches in topsoil, overburden and minerals (Rule 15)			
2c	Stripping ratio or ore to OB ratio			
2d	Quantity of topsoil generation in m3		No topsoil generated earlier	
2e	Quantity of overburden generation in m3		The actual waste reported from 2011-12 to 2016-17 was 86100 tonnes	None

2f General remarks --of inspecting
officers on
development of
pit w.r.t. type
of deposit etc

The inspection was carried out for review of Mining Plan submitted by the lessee.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production		There are 5 pits	
3b	Quantity of ROM mineral production proposed			
3c	Recovery of sailable/usable mineral from ROM production			
3d	Quantity of mineral reject generation			
3e	Grade of mineral rejects generation and threshold value declared.			
3f	Quantity of sub grade mineral generation.			
3h	Manual / Mechanised method adopted for segregating from ROM			
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.			
3j	Provision of drilling and blasting in mineral benches			
3k	Provision of mining machineries in mineral benches			

31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	 	
3m	Total area covered under excavation/pits	 11 ha	
3n	Ore to OB ratio for the pit/mine during the year.	 	
30	Total area put in use under different heads at the end of year	 20 ha	
3p	Production of ROM mineral during the last five year period as applicable	 	The Mining operations are under suspession since 30.10.2021
3q	General remarks of inspecting officers on method of mining etc.	 	

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)			
4b	Location of topsoil, OB and mineral reject dumps			
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)		Three dumps were noticed.	
4e	Number of active and alive dumps.			
4f	Number of dead dumps.			
4 g	Number of dumps established.		03	

4h	Whether Retaining wall or garland drain all along dumps are there.			
4i	Length of Retaining wall or garland drain all along dumps			
4j	Number of settling ponds	nIL	nIL	nIL
4k	Specific comments of inspecting officer on waste dump management		None	None

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.			
5b	Area under backfilling of mined out area			
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)			
5d	Total area fully reclaimed and rehabilitated			
5e	General remarks of inspecting officers on backfilling and reclamation etc.		No area was mined out nor recalimed till date	none

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	 	
6b	Area available for rehabilitation (ha).	 	
6c	afforestation done (ha).	 The lease area is in the forest.Lot of dense vegetation was noticed.	
6d	No. of saplings planted during the year	 	
6e	Cumulative no .of plants	 	
6g	Cost incurred on watch and care during the year	 50000 as reported by the lessee	
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	 	
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area	 	
бт	Compliance of rehabilitation of waste land within lease (i)afforestation	 	
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	 	
6р	Compliance of environmental monitoring (core zone and buffer zone)	 	

6q General remarks -- -- None of inspecting officers on PMCP compliance and progressive closure operations etc.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area			The mining operations under suspension since 30/10/2017.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.			
7c	Different grade of mineral sorted out at mines.			
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)			
8b	Concurrent use or storage of topsoil			
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use			

8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	 	
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	 	
8h	Water sprinkling on roads to control airborne dust	 	
8i 	General remarks of inspecting officer on aesthetic beauty in and around mines area	 	

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns			
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	As per the Annual return 2020-21,Sri Khaja Babu is the Mining Engineer	The same was observed during the inspection	Lessee informed that as the Mining operations are under suspension as soon as the suspension is revoked and mining operations resume, will appoint the Geologist.

9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	various heads is as follows Area under	Same was noticed duirng the inspection.	None
9d	Scrutiny of Annual return on afforestation		580 no.s	None
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)		None	None
9f	Scrutiny of Annual return on ROM stock and/or graded ore		The same was noticed duirng the inspection.	The mining operation are under suspension since October 2018.No production reported duirng the period of suspension.
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	The ex-mine price reported in the Annual return was Rs.820/- per tonne	The mining operations are under suspension. As such the ex-mine price could not be ascertained.	None
9h	Scrutiny of Annual return on fixed assets	Nil	None	None
9k	Scrutiny of Annual return on mining machineries	No machinery reported in Annual return 2020-21	Same was noticed duirng the inspection	None

PAGE : 11

Details of violations observed du violation pointed out	uring current inspection and compliance position of
Violation observed	Show couse position

Violation observed			Show couse position	
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on Compliance on

Date :

(A.V.Ramesh Kumar)

Indian Bureau of Mines