

भारत सरकार /Government of India

खान मंत्रालय/Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757

Fax No. : (0832) –2741758

E-Mail : ro.goa@ibm.gov.in

File No:- KNT/BJP/Fe-1/GOA, Vol-III,

Opp.Old R.T.O.'s Office,

P.O. FATORDA - 403602,

Margao-GOA

Date:-11.12.2017

Mine Code:-30KAR05002

To,
M/s. Doddanavar Brothers,
Mine Owner & Exporters,
Corporate office,738/1,
Kanapur Road, Near 3rd Railway Gate,
Belagavi, Karnataka-590008.

Sub :Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Hiremagi, Ramthal Iron Ore Mines (M.L.No-2394), over an extent of 39.20 Ha. Situated in Hiremagi & Ramthal villages, Tq- Hungund, in Bagalkot District of Karnataka State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 24/11/2017(F/N), by the undersigned in presence of Amit Ghooli Asst. Mines Manager.

Rule	Nature of Violation observed
11(1)	<p>The mining operation in the lease area are not carried out as per approved Scheme of Mining dated 23.04.2015 and following deviations are observed during inspection.</p> <p>a) In the approved Scheme of Mining there was a proposal to drill 5 core boreholes to a total depth of 201 mtrs in the year 2015-16 and 5 core boreholes to a depth of 269 mtr in the year 2016-17. During inspection it was observed that no such exploration was done by the lessee.</p> <p>b) The year wise production and development for the year 2015-16, 2016-17 and 2017-18 is not carried out between the co-ordinates and RL's as mentioned in the approved Scheme of Mining. The benches were not maintained properly as mentioned in the approved document.</p> <p>c) Production and development for the year 2015-16 is not carried out as per the proposal and 100% (Negative) deviation is there. In the year 2016-17 there was a proposal to rehandle about 40000 Cub mtr from the dump for recovery of ore. During inspection it was observed that no such dump rehandling was done.</p> <p>d) The waste dumping is not made as per the proposal shown on production and development plates for the year 2015-16,2016-17 and 2017-18. Between BP-1, BP-7 and BP-8 it appears dump was extended beyond lease boundary also. Bench terraces are not maintained.</p>

26(2)	An yearly report before 1st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted for the year 2015-16 and 2016-17 so far.
27(1)	The differential financial assurance for the mining and allied activities as per MCDR 2017 is not paid for the entire area as shown in the PMCP chapter of approved Scheme of mining.
Rule 45(5)(c)	a) In the annual returns submitted for the year 2016-17 at para 4.1 under exploration it is stated that 32 boreholes were drilled to a depth of 280 mtrs and 11 trenches and 9 pits were made. However during inspection it is noticed that no such exploration is carried out by the lessee. b) Reserves and reserves shown in the annual returns are incorrect. UNFC codes and quantity are not matching with the approved document. c) The ROM production given at para 4.2(A) and Part VI are not matching. d) At part vii production proposal for the year 2016-17 is shown as zero. e) Production and stock positions mentioned under part-VI (2) and (3) are mismatching.
55(1)(3)(iii)	The Mining Engineer and Geologist required under the said rule is not appointed by the lessee.
67	A self appraisal note to be submitted by the mines owner/lessee stating extent of implementation of approved mining plan/scheme of mining during the year 2015-16 and 2016-17 along with supporting plan & sections, representative photographs is not submitted to this office so far in hard as well as soft copy.

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Forty five) days from the date of issue of this letter.

Yours faithfully,

(Kalmata.M.K)
Senior Mining Geologist
Indian Bureau of Mines

Copy forwarded to: -

1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
2. The Director, Directorate of Geology & Mining, Govt. of Karnataka, Khanij Bhavan, Race Course Road, Bengaluru-1.

(Kalmata.M.K)
Senior Mining Geologist
Indian Bureau of Mines

