



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINE



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
Bengaluru/ बेंगलुरु -560022

सं/No.: KNT/TMK/FE/23/BNG Mine-code: 40KAR19021 दिनांक/Dated: 19/08/2022

To,

Smt. Dr. Mathura Bai
M/s Karnataka Limpo Cement Industries
No. 64, 2nd Floor, Railway Parallel Road
Kumara Park West, Bangalore - 560020

विषय/Subject: Violation of provisions of MCDR 2017 in respect of your Karekurchi Iron ore and Mn Ore Mine (ML No. 2028) over an extent of 16.19 Ha located in Karekurchi village, Tipatur Taluk, Tumkur District of Karnataka State

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 12/08/2022 by undersigned along with Shri H.M. Shivakumar, AME in presence of Shri A.M. Rudraiah, Mining Engineer cum Mines Manager and Sri Karunakar M.A., Asst. Mines Manager

Rules	Nature of Violations observed
11(1)	<p>The Mining operations required to be carried out in accordance as per the approved Modified Review and Updation of Mining Plan document vide letter no. 279/780/2003/BNG dated 06/03/2020, However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>(i) For the 2021-22, float ore production proposed between section line A1-A1' to B-B' to C-C' in between the grids 685616E – 685724 and 1475369N – 1475523 N, however it is observed that, production & development/excavation are not carried out at the proposed location.</p> <p>(ii) During the year 2021-22, it was proposed to construct 368m Retaining wall and 473m Garland drain all along the toe of the waste dump - PD-2 and 2 nos. of check dams and 10 nos. of Gully plugs. During the inspection it is observed that construction of Retaining wall, garland drain check dams and Gully plugs are not constructed as proposed.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Dr. Sudhakara T.L.)

Senior Mining Geologist

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Dr. Sudhakara T.L.)

Senior Mining Geologist