

मेल/त्वरितडाकद्वारा



भारतसरकार /GOVERNMENT OF INDIA
खानमंत्रालय/ MINISTRY OF MINES
भारतीयखानब्यूरो /INDIAN BUREAU OF MINES
क्षेत्रीयखाननियंत्रककार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियलसबर्बाIIस्टेज,,तुमकुरोड,
गोरगुंटापाल्यायेशवंतपुर,
बेंगलुरु -560022

सं.KNT/BLR/FE/125/BNG

दिनांक:19.07.2021

सेवामें/To,
Shri. Syed Ahmed,
M/s Zeenath Transport Company,
Zeenath House, Cowl Bazaar,
Ballari-583 102,
Karnataka State.

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Dharmapur Iron Ore Mine (ML. No 2309, Mine code: 30KAR03055) over an area of 36.42 Ha located in Ramgad village, Sandur Taluka, Ballari district of Karnataka State

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned along with Shri. H M Shiva Kumar-Assistant Mining Engineer in presence of Shri. Pampapathi Garke - Manager Mines, Shri. Shashidhara L -Mining Engineer & Sri Kummara Anil Kumar - Geologist on 21.06.2021

Rule	Nature of violations observed
11(1)	Modified RMP along with PMCP was approved vide letter no.279/68/89/BNG dated 22.09.2020 for a period of 2020-21 to 2024-2025. The deviation observed in mining operation vis-a-vis approved document are given below It was proposed to extract 69500 Tons of iron ore and remove 5148 Tons of Overburden in the year 2020-21.During the inspection it was observed that only 36000 Tons of ore were extracted and 2668 Tons of overburden were handled.
47	It was observed that 13 core bore holes, 26 DTH and 18 trial pits were carried out in the mine against the proposal of 7 core bore holes and 17 DTH drilling as submitted in Form I. Revised Form I may be submitted to this office.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुण कुमार)/Arun Kumar

उप खान नियंत्रक/Dy. Controller of Mines

भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपि सूचनार्थ /Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhan, R.C. Road, Bangalore-560 001

Sd/-

उप खान नियंत्रक/Dy. Controller of Mines

भारतीय खान ब्यूरो/Indian Bureau of Mines