

**INDIAN BUREAU OF MINES
MINERALS DEVELOPEMMENT AND REGULATION DIVISION**

MCDR inspection REPORT

Kolkata regional office

Mine file No : CAL/BH/SB(W)/FE(M-3)

Mine code : 30JHK18001

- (i) Name of the Inspecting : **K004**) **B.P KERKETTA**
Officer and ID No.
- (ii) Designation : Sr. Asst. Contrl. Mines
- (iii) Accompanying mine : Mr Ratan Kr Patri, Mining Engineer , Mr R K. Naik, Geolo
Official with
Designation
- (iv) Date of Inspection : 14/03/2020
- (v) Prev.inspection date : 13/06/2007

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **MANOHARPUR (MACLELLAN)**
- (b) **Registration NO.** :
- (c) Category : A Other than Fully Mech.
- (d) Type of Working : Opencast
- (e) Postal address
- State : JHARKHAND
- District : SINGHBHUM (WEST)
- Village : MACLELLAN
- Taluka : MANOHARPUR
- Post office : CHIRIA
- Pin Code : 833106
- FAX No. :
- E-mail : momchiria@gmail.com
- Phone : 9308128776
- (f) Police Station : CHIRIA
- (g) First opening date : 10/03/1960
- (h) Weekly day of rest : SUN
2. Address for :
correspondance
3. (a) Lease Number : JHK0001
- (b) Lease area : 823.83
- (c) Period of lease :
- (d) Date of Expiry : 08/12/2025
4. Mineral worked : IRON ORE Main

5. Name and Address of the

Lessee : STEEL AUTHORITY OF INDIA LTD.
 INDUSTRY HOUSE 5TH & 6TH
 FLOOR 10, CAMAC STREET
 KOLKATA WEST BENGAL
 Phone:033-22822316/0462/3385
 FAX :033-22822316/0462

Owner : Amarendu Prakash
 Steel Authority Of India
 Limited Bokaro Steel Plant
 Bokaro-827001 SINGHBHUM
 (WEST) JHARKHAND
 Phone: 05642240300,024
 FAX : (06542)240/82

Agent : R.P.SINGH
 MANOHARPUR(Mc LELLAN)IRON
 ORE MINE
 P.O.CHIRIA,DIST.WEST
 SINGHBHUM JHARKHAND STATE
 SINGHBHUM (WEST) JHARKHAND
 Phone: 8986881005
 FAX :

Mining Engineer

Name : R.K.Patri,Full Time
 Qualification : B.Tech (Min.)
 Appointment/ : 18/01/2019
 Termination date

Geologist

Name : Dr.RAJESH KUMAR NAIK,Full Time
 Qualification : MSc (Geo)
 Appointment/ : 14/11/2014
 Termination date

Manager

Name : RAVI RANJAN
 Qualification : B.TECH(MINING)
 Appointment/ : 18/01/2019
 Termination date

6. Date of approval of Mining	:	Renewal under rule 24 MCR1960	03/03/2008
Plan/Scheme of Mining	:	Mining Scheme rule 12 MCDR1988	27/05/2016
	:	MP review under 17(1) MCR 2016	27/12/2019

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	There was no proposal for drilling in 2018-19	No boreholes drilled during 2018-19.	
1b	Exploration over lease area for geological axis 1 or 2	There was no proposal during 2018-19	Entire area has been explored in the 200 X 200 m and 400 X 400 m Grid pattern previously. A total 109 no. of boreholes have been drilled in the entire lease area. Total meterage drilled was 9929.6 m. Hence entire lease area can be put in G2/G1 category for the reserve estimation.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	No Proposal	No Exploration Done in 2018-19	
1d	Balance area to be explored to bring Geological axis in 1 or 2	No Proposal	No Exploration has been done in 2018-19.	No Exploration has been done in 2018-19. Entire area has to be explored in G1 Axis
1e	Balance reserve as on 01/04/20		Balance Reserve as on 01/04/2020 Total Probable Reserve - 837.6 Million Tonnes(Probable 121:604.6Tonnes+Probable 122:233Tonnes) Total Resources - 930.7 Million Tonnes	
1f	General remarks of inspecting officers on geology, exploration etc	No Exploration was proposed for 2018-19 and no exploration has been done in 2018-19	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance.

Development :

Sl.No.	Item	Proposals	Actual work	Remarks
--------	------	-----------	-------------	---------

2a	Location of development w.r.t.lease area	2 Locations - Quarry no.8 and North pit	No Development work has been carried out during 2018-19.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Seperate benches of OB and minerals are proposed.	No work done in OB & Mineral Benches, Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
2c	Stripping ratio or ore to OB ratio	1:0.119 (T/m3)	No work has been carried out during 2018-19	
2d	Quantity of topsoil generation in m3	Nil	No work has been carried out during 2018-19.	
2e	Quantity of overburden generation in m3	500156 m3 OB/ Topsoil proposed for generation during 2018-19	No work has ben carried out during 2018-19.	
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc		Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

3a	Number of pit proposed for production	02 Pits (North Pit & Quarry No.8) proposed for production.	No production has been done during 2018-19	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
3b	Quantity of ROM mineral production proposed	During 2018-19, 3.92 Million Tonnes were proposed for production	No Production has been carried out during 2018-19	This mine is not working since December '2005 for want of Stage II Forest clearance.
3c	Recovery of sailable/usable mineral from ROM production	Recovery factor is based on the proportion of ore types as mentioned in the geological exploration report, carried out M/s MECL. As per the geological report, the ratio of overburden: Lump ore zone: Powdery ore zone: non ore band within the ore zone on the basis of tonnage are in proportion of 0.17:1.1, 52:0.07. From this recovery of ore is around 91% on the basis of tonnage. Bulk Density is 3 as per the Geological Report.	No Recovery has been made in 2018-19.	This mine is not working since December '2005 for want of Stage II Forest clearance.

3d	Quantity of mineral reject generation	No Proposal for Mineral Reject generation.	No Mineral Rejects generated during 2018-19	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	
3e	Grade of mineral rejects generation and threshold value declared.	No Proposal	No Mineral Rejects generated in 2018-19.	do-	-
3f	Quantity of sub grade mineral generation.	102050cum. sub-grade mineral generation	No Sub-grade Mineral Generated during 2018-19	do-	-
3g	Grade of sub grade mineral generation	45 % Fe to 57 % Fe = Grade of Sub grade Mineral Generation.	No Sub-grade Mineral Generated during 2018-19	do-	-
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised.	No ROM Screening done in 2018-19	do-	-
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No proposal proposed	No beneficiation study carried out for sub grade mineral rejects.	do-	-
3j	Provision of drilling and blasting in mineral benches	Provision of drilling and blasting in mineral benches present.	No drilling and blsting done in mineral benches.	do-	-
3k	Provision of mining machineries in mineral benches	Mining Machineries in Mineral Benches proposed.	No Mining Machineries in Mineral Benches were seen during inspection as No work for want of Stage II Forest Clearance.	do-	-

3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Bench height 6 m Bench width 10 m	Bench height of 6 m and Bench width of 10 m were found during inspection.	
3m	Total area covered under excavation/pits	Details of existing Pits. Quarry No. -8 = Length 507 m X Bredth 846 m = 428922 m2 = 42.8922 Ha Quarry No.-6 = Length 313.5 m X Bredth 23 m = 7210.5 m2 = 7.21 Ha Quarry No.-5 = Length 98 m X Bredth 94 m= 9212m2 = 9.21 Ha. Total = 59.31 Ha.	Details of existing Pits. Quarry No. -8 = Length 507 m X Bredth 846 m = 428922 m2 = 42.8922 Ha Quarry No.-6 = Length 313.5 m X Bredth 23 m = 7210.5 m2 = 7.21 Ha Quarry No.-5 = Length 98 m X Bredth 94 m= 9212m2 = 9.21 Ha. Total = 59.31 Ha.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
3n	Ore to OB ratio for the pit/mine during the year.	Ore to OB Ratio = 1:0.119	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
3o	Total area put in use under different heads at the end of year	Existing Pits = 59.31 Ha. Dumps = 11 Ha.	Existing Pits = 59.31 Ha. Dumps = 11 Ha. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.

3p	Production of ROM mineral during the last five year period as applicable	Production of ROM In Million Tonnes 2015-16 = 1.52 2016-17 = 4.00 2017-18 = 3.96 2018-19 = 3.92 2019-20 = 3.9	Production of ROM In Million Tonnes 2015-16 = NIL 2016-17 = NIL 2017-18 = NIL 2018-19 = NIL 2019-20 = NIL	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
3q	General remarks of inspecting officers on method of mining etc.	Method of mining proposed is open cast mining with forming benches and drilling and blasting in the mialal benches. But Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Method of mining proposed was open cast mining with forming benches and drilling and blasting in the mialal benches. But Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	There is proposal for seperate dumping of topsoil OB and mineral Rejects.	There is minimal amount of topsoil so generation of topsoil could not be accounted how ever ob & mineral rejects generated earlier have been dumped seperately. But Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance.

4b	Location of topsoil, OB and mineral reject dumps	OB and mineral rejects dumps are proposed to be dumped within the lease area.	OB and mineral rejects dumps are dumped within the lease area. But Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4c	Number of dumps within lease area and outside of lease area	NE side of the Northern Pit within the lease area.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	NE side of the Northern Pit within the lease area.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4e	Number of active and alive dumps.	One Dump of area 1ha	No active and alive dumps as Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4f	Number of dead dumps.	Four Fines Dump (Total 116760Tonnes)	No waste dump noticed. The area has not been worked since December '2005 for want of Stage II Forest Clearance. Four Dead Fines Dump (Total 116760Tonnes). Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4g	Number of dumps established.	Four Fines dead dump to be established by plantation.	Four Fines dead dump established naturally by growth of vegetation.

4h	Whether Retaining wall or garland drain all along dumps are there.	Proposal for retaining wall and garland drain.	Retaining wall present.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4i	Length of Retaining wall or garland drain all along dumps	Proposal of settling ponds at the end of retaining wall	Settling pond present at the end of retaining wall.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4j	Number of settling ponds	One	One	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
4k	Specific comments of inspecting officer on waste dump management		No waste generated and dumped during last year i.e. 2018-19.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan. This mine is not working since December '2005 for want of Stage II Forest clearance.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	Full extraction of mineral before backfilling.	Mineral has not been fully extracted.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.

5b	Area under backfilling of mined out area	No Proposal	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Concurrent use of Topsoil for restoration has been proposed.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
5d	Total area fully reclaimed and rehabilitated	No such proposal	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
5e	General remarks of inspecting officers on backfilling and reclamation etc.		Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).		Annual Report on PMCP submitted.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
6b	Area available for rehabilitation (ha) .	Nil	Mines is non-working for want of Stage II Forest Clearance.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
6c	afforestation done (ha).	Nil	Nearly 15 Ha of land has been afforested.	This mine is not working since December '2005 for want of Stage II Forest clearance.
6d	No. of saplings planted during the year	Nil	600 saplings planted outside lease area during the year.	This mine is not working since December '2005 for want of Stage II Forest clearance.
6e	Cumulative no .of plants	Nil	Afforestation has been taken up over mined out areas and outside lease areas near Chiria Township. So far he mine management have planted nearly 1,04,035 trees in township, hospital, guest house, camps and office areas. Trees that have been planted are Babul, Acacia, Jamun Karanj, Neem, Teak, Amrud(Gwava), Gamhar, Sisam, Ashoka, Sal, Bija, Asan, Mango, etc.	This mine is not working since December '2005 for want of Stage II Forest clearance.
6f	Any other method of rehabilitation	Nil	Not applicable	This mine is not working since December '2005 for want of Stage II Forest clearance.

6g	Cost incurred on watch and care during the year	Nil	Nearly 1.00 Lakhs Rupees	- do-
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	Nil	Not applicable	- do-
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	Nil	Not applicable	- do-
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestation on backfilled area	Nil	Not applicable	- do-
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	Nil	Not applicable	- do-
6l	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	Nil	Not applicable	- do-
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	Nil	Not applicable	- do-
6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	Nil	Not applicable	- do-

6o	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Nil	Not applicable	- do-
6p	Compliance of environmental monitoring (core zone and buffer zone)	Proposal for monitoring in Core Zone and Buffer Zone	No monitoring done as Mines is non-working.	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.		Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Proposal for grade wise sorting.	No work done.	This mine is not working since December '2005 for want of Stage II Forest clearance.
7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	Mechanical	No work done.	
7c	Different grade of mineral sorted out at mines.	>58% Fe	No work done	
7d	Any beneficiation process at mines	No such proposal	No work done.	

7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.	This mine is not working since December '2005 for want of Stage II Forest clearance. Stage-II Forest clearance is still awaited. Hence, work could not be commenced as proposed in the previous approved Mining plan.
----	--	--	---

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Proposal for topsoil removal wherever present as minimal amount of topsoil is present within the lease area.	No work done.	This mine is not working since December '2005 for want of Stage II Forest clearance.
8b	Concurrent use or storage of topsoil	Storage of Topsoil	No work done.	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Proposal for Seperate dumps for OB Wsate rock rejects and fines.	No work done.	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Proposal for restoring in its original land use.	No work done.	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Phase restoration.	No work done.	

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	No such proposal	600 saplings planted outside lease area during the year.	
8g	Survival rate	No such proposal	60%	
8h	Water sprinkling on roads to control airborne dust	Proposal for water sprinkling on roads to control airborne dust.	no work done as mines was non-working.	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area		This mine is not working since December '2005 for want of Stage II Forest clearance.	As the mines lies in the Saranda Reserve forest ; good greenery lies in and around the Mines.The aesthetic beauty is good in and around the mines area.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns		Monthly and annual returns submitted on time.	
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mr. Ratan Kumar Patri, Mining Engineer and Dr. Rajesh Kumar Naik, Geologist	Mining Engineer and geologist appointed were present during the Inspection.	

9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Area covered under current O/C working 160ha.,waste disposal area 4.59ha.,Area Occupied by plant, buildings, residential, welfare buildings & roads 5.561ha.,Other Purpose (Mineral Storage & Aforesattion) 18.117ha.	No work has been carried out hence ther is no change in land use pattern commpared to last year.
9d	Scrutiny of Annual return on afforestation	600nos of saplings planted outside the lease area with survival rate 60%	Found correct.
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	No mineral reject generated and nothing mentioned in Returns	Found correct.
9f	Scrutiny of Annual return on ROM stock and/or graded ore	ROM Opening & closing Stock 22665MT. Closing Stock of Graded Lumps: 55% to below 58% Fe 78569.56MT, 62% to below 65% Fe 31334.52MT, Clo sing Stock of Fines: Below 55% Fe 116760.93MT	Graded Ore stock present in the mine
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Sale Value, Ex. Mine Price& Production cost given as Nil	Mines is non-working
9h	Scrutiny of Annual return on fixed assets	Rs. 1375521931/-	Appears to be correct.

9k Scrutiny of DOZER 320HP : Mining Machineries
Annual return on lno. present but not in
mining operation, as mines is
machineries non-working.

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed		Show couse position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on

Date :

(B.P KERKETTA)

Indian Bureau of Mines