

REPORT ON CHECK UP INSPECTION OF Kendadih Copper MINE OF M/s Hindustan Copper Ltd. SITUATED IN VILLAGE Kendadih DISTRICT East Singhbhum STATE Jharkhand

File No:

Mine code 14BHR27001

Name & Designation of the Inspecting Officer: PK Bhattacharjee, RCOM

Date of inspection: 18.9.2021

1. General Information about the Mine:

- (i). Mine Name: **Kendadih Copper Mine**
- (ii). Owner: **M/s Hindustan Copper Ltd.**
- (iii). Nominated owner: **Mr. Sanjay Panjiyar**
- (iv). Mining Engineer: **Mr. Sampath Kr. Sangi**
- (v). Geologist: **Mr. Amit Degvekar**
- (vi). Agent: **Mr. SK Singh**
- (vii). Mines Manager: **Mr. Sampath Kr. Sangi**
- (viii). Lease Area: **1139.6 Ha.**
- (ix). Location: **Kendadih Copper Mine**
- (x). Lease Period: **As per MMDR Act, 2015**
- (xi). Date of Expiry: **Upto 2.6.2023**
- (xii). Date of Approval of Mining Plan: **21.12.2017**
- (xiii). Date of Approval of Modification/Review of Mining Plan/Mining Scheme/FMCP etc. **25.11.2020 (MMP)**
- (xiv). Period of Mining Plan/Mining scheme/FMCP: **1.4.2020 to 2.6.2023**

2. Status of compliance of MCDR'2017 during the last 3 years:

SN	Date of Inspection	Name of Inspecting Officer	Violation of MCDR,2 017 Observed & pointed out	Rectification of violation	Remarks
1	17.7.2019	N Ekka, JMG	11(1), 26(2) & 35(2)	28.10.2019	-
2	1.1.2020	GS Kanan, SMG	45(5)(b)	14.2.2020	Office scrutiny
2	23.7.2021	GS Kannan, SMG	35(2)	17.8.2021	Office scrutiny
3	25.8.2021	OP Gopal, RMG	45(7), 45(6)	-	In process.

3. Observations/ remarks on the earlier inspection carried out by sub-ordinate officer(s) with specific thrust on systematic and scientific mining, mineral conservation and environmental protection and other sensitive/important aspects pertaining to the mine area or surroundings (CRZ/ Western Ghats/ Wildlife Sanctuaries etc.):

- 1) Name of inspecting officer: **As mentioned in table 2 above.**
- 2) Date and Type of inspection: **As detailed in table 2 above (MCDR/ SDF inspection)**
- 3) Observations/Remarks w.r.t. the inspection carried out by the sub-ordinate officer(s) and shortfalls in the inspection report, if any, thereof: **The mine is presently under development wherein the production is achieved through development. The proposal given for stoping has been returned as there has been difference in the position of proposed stope location from the drawings submitted vis a vis approved in the last mining plan. The house keeping of the mine was not upto mark as the haulage tracks were found submerged in water at many places.**

4. Communication / Direction(s) issued to the concerned IO based on the check-up inspection for further necessary action accordingly: There is a need for modification of the mining plan prior to approval of any stoping permission requested.

Place: Ranchi
Date: 27.9.2021


Signature