

भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



REGD. POST
Phone: 0674-2352463
TeleFax: 0674-2352490
E-mail: ro.bhubaneshwar@ibm.gov.in
Plot No.149, Pokhariput
BHUBANESWAR-751020

No. MPM/OTFM/14-ORI/BHU/2017-18

Date: 04.10.2017

To

Shri Vivek Lall, Mine Owner, Plot No- H/1, 7 & 8 Area, Civil Township, Rourkela, Sundargarh Odisha- 769004

Sub: Approval of Modification of Mining Plan of Jharbeda Limestone & Dolomite Mine along with Progressive Mine Closure Plan (PMCP), over an area of 87.906 ha in Sundargarh district of Odisha State, submitted by Shri Vivek Lall under Rule 17 of MCR, 2016.

Ref: - i) Your letter No. Nil dated 29.08.2017 received on 18.09.2017.

ii) This office letter of even no. dated 18.09.2017.

iii) This office letter of even no. dated 18.09.2017 addressed to Director of Mines, Government of Odisha copy endorsed to you.

Sir.

This has reference to the letter cited above on the subject. The draft of Modification of Mining Plan along with Progressive Mine Closure Plan (PMCP) has been examined in this office based on earlier site inspection carried out on 09.06.2017 by Shri G C Sethi, Deputy Controller of Mines. The deficiencies observed are enclosed herewith as Annexure I.

You are advised to carry out the necessary modifications in the draft Modification of Mining Plan along with Progressive Mine Closure Plan in the light of the contents vide Annexure I and submit three (3) firm bound and two (2) soft copies of the document text in CD in a single MS Word file (the drawing/plates in Auto CAD compatible format or JPG format in resolution of 100x100 pixels on same CD) with financial assurance under Rule 27 of MCDR 2017 of the Modification of Mining Plan within 15 (fifteen) days from the date of issue of this letter, for further necessary action. If the total page of annexures exceeds 50 (Fifty) then it should be submitted as separate volume. But reference of these annexures must appear in the Modification of Mining Plan document. The plates are also to be submitted in separate volume.

The para-wise clarifications and the manner in which the deficiencies are attended should invariably be given while forwarding the modified copies of the Modification of Mining Plan along with Progressive Mine Closure Plan. It may be noted that no extension of time in this regard will be entertained and the Modification of Mining Plan along with Progressive Mine Closure Plan will be considered for rejection if not submitted within above due date. It may also be noted that if the deficiencies are not attended completely, the submission would be liable for rejection without further correspondence.

भवदीय / yours faithfully,

क्षेत्रीय खान नियंत्रक / Regional controller of Mines

& DOLOMITE MINE OF SHRI VIVEK LALL, OVER AN EXTENT OF B7.906 HECTARES, LOCATED IN JHARBEDA & TUNMURA VILLAGES, UNDER KUTRA TAHASIL OF SUNDARGARH DISTRICT OF ODISHA STATE, SUBMITTED UNDER RULE 17(1) OF MCR, 2016.

(1) The copy of the explosive procurement license issued by the competent authority in favour of the applicant has not been enclosed. Besides, a copy of the blasters license issued by the competent authority for carrying out blasting operations may also be submitted.

(3) The ambient air quality analysis, flue gas, effluent, soil, surface water, noise level & vibration level monitoring reports has not been enclosed and the data for the same for all four seasons should be submitted for ease in monitoring.

(3) No photographs in support of existing quarry, backfilling, existing waste dump, boundary pillars existing exploration, afforestation & rehabilitation etc. have not been enclosed and the same should also be submitted for more informative.

(4) In case of individual or partner, a declaration/affidavit should be submitted to know whether he is working in other firms/company/organization etc.

(5) The dimension of the existing quarries has been furnished in tabular form but the location coordinates of such quarries is missing, which should be furnished by adding one more column in the table for more informative. (Para 4.5.1)

(6) Already drilled status of DTH/non-core and core drill holes are furnished but the litho logs for such boreholes are missing, which should be furnished and the para may be revised accordingly. (Para 4.5.2)

(7) The proposed exploration schedule in the form of bore holes for the year 2017-18 has been furnished but the holes are coring or non-coring type has not been specified. Besides, the balance unexplored area should be explored before 31.03.2018. Accordingly, the exploration proposal given in the para under reference should be revised. (Para 4.9)

(8) The bulk density test and recovery test for limestone & dolomite from NABL accredited laboratory has not been furnished and the same should be submitted for more informative.(Para 4.12.1)

(9) The status existing quarries & dumps has been furnished in tabular form but nothing has been mentioned about the existing status of reclamation, rehabilitation, afforestation etc. The same may be furnished and the para may be revised accordingly. (Para 5.1.1)

(10) Plate-II (Surface Plan): At least three permanent ground control points situated beyond the lease area has not been selected, which should be done. Besides, latitude and longitude of those ground control points need to be furnished and those ground control points should be linked with boundary pillars. Moreover, Surveyor's signature is missing on the plan, which should be signed by a competent surveyor.

(11) Plate-IV/2 (2<sup>nd</sup> Year Development Plan & Sections): The index reference given for proposed topsoil dump is not to be seen on the plan portion of the plate. Besides, the dump sections for the both the proposed dumps are not drawn, which should be furnished. Accordingly, the plates submitted depicting the development plan & sections for the years 2018-19 to 2020-21 as well as other relevant plates may also be revised.

(12) Plate-V (Key Plan): (i) Population of villages falling within the 5 km radius of the lease area is missing, which should also be furnished. (ii) Direction of flow of nala is has not been marked, which may also be furnished. (iii) The index reference given for reserved forest/village forest has not been correctly marked on the plan portion of the plate, which should be furnished.

(G. C. SETHI)