



VIOLATION LETTER

REGD/AD

भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463;
TeleFax: 0674-2352490;
eMail:
ro.bhubaneswar@ibm.gov.in
Plot No.149, Pokhariput
BHUBANESWAR-751016
Date:17.10.2017

No.: ORI/IRON/SNG/MCDR-9/BBS/ VOL-II/ 1757

Date: 17/10/2017

सेवा में,
Shri C S Grewal, Proprieter,
M/s National Enterprises,
PO Box No.44, Barbil,
Dist- Keonjhar, Odisha - 758035

Sub: Violation of provisions of MCDR, 2017 in respect of your Raikela Iron Mine over an area of 45.932 hectare in Sundergarh district of Odisha.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 07.10.2017 by the undersigned accompanied by S/Shri Rajendra Prasad Khuntiya, Senior Inspector, (Koira Circle) Kailash Kumar Pradhan, Mine Manager, N Patel, DGM (Mines) and B N Mohanty, Manager (Geology) of your mine.

Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining scheme dated 02/06/2015, i) Bench height should be maintained of 6 m in the working pit called Top Pit-A. ii) retaining wall should be maintained around waste dump dump-A iii) Safety zone of 7.5 m by planation should be maintained all along boundary line of boundary point 3, 4 and 5.	i) During inspection it is observed that bench height is more than 6 m in north side of Top pit-A between E312501-E312701. ii) During inspection it was observed that the retaining wall constructed around dump-A, got damaged and also not continuous around dump iii) During inspection it is observed that safety zone is not maintained all along boundary line of boundary points 3, 4 and 5 by planation.
54 (b)	Holder of mining lease shall maintain the sub grade or mineral reject stack register along with grade.	During inspection it is observed that sub-grade or mineral reject stack register along with not maintained.
55 (3)	Holder of mining lease shall employ a whole-time mining engineer having prescribed qualification and experience under these rules in case of Category - 'A' mines.	During inspection it is reported that whole-time mining engineer is not appointed having qualification and experience prescribed under these rules.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.


Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

- o/c -

1 signed
17.10.17

03. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (forty-five) days** from the date of issue of this letter.


Yours faithfully,


(Ramkishan R)

Senior Assistant Controller of Mines
Indian Bureau of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- (1) खान नियंत्रक(मध्यप्रंचल)/**The Controller of Mines (CZ/EZ)**, भारतीय खान ब्यूरो/
Indian Bureau of Mines, Nagpur-440001/Kolkata-700091.
- (2) डायरेक्टर ऑफ माइन्स /**The Director of Mines**, डायरेक्टोरेट ऑफ माइन्स/**Directorate of Mines**, उड़ीसा सरकार /**Government of Orissa**, हेडस ऑफ डिपार्टमेंट बिल्डिंग /**Heads of Department Building**, न्यू कैपिटल /**New Capital**, भुवनेश्वर /**Bhubaneswar-751 001** : *For information & further necessary action on following :*


(Ramkishan R)

Senior Assistant Controller of Mines
कृते क्षेत्रीय खान नियंत्रक/*For Regional Controller of Mines*