

**VIOLATION LETTER**

**REGD/A D**

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of  
Mines.

Ph-(0674)2352490 / Fax-(0674)2352463

File No. - ORI/IRON/SNG/MCDR-9/BBS / 38

Plot No. 149, Pokhariput,  
Bhubaneswar-751 020

To,  
Sri C.S. Grewal, Proprietor  
M/s. National Enterprises,  
P.O. Box No.- 44, At/P.o.- Barbil -758035  
Dist. - Keonjhar, Odisha State

Date : 01.04.2016

**Sub: Violation of provisions of MCDR, 1988 in respect of your Raikela Iron Ore Mine over an area of 45.932 Ha in Sundergarh district of Odisha State.**

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 04.03.2016 by the undersigned, in presence of S/Shri K.K. Pradhan, Mines Manager and N. Patel, DGM- Mines of your mine.

Rule No.	Nature of Violation																				
13(1)	<p>Mining operation has not been carried out in accordance with the modification of Scheme of Mining, approved dated 02.06.2015 to the extent indicated below:-</p> <p>i). The exploration approved for the year 2015-16 (09 Bore Holes) was not carried out. Further, against approved exploration for the year 2014-15 of 20 Bore holes; only 07 Bore Holes were reported drilled.</p> <p>ii). As per approved MSOM (ref. Para 3.d with PMCP Plate no.-XII), Following environmental protective measures proposed to be constructed/taken around the waste dump and fines stacks for arresting solid wash-off:</p> <table border="1"><thead><tr><th>Year</th><th colspan="3">(All in m)</th><th>Coir matting over Waste Dump-1</th></tr><tr><td></td><th>Retaining wall</th><th>Garland drain</th><th>Check dam</th><td></td></tr><tr><td></td><th>LxBxH</th><th>LxBxH</th><th>LxBxH</th><td>5200 sq. m</td></tr></thead><tbody><tr><td>2015-16</td><td>500x1x1.5</td><td>920x1x1</td><td>8x4x2</td><td></td></tr></tbody></table> <p>However, during inspection, above protective measures are not found constructed and escape of wash-off material observed therefrom in harmful quantities; resulting in degradation of environment.</p> <p>iii). Pit was approved to develop/ excavate from grid E312350 &amp; E 312450, whereas pit observed developed from grid E312501 &amp; E 312601. Further, Width of the Quarry benches have not been maintained as approved; against approved width of 9 m, bench width observed about 5 to 6 m at the places in irregular manner.</p> <p><i>These have endangered the systematic and scientific mining as well as protection of environment.</i></p>	Year	(All in m)			Coir matting over Waste Dump-1		Retaining wall	Garland drain	Check dam			LxBxH	LxBxH	LxBxH	5200 sq. m	2015-16	500x1x1.5	920x1x1	8x4x2	
Year	(All in m)			Coir matting over Waste Dump-1																	
	Retaining wall	Garland drain	Check dam																		
	LxBxH	LxBxH	LxBxH	5200 sq. m																	
2015-16	500x1x1.5	920x1x1	8x4x2																		
27(3)	<p>Surface plan kept/maintained at the mines office, up dated as on 06.02.2016, was not found correct with actual field position in respect of pit bench profile, excavation/development position etc.</p>																				

Extens<sup>n</sup>  
spectm  
officer

O/C

12/04/16

45(7)	Details furnished under Part- VII of Annual Return 2014-15; regarding the Cost of production i.e. cost per tonne of Rs. 2902, reported during the year seems to be very high and does not appear to be realistic.
-------	---


02. It is brought to your notice that these violations constitute an offence punishable under Rule 58 of MCDR 1988.

*Besides, inability to comply with the provision of Rule 13 (1) is liable for suspension of mining operations according to the provisions of Rule 13 (2) of MCDR, 1988.*

*Further, in view of the above position, the information furnished under Rule 45(5) in the Annual return is construed as furnishing wrong or false information, which may lead to suspension of all mining operations in the mine and prosecution of the owner, agent and manager as well as recommendation for termination of mining lease according to provisions of Rule 45(7) of the Mineral Conservation and Development (Amendment) Rules '2011.*

03. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (forty-five) days** from the date of issue of this letter.


Yours faithfully,



(PREM PRAKASH)  
Dy. Controller of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- (1) खान नियंत्रक(मध्यमंचल)/The Controller of Mines (CZ), भारतीय खान ब्यूरो / Indian Bureau of Mines, नागपुर /Nagpur-440 001.
- (2) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार /Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग /Heads of Department Building, न्यू कैपिटल /New Capital, भुवनेश्वर /Bhubaneswar-751 001.



(PREM PRAKASH)  
Dy. Controller of Mines

कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines