

## भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय



## OFFICE OF REGIONAL CONTROLLER OF MINES

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर

बेंगल्र -560022

दूरभाष: (080) 39505368 / 29720499

Email ID: ro. bangalore@ibm.gov.in

सं/No.KNT/BLR/FE/52/BNG/VOL-VII

Mine-code:30KAR03035

दिनांक/Dated: \_\_\_/03/2023

To,

Sir.

Shri P.V Prakash, Nominated Owner & Managing Partner Karadikolla Suresh Iron ore mine M/s. P. Balasubba Setty & Son D. No. 2078, P.B. No-03, 22nd ward J.P. Nagar, Bellary Road, Hosapete Karnataka- 583 201

E-mail id- pbsmines2502@gmail.com, pbsandson@gmail.com

विषय/Subject: Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Karadikolla Suresh Iron ore Mine, ML 2502 of M/s.P. Balasubba Setty & Sonover an extent of 42.10ha (as per CEC sketch), inKaradikollaVillage, SandurTaluk, Ballari District of Karnataka State.

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 25.02.2023by undersigned presence of Shri Y.V Ramakrishna Reddy, Mine Manager & Mining Engineer, Shri N. Siva Prasad, Geologist, and other mining officials:

| Rules            | Nature of Violations observed  |
|------------------|--|
| 11 (1)&<br>37(2) | Modification of Mining Plan was approved by IBM vide letter no. 279/125/89/BNG dated 02/08/2021, for the period 2021-22 to 2022-23&FMCP approved by IBM vide letter no 279/125/89/BNG/FMCP dated 14/10/2021. The deviations observed in mining operation vis-à-vis approved document are given below.  i) It was observed during inspection that bench height of 8m as proposed, has not been maintained at Sec B-B'(N-1684031, E-653595) from 780 to 790 mRL& Sec E-E'(N-1683874, E-653883) from 764 to 794 mRL. The benches have been developed with 10 metres height whereas, as per the proposal the benches haveto be developed of 8m height systematically between 792 to 776 mRL at Sec B-B' and 808 to 752 mRL at Sec E-E' till 2022-23.  ii) The active Waste dump AD-1 slope failure has occurred at North Eastern portion of the lease of approximate height 80 metres and width 120 m. The waste dump material has escaped outside the mine lease area due to the dump sliding. The active waste dump AD-1 has |

|         | not been properly maintained in stages and secured as per the                    |
|---------|--|
|         |  |
|         | proposal and provision of Rule 37(2).  |
|         | iii) The constructed Retaining wall and garland drain at bottom of the           |
|         | Inactive dump ID-2 at North Eastern portion of the lease have been               |
|         | damaged due to portion of active waste dump AD-1 sliding                         |
| 12(4B)  | The Geological study report prepared in the manner specified in the Minerals     |
| , ,     | (Evidence of Mineral Contents) Rules, 2015 have not been submitted after         |
|         | completion of the detailed exploration (G-1 level) to the State Government and   |
|         | the Indian Bureau of Mines as per the provision of this rule.                    |
| 34A (2) | The satellite image has not been submitted in accordance with the Standard       |
| • (_,   | Operating Procedures under sub rule (2) of rule 34A of MCDR, 2017 for            |
|         | submission of Satellite Imageries. The Lease area with 100 m buffer shp file,    |
|         | establishment of Ground Control points, Data output and formats (Meta data,      |
|         | GCP's data, RMSE Report, Map of the mining lease(.shp files of actual            |
|         | excavation, mineral storage, waste dump, afforestation etc.), Lease boundary     |
|         |  |
|         | pillar co-ordinates(.shp & MS excel) have not been submitted in accordance with  |
|         | the SOP.   |
| 48      | The record of the 6 nos. of boreholes drilled during year 2022-23 were not found |
|         | maintained properly with all details in "Form-J"as per provision of this rule.   |

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this officewithin 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Sandeep Kumar Singh)

Assistant Controller of Mines Indian Bureau of Mines

## Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines