1/16882/2023



भारत सरकार / GOVERNMENT OF INDIA खान मंत्रालय / MINISTRY OF MINES भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय



29, इंडस्ट्रियल संबर्ध, II स्टेज, तुमक्र रोड,

गोरगुंटापाल्या, येशवंतपुर,

Bengaluru/ बेंगलुरु -560022

दिनांक/Dated: August /2023

क्षत्राय खान ।नयत्रक कायालय OFFICE OF REGIONAL CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67 Email ID: ro. bangalore@ibm.gov.in

सं/No.: KNT/GLB/LST/11/BNG/Vol IV

सेवा में / To:

Shri Kailash Chandra Jhanwar

Nominated Owner

M/s Ultratech Cements Ltd.

A-Wing, Ahura Center, 1st Floor, Mahakali Caves Road, Andheri (E)

Mumbai – 400 093

Email: kailash.jhanwar@adityabirla.com; rajesh.sambrey@adityabirla.com

विषय/Subject: Violation of provisions of MCDR, 2017 in respect of your Rajashree Limestone Mine (ML No. 2666 & Mine-code 38KAR10009) over an extent 715.987, located in Diggaon & Malkhed villages, Chittapur Taluk, Kalaburgi District, Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 06/09/2023 by undersigned in presence of Shri Rajesh Sambrey, Sr. Vice President & Agent, Shri Sameer Kumar Arora, Mines Manager, Shri Gaurav Soni, Mining Engineer and Shri Pramodaran, Geologist

Rules	Nature of Violations observed
11(1)	The Mining operations required to be carried out in accordance as per
	the approved Modifications in the Review and Updation of Mining Plan
	document vide letter no. 279/127/89/BNG dated 23/07/2021, However,
	during the inspection deviations were observed in mining operation vis-
	à-vis approved document and are as follows:
	i. The said mining plan was approved with a condition to maintain the
	lease boundary pillars as per Rule 12 of the Minerals (Other than
	Atomic & Hydro Carbons Energy Minerals) Concession Rules,
	2016. However, upon inspection, it has been noted that the
	boundary pillars have not been maintained all along the lease
	boundary in accordance with the aforementioned Rule.

I/16882/202\$

- ii. Safety zone maintenance is lacking between Boundary Pillar Nos. BP 68 and 69A, and the excavation has been conducted within the safety zone in the said location.
- iii. During the year 2022-23, it was proposed work in single pit at 04 locations viz. (i) section D-D' (eastern part of pit), (ii) Section B-B' (western part of pit), (iii) section C-C' (South-western part of pit) and (iv) Section S-S' (south-eastern part of pit), however, Production & Development were not carried out at section B-B' and section C-C'.
- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.) वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist

Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

डॉ. सुधाकर टी.एल. / Dr. Sudhakara T.L.) वरिष्ठ खनन भूविज्ञानी / Senior Mining Geologist