MCDR-MiFL0BXT/20/2023-JBP-IBM_RO_JBP

<u>उल्लंघन नोटिस</u>

<u>By email</u>



भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines *********



Dated: 06/06/2023

To,

Shri Surendra Singh Saluja Nominated Owner, Salaiya Bauxite Mine, M/s Madhya Pradesh Mineral Supply Co., PO: Jaitwara, District: Satna, Satna, 485221, M.P. Email- nikkoonib@gmail.com

<u>Subject</u>:- Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect of your Salaiya Bauxite Mine, over an area of 16.18 hectare, situated in village-Salaiya, Tehsil-Semariya, District-Satna of Madhya Pradesh State

Sir,

Undersigned has inspected your mine in the presence of your representative Shri G.P Garg, Shri Dharmendra Pandey (Mine Geologist), and other mines officials on 27/05/2023. Following provisions of MCDR 2017 were found violated in your mines at the time of inspection.

11(1)of MCDR 2017	 Mining operations under mining lease(1) No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5. The document of above mentioned mine was approved vide letter NoMP/Rewa/Bauxite/MPLN/MOD-16/21-22 dated 12/11/2021 incorporating proposal of working from 2021-22 to 2022-23 During inspection it has been observed that the following provisions of the rule have been violated: - 22499 tonnes of bauxite production is raised during 2022-23 against the proposed 50013 tonnes.
	2. It was proposed to produce 13153 tonnes of overburden during 2022-23 but only 4800 tonnes overburden is produced.
	 It was proposed to produce 10003 tonnes of mineral rejects but only 4800 tonnes of mineral rejects is produced.
	 Lease barrier of 7.5 m is not maintained with adjoining leases. At many places dumping and pitting has been done in 7.5 m barrier (B.P 6 to BP 8, BP 4 to BP 6 and BP 9 to BP 15). It was proposed to plant 400 saplings during the year 2022-23, but plantation is not done.
	7. It was proposed bench height of 3m in mineral will be maintained, but height was not maintained.
34A	Submission of Drone survey data . – 1. Drone survey data is submitted, but SOP is not followed, Shape file of lease boundary furnished is not correct. Separate shape file of existing pit, dump, top soil dumping area, plantation etc is not submitted. Shape file in polygons for above mentioned heads along with for future proposals may also be submitted. 2. Ground control points are not constructed.
Rule 55(1)(3)(ii)	Employment of geologists and mining engineers:- For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules,- (ii) category 'A' mines having lease area below twenty-five hectares and category 'B' mines, a part-time mining engineer and a part-time geologist: But, during inspection it was observed that, a full time/ part time Mining Engineer is not appointed for the purpose of carrying out the mining operations in accordance with these rules
	As per the provisions of Rule 62(2) Mineral Conservation and Development (Amendment) Rules, 2021, contravention of this rule shall be punishable with fine for an amount as specified in Schedule III. Therefore, you shall be liable a fine of Rs 5,00,000 if the mining engineer is not appointed as per the provisions of rule within till rectification of this violation.

MCDR-MiFL0BXT/20/2023-JBP-IBM_RO_JBP

1 In this connection, it is brought to your notice that the above violations constitute an offence punishable 1/10877/202ander Rule 62 of Mineral Conservations and Development Rules, 2017.

- 2. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
- 3. You are advised to rectify the violations of above mentioned rules immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय,

(माधवराव साबरे) वरिष्ठ खनन भूविज्ञानी कृते क्षेत्रीय खान नियंत्रक

- 01. The Director, Director of Geology & Mining, Govt.of Madhya Pradesh, Khanij Bhawan, 29-A, AreraHills, Jail Road, Bhopal (M.P.) for information and further necessary action.
- 02. The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur for kind information.

(माधवराव साबरे) वरिष्ठ खनन भूविज्ञानी कृते क्षेत्रीय खान नियंत्रक