INDIAN BUREAU OF MINES MINERALS DEVELOPMEMT AND REGULATION DIVISION FMCP REPORT

Dehradun regional office

Mine File No. Minecode: 38HPR10012

(i)	Name of the Inspecting Officer	Shri Deepak Sharma and Shri Damodar P Sharma	
(ii)	Designation	Senior Mining Geologist and ACOM	
(iii)	Accompanying mine official with designation	Kapil Anand	
(iv)	Date of Inspection	23.08.2024	
(v)	Prev. Inspection date	-	

PART-I: GENERAL INFORMATION

1	(a)	Mine Name	Hiyona Limestone Mines
	(b)	Registration No.	The one difficulty whites
	(c)	Category	A-Category
	(d)	Type of Working	Opencast
	(e)	Postal Address	- Spinoust
		State	Himachal Pradesh
		District	Sirmour
		Village	Mauza Barwas
		Taluka/Tehsil	Poanta Sahib
		Post Office	Poanta Sahib
		Pin Code	173001
		FAX No.	NA
		E-mail	Kapilanand51@gmail.com
		Phone	NA
	(f)	Police Station	Poanta Sahib
	(g)	First Opening Date	NA
	(h)	Weekly day of rest	-
2		Address for Correspondence	Kapil Anand
			R/o Bata Mandi
			Tehsil-Poanta Sahib
			District-Sirmour
			Himachal Pradesh-173001
3	(a)	Lease Number	-
	(b)	Lease Area	18.21 hect.
	(c)	Period of Lease	Up to 05.11.2023 As per Section 8(A)(6) of MMDR Act-2015.
4		Mineral Worked	Limestone

SN	Item	Proposals	Achieve
1.	Reclamation and Rehabilitation of Mined Out Pits	Two Pits were developed in mine during the whole lease period Pit-1 and Pit-2 Regrassing was proposed on worked out benches.	left event le l
2.	Reclamation of Virgin undisturbed land within lease area		Entire vincia
3.	Waste/OB Dump Management	2 Minerals Reject dump were proposed to established and manage by means of garland drain, retaining wall and plantation.	Waste dump found stabilized with Plantation. Retaining walls and Gar and drain found constructed along the waste dump. 02 Mineral Reject dump also developed in mine. Total Mineral Reject Quantity approximately found 42000 to 46000 Tonnes in Mine. Total length of fencing was found
4.	Top Soil Management	No Top Soil stacking was proposed in mine	approx 600 meter. No top soil stack found at the time of inspection.
5.	Fines/ tailing management	Not Applicable	Not Applicable
6.	Water Quality management	The topography of the area is hilly at a level above mean sea level ranging from 1495mRL to 1145 mRL. As the mine is in hilly terrain, the rainwater flow and downwards and gets drained away through various nallas.	Same is observed during the inspection. Ultimate pit bottom is nearly 1325 mRl and the ground water table exist at 1000 mRl(approx) so water not intersected by the mining operation garland drain were prepared for
7	Tailings dam management	Not applicable	continues water flow.
8	Security and safety	Access routes to the mining lease are proposed to be fenced to protect inadvertent access. Mined out areas, pits, dumps etc. are proposed to be fenced and to be close for any type of entries.	Not applicable During the Inspection it was found all the Access routes blocked through construction of stone/ Retaining Wall and Parapet Walls and Wire Fencing. Appox 625-650 meter fencing, 700 meter retaining wall, stone wall fencing 600 meter.
1	Infrastructure and Machinery	after the recommended mine life. At the	All the machineries deployed in the mine have been shifted to the other businesses of the mine owner.
0 F	Flora and fauna	No impact over flora and fauna due to mining activities.	No impact over flora and fauna due to mining activities. In last 2.400 under total area under during this cumulative and total expenditure reported for a forestation is 47750 INR


11	Balance Reserve and	111-1203192	s reported by	ML holder.
	Resources	221-121459 Reserve depleted from last two year i.e. 05.11.2023)	2022-23 &	2023-24 (upto
12	Existing Man Power	Man power was proposed to shift to other business and to provide help to getting new jobs.	were consu	sting man power med in the other the ML holder.
13	Closures cost	300000 INR	304250 INI	

Shri beepak Sharma

Senior Mining Geologist

Shri Damodar P Sharma

Assistant Controller of Mines.



FMCP HIYONA LIMESTONE MINE:

MANAGEMENT OF MINED OUT BENCHES



FMCP HIYONA LIMESTONE MINE:


MINED OUT AREA RE-GRASSING




FMCP HIYONA LIMESTONE MINE:

MINED OUT AREA
PLANTATION & RE-GRASSING







FMCP HIYONA LIMESTONE MINE:

MINED OUT AREA PLANTATION



FMCP HIYONA LIMESTONE MINE:



