



भारत सरकार /Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो /Indian Bureau of Mines
Office Of Regional Controller of Mines



Violation Letter Speed Post/Email

दूरभाष: (080) 39505368 / 29720499

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

No: I- MCDR-MiFLOLST/7/2023-BNG-IBM_RO_BNG Mine-code: 38KAR10017 Dated: 13 /01/2025

To,

Shri Anoop Kumar Saxena,
Nominated Owner, Vicat Sagar Limestone mine
M/s. Kalburgi Cement Private Limited
Chatrasala Village, Karchikhed Post
Chincholi Taluk, Kalaburagi District
Karnataka-585 320

E-mail id- kalburgicementmines@gmail.com Kanchan.kumar@vicat.com
stalinrichardson.c@vicat.com

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Vicat Sagar Limestone mine, ML 2612 over an extent of 446.77 ha, in Chatrasala Village, Chincholi Taluk , Kalaburagi District of Karnataka State.**

Sir,

The undersigned carried out virtual inspection of your mine on 06/01/2025 based on your submitted drone data and available information as per office records and following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine.

Rules	Nature of Violations observed
11 (1)	<p>The Review and updation of mining plan was approved by IBM vide letter no. 279/1030/2009/BNG dated 20/11/2018 for the period 2019-20 to 2023-24 and vide letter no. MCDR-MPCOLST/5/2023-BNG-IBM_RO_BNG dated 15/12/2023 for the period 2024-25 to 2028-29. The deviations observed in mining operation vis-à-vis approved document are given below.</p> <ol style="list-style-type: none"> It is observed from drone data that OB dump 5 present at Southern portion of the mine lease between pillar BP-30 & BP-31 and section C-C' to D-D' is overlapping with the mine lease boundary and safety zone. It is also observed from drone data, that Retaining wall constructed from East to North for OB-dump A to OB dump E (OB Dump A,B,C,D & E) between pillar 17 to 18(17A,17B,17C,17D,17E & 17F) is overlapping with the Lease

boundary and safety zone.
iii. It is observed from the drone data that the 148 metres Retaining wall proposed from South to West at toe of OB dump 5 has not been completely constructed as per the proposal.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(Sandeep Kumar Singh)

Senior Assistant Controller of Mines

Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(Sandeep Kumar Singh)

Senior Assistant Controller of Mines

Indian Bureau of Mines