Violation Letter
By Register Post

भारत सरकार /**Government of India**
खान मंत्रालय/ **Ministry of Mines**
भारतीय खान ब्यूरो/ **Indian Bureau of Mines**
क्षेत्रीय खान नियंत्रक का कार्यालय/ **Office of the Regional Controller of Mines**

ISO 9001:2015

Phone No.: (0832) - 2741757
Fax No. : (0832) –2741758
E-Mail : ro.goa@ibm.gov.in

Opp. R.T.O.'s Office,
P.O. FATORDA - 403602,
Margao – GOA

File No. KNT/BJP/LST-106/GOA **38KAR26092** **Date -15/03/2019**

To,
Shri. R.M.JUMNAL (Mine Owner),
M/s. Sri Nandi Mining Company,
A.P.M.C. Yard, Plot No-43A,
Navanagar, Bagalkot Taluk,
Bagalkot District, Karnataka – 587 102

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Naganapur Limestone Mine (ML-001) over an extent of 8.10 hectares situated in Naganapur Village, Mudhol Taluk, Bagalkot District, Karnataka State - Reg.

Sir,

The following provision of the Mineral Conservation and Development Rules, 2017 was found violated in your above mine during the inspection on **11/03/2019** by the undersigned.

Rule No.	Nature of Violations observed
11(1)	The mining operations in the Lease area are not carried out as per the last approved Mining plan. The following deviation is observed during inspection, a) Dumping is proposed in the northern side of the lease boundary, but during inspection it was noticed that no dump has been formed. b) It is proposed in Page-34, to construct Retaining wall along the lease boundary, but during inspection it was noticed that no wall has been constructed. c) It is proposed in page-17, that budget has been allotted for CSR activity. But, on the day of inspection, it was noticed, no amount has been spent on CSR.
33	The plans & sections prepared under rule 32 for the year 2017-2018 have not been submitted on or before 30th June 2018.
55(1)(3)(iii)	The mine is being operated without employing the full time Mining Engineer required under the provision this rule.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2) if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

(G.S.Kannan)
Junior Mining Geologist

Copy forwarded to:
1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, DMG, No.49, Khanija Bhavan, Race Course Road, Bangalore-560001.
3. Mine File

(G.S.Kannan)
Junior Mining Geologist