भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो,
क्षेत्रीय खान नियंत्रक कार्यालय
द्वितीय तल, जी0 एस0 आई0 फील्ड प्रशिक्षण केन्द्र, महालेखाकार कार्यालय परिसर,
पोस्ट–विधानसभा, रायपुर–492005 (छत्तीसगढ़)
फोन एवं फैक्स–0771–2282530, 2285590 ई–मेल: ro.raipur@ibm.gov.in

उल्लंघन पत्र
रजि. ए.डी. / स्पीड पोस्ट / ई–मेल / फैक्स

क्र0– छ0ग0 / दंतेवाड़ा / टिन–01 / रायपुर 60 छ0ग0 03001 दिनांक :– 12 / 06 / 2020

प्रति,

श्री निर्मल लूनिया, निदेशक एवं नॉमिनेटेड ऑनर
सर्वश्री प्रीशियस मिनरल्स एवं स्मेलटिंग लिमिटेड,
सेमी अर्बन ईन्डस्ट्रीयल एरिया, फ्रेजीपुर,, पोस्ट– जगदलपुर ,
जिला – बस्तर (छत्तीसगढ़) – 494 001

विषय:– छत्तीसगढ़ राज्य के दंतेवाड़ा जिले में स्थित आपकी बड़े बचेली टिन अयस्क खदान क्षेत्रफल 7.739 हे0 में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में।

महोदय,

आपकी उपरोक्त खान का निरीक्षण दिनांक 17 / 03 / 2020 को अधोहस्ताक्षरी द्वारा श्री विमल कुमार लूनिया, निदेशक एवं श्री मोहित कुमार लूनिया, खान मालिक प्रतिनिधि की उपस्थिति में किया गया तथा खान के निरीक्षण के दौरान यह पाया गया कि आपने खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबंधों का उल्लंघन किया हैः–

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
Rule 11 (1)	The following deviations have been found in the mine from the approved Modified Mining Plan vide letter no. DNT/TIN/MPLN-1070/2017-RPR Raipur dated 13/02/2017 for the period of F.Y. 2016-17 to 2019-20: **Exploration:** During F.Y. 2018-19 to 2019-20; it was proposed to carry out 07 nos. of Boreholes up to a cumulative depth of 210 meters; whereas, 04 nos. of boreholes have been drilled with a cumulative depth of 97.0 meters. **Development:** In the approved Review of Mining Plan, there was a proposal given for the production and development during the financial year **Pit No. 2** **2018-19:** In between local co-ordinates N004 to N040 and E078 to E203 **2019-20:** In between local co-ordinates N114 to N152 and E217 to E243 Whereas, production and development is being done in irregular and unscientific manner at many places in Pit No. 1 in between local co-ordinates N007 to N190 and E272 to E352.. **Afforestation:** There was a proposal given for plantation of 200 nos. of plants during 2019-20. Whereas, NIL plantation has been done. **Protective Measures:** There was a proposal given for construction of Garland Drain and De-siltation pits around the waste dump. Whereas, Garland Drain and De-siltation pits have not been constructed.
Rule 26 (2)	A yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilative works carried out has not been submitted for the year 2018-19.
Rule 45 (7)	**Annual Return F.Y. 2018-19:** **Part V; General Geology & Mining: Para 4.2 (c):** Total quantity of Overburden/Waste removed during the year (tonnes) has not been mentioned. **Part – VII; Cost Of Production:** During F.Y. 2018-19, (i) (ii) & (v) Since the production has been done during the F.Y. 2018-19 and the beneficiation in the form of Manual Panning has been done, hence the Beneficiation Cost, Overhead Cost and Royalty may not be considered as 'zero'. (iii) Since the value of the fixed assets is Rs. 3,39,972/- only, whereas the value of depreciation has been taken at very high side, i.e. Rs. 4,558/-. (vii) Value of Rs. 734/- as the Dead Rent in the working mine may not be considered. Hence, this may be removed or considered as 'zero'. (viii) Whether DMF and NMET have been paid is not clear. If paid, these may be specified under para 'Others (specify)'.
Rule 46	**Notice of Certain Appointment:** Appointment notice of the Manager (Mines) and the Nominated Owner have not been sent in the prescribed format to the authorized officer within fifteen days from the date of such appointments.

कृ0पृ0प0..2.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं इस नियम का उल्लंघन की अनुपालन नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(1) एवं 45(7) के अंतर्गत :–

(क) खान की समस्त खनन संक्रियाएं बंद की जा सकती है।
(ख) आपके विरूद्ध अभियोग याचिका दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिश राज्य सरकार से की जा सकती है।

03. अतः आपको सलाह दी जाती है कि आप उपराक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी,
भारतीय खान ब्यूरो, रायपुर

प्रतिलिपिः सूचनार्थ हेतु :–

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर (महाराष्ट्र)–440001
2. संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ़ इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिट्ल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ़।

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो, रायपुर