ई मेल

भारत सरकार / Government of India
खान मंत्रालय / Ministry of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES
100, ओल्ड नेहरू कालोनी, देहरादून (उत्तराखंड) 248001 / 100 Old Nehru Colony, Dehradun (U.K.)248001
TEL- 0135-2676350 / 2671896, FAX-0135-2674962, E-mail ro.dehradun@ibm.gov.in

फाईल संख्या File No: 614(2)/MS-B-233/13-DDN

दिनाक 21.08.2018

e-mail - gnchowdry@yahoo.com

सेवा में/ To :

G.N. चौधरी, भूगर्भ विज्ञानी,
17-इकबाल कॉलोनी, चनापोरा,
श्रीनगर (जम्मू और कश्मीर)

G.N. Chowdry, Geologogist,
17-Iqbal Colony, Chanapora,
Srinagar(J&K)

विषय/ Sub : Submission of Review & Updation of Mining Plan with Progressive Mine Closure Plan in respect Yamdoor Limestone Mine over an mine of 4.92 Hectares at Village- Bathyn, Tehsil – Pampora District Pulwama, Anantnag, State–Jammu & Kashmir of Mohd. Shafi Trumboo, submitted under Rule 17 (1) of Minerals (Other than Atomic And Hydro Carbons Energy Minerals) Concession Rule, 2016 & 23 of Mineral Conservation and Develppment Rules-2017.

संदर्भ/Ref. : Your letter No. Nil dated Nil received on dated 01.08.2018

महोदय/ Sir,

This office is in receipt of two copies of the above-mentioned draft Review and Updation of Mining Plan including Progressive Mine Closure Plan on 01.08.2018. On examination of the same the discrepancies / deficiencies observed have been listed in annexure.

You are advised to correct the submitted Mining Plan including Progressive Mine Closure Plan as per deficiencies /discrepancies pointed in the enclosed annexure as scrutiny comments and submit **3** fair copies of the Mining Plan including Progressive Mine Closure Plan within **15 days** from the date of issue of this letter after corrections in hard bound copies (no spiral binding). If the fair copies of Mining Plan including Progressive Mine Closure Plan will not be submitted within stipulated time, final action will be taken as per rule. Two CDs of the fair Mining Plan including Progressive Mine Closure Plan may also be submitted including text, plates and annexures. On receipt of additional comments from State government, it shall be communicated to you subsequently. In case if it is necessary to incorporate the additional information, the details of the same should be given along with page numbers.

You are further advised to prepare the fair copies carefully and ensure that it is correct in all respect. Preferably use of paper on both the side should be made. If again deficiencies are observed then final action will be taken by this office without returning the copies for correction. This issues with the approval of competent authority.

Encl: as above.

भवदीय/ Yours faithfully,

21/8/18

(एस.सकलानी S Saklani)
सहायक खनन भूवैज्ञानिक AMG
कृते प्रभारी अधिकारी For Officer In Charge
भारतीय खान ब्यूरो Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

1. खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर।
2. मोहम्मद। शफी ट्रंबो सी / ओ - 63-सी राजबाग एक्सटेंशन श्रीनगर (जम्मू-कश्मीर) 1 9 0008 Mohd. Shafi Trumboo C/o – 63- C Rajbagh Extension Srinagar (J&K) 190008
2. उप खान नियंत्रक एवं प्रभारी अधिकारी, भारतीय खान ब्यूरो, क्षेत्रीय कैम्प कार्यालय, नई दिल्ली।

सहायक खनन भूवैज्ञानिक AMG
कृते प्रभारी अधिकारी For Officer In Charge
भारतीय खान ब्यूरो Indian Bureau of Mines

MukeshL.I C:\Users\ilm\Desktop\Unicode\For Scr. Yamdoor Limestone Mine of Mohd. Shafi Trumboo.doc

Scrutiny comments indicating defficiencies in respect of submitted review and updation of Mining Plan with PMCP of Yamdoor limestone mine of Mr. Mohd Shafi Trumboo (4.92) hect.) in Pulwama district of J&K State submitted under Rule 17(1) of MCR 2016 & 23 of MCDR 2017.

1. Name of mine indicated on cover page and other relevant pages is not matching with the name indicated in the lease deed. The name and spelling of mine is different at different places.
2. Rule mentioned on cover page is not correct.
3. Address of lessee is not matching as per lease deed. Details at chapter 1.0(a) and 2(vi) is not substantiated with documentary proof and MCDR provision are not followed in such changes, if any.
4. Name of mine on various plan and section is not matching with the details given at 2.0(I) on page 4. Further these are also not matching with name of mine on cover page, and authorization letter from the lessee in favour of qualified person.

5. On page 4 date of execution of lease deed given is not correct.
6. UNFC classification under different G axis has not been indicated.
7. Nearly six months have gone to implement the production schedule for the year of 2018-19. Thus production for the year 2018-19 should be revised proportionately and changes should be made in the relevant plates.
8. On page 42 under chapter conceptual mine plan, the total mineable reserves have been indicates as 2.38 million tonnes whereas mineable reserves are estimated to the tune of 2.18 million tones at page 25.
9. The details given at page no. 43, at para 'g' of conceptual mine planning is not correct with respect to exploration, entire details need to be corrected, evaluated afresh and furnish requisite details for exploration.
10. On page 43 year wise bore holes to be drilled have been indicated as 450 no. in each year which is an imaginary figure. What does 450 no indicates is not clear.
11. On page 18 depth of bore hole in table not given. Please confirm that with the help of this exploration the entire lease will come under G1 axis by 2022.

12. All the proposals should be made within the ML only.
13. Based on surface plan the area claimed as fully reclaimed and rehabilitated as 0.30 ha can not be considered, then FA should be submitted for 3.542 instead of 3.242 ha. Review the same on page 77 and financial assurance plan.

14. Cao should be written as CaO.
15. Area not given in table on page 19.
16. Area not given in table on page 20.
17. On page 29 at para 5 change "by recording" to "monitoring".
18. On page 69 use proper terminology instead of vibrometer.
19. Annexure 5 not legible.
20. On page 4 see the heading used in table in para B.
21. Details given at Annexure15 and 16 shall be given in geology chapter and not in annexure.
22. Financial Assurance need to be submitted as per MCDR 2017 and not MCDR 88
23. Points 3,8, 12,20,39,41,43 &51 of previous scrutiny comments are still not addressed completely.
24. The mine is located on hill slope. Hence adequate proposals should be incorporated like controlled blasting techniques, erecting retaining walls, check dams, parapet walls to ensure safe and systematic mining for ensuing five years.

25. There are several typographical mistakes which require to be corrected.
26. All the annexures should be attested by qualified persons for their authenticity.
27. Two CDs covering the entire document and plans should be enclosed at the time of final submission. Undertaking in this regard by the qualified person should be given that the CD contains the same text & plates as submitted in hard copy.

Plates

28. In annexure 14 Mining lease is not superimposed over khasra plan as enclosed at plate.

29. Surface plan- All the surface features are not shown in Surface Plan.
30. Financial Area Assurance Plan- Figures mentioned under area put in use are not matching with the figures given on page 77. Area considered for others is indicated as 0.002 hectares on page 77 whereas on financial assurance plan it is given 0.006 hectares.
31. All plans and sections shall be prepared in accordance with the rules under chapter VI rule 31-34 (refer general comments of Surface plan) of MCDR 2017. Still there is lot of discrepancies in surface plan, surface geological plan , environment plan of this mine submitted with document.

32. Environment plan- A substantial part of the lease is plotted under forest land whereas the entire lease area (4.92 hectares) is shown as non forest land on cover page.
33. Surface mineable section i.e. plate 6 not as per guideline
34. UNFC on geological section is not correct.

21/8/18