भारत सरकार / GOVERNMENT OF INDIA खान मंत्रालय/ MINISTRY OF MINES भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक का कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES

No. ORI/IRON/KJR/MCDR-63/BBS-Vol-III

Plot No. – 149, Pokhriput In front of CPWD office, BHUBANESWAR – 751020 Date: 02/01/201

To,

Dipti Ranjan Patnaik, Managing Director, Deojhar Iron Ore Mines, M/s Tarini Minerals (P) Ltd., X-5, Civil Township, Rourkela, Odisha-769004

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Deojhar Iron Ore Mines located in Keonjhar District of Odisha State.

Sir,

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) was found violated in your above said mine during inspection on 20/12/2018 by the undersigned and Sri Ashok Kumar Pany, AME of this office. The inspection was accompanied by Sri Pinaki Mondal (Mines Manager) of your organization.

Rule	Rule position	Status and extent of violation
11(1)	No holder of a mining lease shall commence or	Mining operations have not been carried out in
	carry out mining operations in any area except	accordance to the Mining Plan approved for the
	in accordance with the mining plan approved,	period from 2014-15 to 2018-19 vide letter
	modified or reviewed by the Indian Bureau of	number MP/FM/07-ORI/BHU/2014-15 dated
	Mines or prepared and certified in accordance	05/12/2014 to the extent given below:
	with the system established by the State	(1) During year 2017-18 a total of 72016.00
	Government pursuant to the proviso to clause	tonnes of Sub-grade ore was proposed to be
10.92	(b) of sub-section (2) of section 5,limits	generated. However, no sub-grade material was
	declared under Schedule-A of the Atomic	generated during the year.
	Minerals Concession Rules, 2016.	(2) It was proposed to generate 25720 tonnes of
		waste during the year 2017-18. However, no
		waste has been generated during the year.
	N N	(3) The bench width was proposed to maintain
	g (# 1 1 a 1	more than the height i.e. more than 10 meters.
		However, during inspection it was observed
		that the benches at places (near boundary pillar
		33) have been reduces to around 6 to 7 mts.
45(7)	If it is found that the holder of a mining lease or	On examination of annual return of the year
92	the person or company engaged in trading or	2017-18, following deficiencies have been
	storage or end-use or export of minerals, as the	observed:
	case may be, has submitted incomplete or	(1) Part V, section 4: During inspection, it is
	wrong or false information in daily or monthly	reported that 19 number of bore have been
	or annual returns or fails to submit a return	drilled during the year 2017-18. However,
	within the date specified; thenrecommend	under above section "Zero" number of drilling
	termination of the mining lease, in case such	have been mentioned.
	suppression or misrepresentation of	
	information indicates abetment or connivance	
##(2)	of illegal mining;	It is a local of the fall time Coals in the section
55(3)	Employment of geologists and mining	It is observed that full time Geologist has not
	engineersevery holder of a mining lease shall	been appointed as required under the rule.
	employ, in case of— (iii) category 'A' mines, a	
	whole-time mining engineer and a geologist;	

- 2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of MCDR, 2017.
- 3. Further, in case of non-compliance of the rule 45(7) of MCDR, 2017, the Regional Controller of Mines may advise the State Government to,-
- (i) order suspension of all mining operations in the mine and to revoke the order of suspension only after ensuring proper compliance;
- (ii) take action to initiate prosecution under these rules;
- (iii) recommend termination of the mining lease, in case such suppression or misrepresentation of information indicates abetment or connivance of illegal mining;

Besides, inability to comply with the provisions of the rule 11(1) and 45(7) of MCDR, 2017 is also liable for suspension of Mining Operation under the provision of rule 11(2) of MCDR, 2017.

4. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

(DILIP JAIN) Junior Mining Geologist IBM, BBSR