



भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो, क्षेत्रीय कार्यालय रायपुर

दूसरी मंजील, जीएसआई फील्ड प्रशिक्षण केन्द्र

महालेखाकार आफिस कोम्प्लेक्स, पोस्ट -विधान सभा- रायपुर- (छ.ग)-492005

फोन- 0771--2282530/2285590/95 [मेल- ro.raipur.ibm@gmail.com](mailto:ro.raipur.ibm@gmail.com)

No.CHG/KNK/Fe-7/NGP

Date: 24.11.2017

To

Shri Ajay Kapur, Nominated Owner,
M/S Ambuja Cements Limited.,
Elegant Business Park, MIDC cross Road,
'B', off Andheri-Kurla Road, Andheri(E),
Mumbai-(MS)-400059

Sub: Violation of provisions of MCDR, 2017 in respect of Maldi Mopar Limestone Mine of M/S Ambuja Cement Ltd over an extent of 553.656 Ha. in Boirdih, Karmandih, Maldi Mopar & Devrani(V) Baloda Bazar & Bhatapara (T) Baloda Bazar -Bhatapara Dist.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 01.11.2017 by undersigned accompanied by Sri.Dinesh singh Panwar, Manager(Mine)

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the approved Mining Plan/Scheme of Mining. The Mining Plan was approved vide letter no.KNK/FE/MPLN-1151/NGP dated 03.07.2015 and following deviation was observed during inspection 1. It was proposed to produce 0.26 million tons in 2015-16 and 0.54 million tons in 2016-17 but achievement is Nil production in 2015-16 & 0.124 million tons. 2. In last approved document the OB/SB/IB proposal given Nil but during mine visit it was observed that OB mixed with limestone is dump in mine area as crusher ramp and also in annual return it was mentioned that 12.461 ha. area is used for waste disposal.
Rule 26	A yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitate works carried out has not been submitted for the year 2016-17
Rule 33	Updated print copy of the surface geological plan and sections has not been submitted before 30th day of June for the year 2016-17.
Rule 45	While scrutiny of the Annual return submitted for 2016-17 it is observed that the mining Engineer charge information is not mentioned where as other place it is mentioned that two mining engineer is there. The OB/Waste generation is kept nil whereas in mine site waste mixed with limestone is dumped for crusher ramp. In part IV it is mentioned 108850MT OB generation shown whereas in Part V it is shown Nil. In annual return the area is given 0.33ha. reclaimed/ rehabilitated but the same is not exist in ML area.
Rule 55	Employment of geologists and mining engineers.-(1) For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules,- 3. every holder of a mining lease shall employ, in case of- (iii) category 'A' mines, a whole-time mining engineer and a geologist; But the mine is not having mining engineer nor Geologist.

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत
(क) खान की सारी खनन संक्रियाएं बंद की जा सकती हैं।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करें।

भवदीय

(राजेश कुमार दास)

वरिष्ठ सहायक खान नियंत्रक
भारतीय खान ब्यूरो, रायपुर

प्रतिलिपि – for information please

- 1 खान नियंत्रक(मध्य), भारतीय खान ब्यूरो, नागपुर
2 संचालक, भौतिकी एवं खनिकर्म, छत्तीसगढ़, इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिटल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ़

वरिष्ठ सहायक खान नियंत्रक
भारतीय खान ब्यूरो, रायपुर

