INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR INSPECTION REPORT

Ajmer regional office

Mine file No : RAJ/BLW- 56 /PB,ZN-1/6/12/200: Mine code : 34RAJ06001

(i) Name of the Inspecting: SQ12) Sharma H.C.

Officer and ID No.

(ii) Designation : Sr. Asst. Contrl. Mines

(iii) Accompaning mine : Sh Ranjan Gupta, Sh. Kishore

Official with Designation

(iv) Date of Inspection : 11-AUG-18
(v) Prev.inspection date : 23-APR-18

PART-I : GENERAL INFORMATION

(a) Mine Name : RAMPURA AGUCHA

(b) Registration NO. : IBM/421/2011

(c) Category : A Mechanised

(d) Type of Working : Opencast

(e) Postal address

State : RAJASTHAN
District : BHILWARA
Village : AGUCHA
Taluka : HURDA
Post office : AGUCHA
Pin Code : 311029

FAX No. : 01483-23073

(f) Police Station : Gulabpura
(g) First opening date : 05-FEB-81

(h) Weekly day of rest : MON

2. Address for : HINDUSTAN ZINC LTD. correspondance : HINDUSTAN ZINC LTD.

RAMPURA AGUCHA MINE,

PO AGUCHA, BHILWARA

3. (a) Lease Number : RAJ0652 (b) Lease area : 1200

(c) Period of lease : 50

(d) Date of Expiry : 12-MAR-30

4. Mineral worked : LEAD & ZINC ORE Main

5. Name and Address of the

Lessee : HINDUSTAN ZINC LTD.

HINDUSTAN ZINC LTD. YASHAD BHAWAN YASHADGARH, UDAIPUR

UDAIPUR RAJASTHAN

Phone: 01483-23331, 23332

FAX :01483-23073

Owner : Sunil Duggal

Hindustan Zinc Limited Yashad Bhawan, Swaroop Sagar Udaipur BHILWARA

RAJASTHAN

Phone: 0294-2529182 FAX : 0294-2525765

Agent : Shri Vinod Kumar

Rampura-Agucha Lead-Zinc Mine Agucha, Bhilwara, Rajasthan BHILWARA

RAJASTHAN

Phone: 01483-229012 FAX : 01483-229011

Mining Engineer

Name : Shri Kishor S, Full Time

Qualification : BE Mining Appointment/ : 11-APR-18

Termination date

Geologist

Name : Ranjan Gupta, Full Time
Qualification : MSc (Tech) Geology

Appointment/ : 01-MAY-17

Termination date

Geologist

Name : Shri Gopal Singh Rathore, Full Time

Qualification : M.Sc Geology

Appointment/: 01-AUG-17 11-APR-18

Termination date

Manager

Name : Shri Vinod Jangir

Qualification : BE Mining Appointment/ : 11-APR-18

Termination date

6. Date of approval of Mining Plan/Scheme of Mining

Existing rule 11 MCDR1988 25-JAN-93 Mining Scheme rule 12 MCDR1988 15-MAY-97 Mining Scheme rule 12 MCDR1988 06-JUN-01 Modif.approved Mining Scheme 29-JUL-03 Modif.approved Mining Scheme 17-SEP-03 Mining Scheme rule 12 MCDR1988 27-FEB-06 Modif.approved Mining Scheme 02-NOV-06 Modif.of approved Mining Plan 04 - MAY - 09Mining Scheme rule 12 MCDR1988 11-JUL-12 Modif.approved Mining Scheme 28-JUN-13

PAGE : 3

Modif.approved Mining Scheme 09-APR-15 MP review under 17(1) MCR 2016 22-FEB-17 MP modif under 17(3) MCR 2016 27-MAR-18

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	Nil	Not applicable	
1b	Exploration over lease area for geological axis 1 or 2	11000m in 65 holes.	6508.55 m (U/G 1748m,Surface 4760.55m in 43 holes (U/G 30, Surface 13))
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Not specified	TDMA, Expenditure- Rs 0.23 Crore U/G, & Rs.3.03 Cr Surface	
1d	Balance area to be explored to bring Geological axis in 1 or 2	Year to year exploration had been planned.	Detailed planning at an averageof 11000m per year to up grade reserves.	
1e	Balance reserve as on 01/04/20	Not Specified	Reserves 45.95 million Tonnes With 1.9% Pb,13.8% Zn & Resources 50.49 million Tonnes with 2.4 % Pb, 11.6 % Zn.	
1f	General remarks of inspecting officers on geology, exploration etc	Not applicable	There is short fall in exploration.	

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	development	North 850 & East 150 to East 700, From 190mRL to 150mRL & 70mRL to 0mRL. Decline Dev	, Vertical Dev- 790m. Waste Generation- 196585	O/C Suspended temprorarily.

2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Nil	Open cast development suspended temporarily.
2c	Stripping ratio or ore to OB ratio	1: 8.0	Not applicable
2d	Quantity of topsoil generation in m3	Nil	Not applicable
2e	Quantity of overburden generation in m3	O/C - 888499 cu m	O/C - Nil
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	Not applicable	The workings of open cast mine had been suspended due to interaction of O/C with U/G.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	One O/C pit & one U/G Mine	Only U/G	
3b	Quantity of ROM mineral production proposed	301376 MT (O/C) & 4500000 MT (U/G)	864531 MT from U/G only.	
3с	Recovery of sailable/usable mineral from ROM production	100%	100%	
3d	Quantity of mineral reject generation	Not applicable	Not applicable	
3e	Grade of mineral rejects generation and threshold value declared.	Not applicable	Not applicable	
3f	Quantity of sub grade mineral generation.	Not applicable	Not applicable	
3g	Grade of sub grade mineral generation	Not applicable	Not applicable	

3h	Manual / Mechanised method adopted for segregating from ROM	Diluted ore is stacked seperately at stackyard & segregated using small size excavator.	Being done
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	Not applicable	Not applicable
3j	Provision of drilling and blasting in mineral benches	As per proposal	Being done
3k	Provision of mining machineries in mineral benches	By HEMM U/G machinery used.	Being done
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Not applicable as work in U/G.	Not applicable
3m	Total area covered under excavation/pits	175.12 ha	175.12 ha
3n	Ore to OB ratio for the pit/mine during the year.	1 : 8.0	Not applicable
30	Total area put in use under different heads at the end of year	Area undermining - 175.12 ha, Waste dumping 316 ha, Tailing Pond- 203.2 ha & Others- 327.27 ha	Area undermining - 175.12 ha, Waste dumping 307.76 ha, Tailing Pond- 184.6 ha & Others- 354.27 ha
3p	Production of ROM mineral during the last five year period as applicable	2017-18- 4741204MT, 2016-17 6046653MT, 2015-16 5200000MT, 2014-15 6000000 MT, 2013-14 6000000MT.	2017-18 3842187T, 2016-17 4700938MT, 2015-16 4704635MT, 2014-15 5451320 MT, 2013-14 5803852MT.

3q General remarks Not applicable Modern Technology of inspecting adopted in U/G Mine officers on method of mining etc.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	The top soil available will be stored seperately & used for stabilisation of waste dump, Slopesof Tailing Dam. O/B to bes tacked seperately.	Not applicable as U/G work only.	
4b	Location of topsoil, OB and mineral reject dumps	Top Soil- NA, O/B- North 1200 To North 2590, & West 600 to East 600.	Top soil- NA, O/B No O/B generation.	
4c	Number of dumps within lease area and outside of lease area	In side lease area.	In side lease area.	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Outside the UPL.	No waste generation.	
4e	Number of active and alive dumps.	one	one	
4f	Number of dead dumps.	NA	Not applicable.	
4g	Number of dumps established.	Dump Top & Slopes stablised with plantation.	Part of different lifts stabilised by plantation.	
4h	Whether Retaining wall or garland drain all along dumps are there.	all around the	Garland drain all around the dumps available.	
4i	Length of Retaining wall or garland drain all along dumps	all around the	Total 8.6 km garland drain along with retaining wall provided	

4j	Number of settling ponds	No proposal	Not applicable
4k	Specific comments of inspecting officer on waste dump management		Part of waste dump stabilised with plantation.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal	Not applicable	
5b	Area under backfilling of mined out area	No Proposal	Not applicable	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposal	Not applicable	
5d	Total area fully reclaimed and rehabilitated	Nil	The part of waste stabilised by plantation.	dump
5e	General remarks of inspecting officers on backfilling and reclamation etc.		The part of waste stabilised by plantation.	dump

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Yes	Submitted	
6b	Area available for rehabilitation (ha) .	No proposal	Not applicable	

6c	afforestation done (ha).	20 ha of waste dump	20 ha of waste dump
6d	No. of saplings planted during the year	20000 nos	20000 nos
бе	Cumulative no .of plants	N A	311650nos
6f	Any other method of rehabilitation	No proposal	Not applicable
6g	Cost incurred on watch and care during the year	No proposal	Rs.177.24 lakh
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	No proposal	Not applicable
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No proposal	Not applicable
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No proposal	Not applicable
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No proposal	Not applicable
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No proposal	Not applicable
бm	Compliance of rehabilitation of waste land within lease (i)afforestation	20000 nos at waste dump	20000 nos at waste dump

бn	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	20 ha of waste dump	20 ha of waste dump
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	No proposal	Not applicable
6p	Compliance of environmental monitoring (core zone and buffer zone)	Yes	Regular monitoring of various parameters done in core & buffer zone.
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	Not applicable	The conduct of Lessee towards implementation of PMCP was satisfactory.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	ROM having grade variability stacked separately & blended.	Being done	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Mechanized	Being done	
7c	Different grade of mineral sorted out at mines.	Different grades of stacked mineral on PCH Pad andoptimum grade to beneficiation plant.	Different grades of stacked mineral on PCH Pad andoptimum grade to beneficiation plant.	
7d	Any beneficiation process at mines	Yes	Yes	

7e General remarks Not applicable ROM is beneficiated in of inspecting the plant having officer on instream analyzer to Mineral monitor the reject conservation and generation & beneficiation that are stored in tailing issues dam.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	stored	No top soil generation	
8b	Concurrent use or storage of topsoil	yes	No top soil generation	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Mineral & O/B wastestackedse parately in PCH pad & waste dump.	Being done	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposal	Not applicable	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Plantation of 20 ha area of waste dump.	NIL	
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	20000 nos to beplanted each year.	Nil	
8g	Survival rate	80%	NA	

8h	Water sprinkling on roads to control airborne dust	Yes	Effective sprinkling done regularly.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	Not applicable	The general aesthatic beauty in & around mine is satisfactory.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Not applicable	M/R submitted up to september 2018. A/R submitted for 2017-18.	
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Manager - Sh. Ram shankar Sharma, Mining Engineer- Sh Jaimurti Sandeep, Geologist- Dr Uma Shankar Pareek.	Manager - Sh. Vinod Jangir w.e.f.11/4/2017, Mining Engineer- Sh. KIshore S since11/4/2018, Geologist- Sh Ranjan Gupta since 1/5/2017.	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Details furnished	Pit-175.12 ha, Reclaimed 81.00 ha, Waste disposal- 307.76 ha, occupied by plant building 92.640, othrs - 17.00 ha	
9d	Scrutiny of Annual return on afforestation	17000 nos planted within lease with survival rateof 90%.	Found in order	
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Reject Generation - NIL	Reject Generation - NIL	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	Details furnished	Opening stock 464737T, Production - 3842187T, Closing stock 71972 T	
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Details furnished	Ex Mine Price- Rs. 2160.75 , & the cost of production-Rs. 8404.25	

9h	Scrutiny of Annual return on fixed assets	Detals Given	Fixed assets Rs.34278110324.00 & depriciation Rs.6324803302.00
9k	Scrutiny of Annual return on mining machineries		

PAGE: 14

Details of violations observed during current inspection and compliance position of violation pointed out				
Violat	cion observed	Show couse position		
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on	

Date : (Sharma H.C.)

Indian Bureau of Mines