

भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0974-2352483; TeleFax: 0874-2352490; eMail: ro.bhubaneshwar@ibm.gov.in Plot No.149, Pokhariput BHUBANESWAR-751016 Date:12.01.2018

REGD/AD

Date: 12/01/2018

No.: ORI/IRON/SNG/MCDR-1/BBS/ VOL-II/ 251 र् सेवा में, Shri Kalyan Maity Director (RM & Logistics) & Nominated Owner

M/s Steel Authority of India Ltd, 10 Camac Street, PO Circus Avenue, Kolkata

State: West Bengal, Pin Code-700017.

Sub: Violation of provisions of MCDR, 2017 in respect of your Barsua Iron Mine over an area of 2486.383 hectare (ML-130) in Sundergarh district of Odisha.

Sir.

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 09.01.2018 by the undersigned accompanied by S/Shri B K Soren, Mine Manager, S K Khande, Mining Engineer and R P Mondal, Geologist of your mine

your mine.			
Rule No.	Proposed in the approved mining plan / Rule	Violation	
11 (1)	As per the approved mining scheme dated	i) During inspection it is reported that	
	04/09/2015,	Nil production of ROM iron ore and	
	i) It is proposed to produce Iron ore ROM of	generation of 0.5 million cu.m. of	
	4.97 Million tonnes with zero waste generation	waste for the year 2016-17.	
	for the year 2016-17.	ii) During inspection it was observed	
	ii) It is proposed to backfill exhaust portion of	that the waste generated from quarry-	
	Area-3 by waste material generated from	3E & 3W was dumped over subgrade	
	quarry-3E & 3W.	dump no.8.	
	iii) It is proposed for afforestation covering area	iii) During inspection it is reported	
	of 15 ha as dump management and stabilization	that 5 ha area has afforested and	
	of SG stacks by coir matting covering an area	stabilization of SG stacks by coir	
	of 15 ha during 2016-17.	matting done over 1 ha for 2016-17.	
14 (1),	All the non-saleable or un-usable mineral above	During inspection it is observed that	
(2) & (3)	threshold value of the mineral shall be stacked	the waste generated from the mine	
	separately, month wise inventory of the	operations are dumped over sub grade	
	material stacked with quantity and quality	stack no.8, whereas both should not be	
	above the limit of threshold value of the mineral	mixed. Month wise inventory of sub	
	shall be updated, the overburden and waste	grade mineral stacked with quantity	
	material obtained during operations shall not be	and quality was not maintained.	
	allowed to be mixed with the materials		
	specified in sub rule 91).		
45 (7)	Holder of mining lease shall not submit	During scrutiny of annual return it is	
	incomplete or wrong or false information in	found that	
	daily or monthly or annual returns.	i) Details furnished under Item 12	
		(part-I) regarding surface area	
		utilization at the end of the year are	
		not matching with the actual field	

-0/1

1 swed

	conditions.  ii) Overburden removed quantity furnished under item 3 of part-IV includes subgrade material quantity, whereas only waste quantity should be furnished.  iii) It is reported that 0.81 million tonnes of subgrade/mineral reject generated but the same was not furnished under 4.2 (B) of part-V.
--	---

**02.** It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

Further, in view of the above position, the information furnished under Rule 45(5) in the Annual return is construed as furnishing wrong or false information, which leads this office to advise the state government under rule 45 (7) to,-

- (i) Order suspension of all mining operations in the mine and to revoke the order of suspension only after ensuring proper compliance;
- ii) Take action to initiate prosecution under these rules;
- (iii) Recommend termination of the mining lease, in case such suppression or misrepresentation of information indicates abetment or connivance of illegal mining;
- 03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully.

n. lade

Senior Assistant Controller of Mines Indian Bureau of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- (1) खान नियंत्रक(मध्यांचल)/The Controller of Mines (CZ/EZ),भारतीय खान ब्यूरो / Indian Bureau of Mines, Nagpur-440001/Kolkata-700091.
- (2) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार /Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग /Heads of Department Building, न्यू कैपिटल /New Capital, भुवनेश्वर /Bhubaneswar-751 001: For information & further necessary action on following:

(Ramkishan R

Senior Assistant Controller of Mines कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines

- ol c-