

By Regd., A/D

GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES

C-4-A, Rajaji Bhavan  
CGO complex, Besant Nagar  
Chennai-600  
090.

No. TN/TCR/LST-47.MDS

Mine code: 38TMN14058

Date : 30.12.2014

To  
Sri P.Saravanan,  
Mathur limestone mine,  
S/o Late R.Perumal,  
49,Raja Illam, Jeeva nagar  
Trichy-620 008.

Sub: Violation of provisions of Mineral Conservation and Development Rules,1988, in respect of your Mathur limestone mine over 1.955 hect in Mathur village, Trichy district, Tamilnadu State.

Sir,

The following provisions of the MCDR, 1988 were found violated in your above mine during the MCDR inspection by Sri A.S.Sanjeeva Rao, Asst., Mining Geologist on 18.11.2014 in your presence.

Rule No	Nature of Violations observed
13(1)	Though proposals made in the approved scheme of mining in the para no.3.0 under year-wise exploration as per the table no.11, for carrying out 08 no of auger bore holes in the year 2013-14. But, the same has not been carried out by you till date.
45(5)(b)	The Owner, Agent, Mining Engineer or Manager of every mine should submit an annual return of the mine before the 1st July every year for the preceding financial year in form H-8. But the lessee has not submitted the same to the Regional Controller of Mines, Indian Bureau of Mines, Chennai for the year 2013-14 till date.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of Mineral Conservations and Development Rules, 1988.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(T.K.Rath)  
Regional Controller of Mines  
Indian Bureau of Mines

Copy forwarded to :

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Commissioner, Department of Geology & Mining, Chennai.

(T.K.Rath)  
Regional Controller of Mines  
Indian Bureau of Mines

