



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कॉलोनी, देहरादून (उत्तराखण्ड), 248001 / 100 Old Nehru Colony, Dehradun (U.K.) 248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in

Violation-Letter
E-MAIL / REGD A.D.



फाईल संख्या File No: HP/SRM/LST-18

Mine Code: 38HPR10011

दिनांक, 01-02-2021

सेवा में To : M/s Mam Chand Goyal & Sons
99/3-3, Ganga Vihar,
Haridwar Road, Dehradun

E-mail: goyalsunil63@gmail.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Banour Limestone Mine, Mining Lease over an area of 4.958 ha located near Village: Banour Tehsil: Paonta Sahib, District-Sirmour, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 02.11.2020 in the presence of Shri R.C Malik, Mine Manger.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining operation were not carried out in accordance with the approved Review & Updation of mining plan with PMCP vide letter no 614(2)/MPB-285/08- DDN dated 25.01.2019 to the following extent: (i) Chapter -2 page no 20 the height of benches in limestone was proposed 6 meter but during the inspection benches height was found more than 6 meter which is not maintained as per proposals. (ii) Chapter-8 page no-46 as per proposals during year 2019-20, it was proposed to erect wire fencing 40 mtr but erection of wire fencing was not carried out as per proposal.
45(7)	The holder of a mining lease has submitted incomplete or wrong information as follows: <u>Annual Returns:</u> 1. Part-VII Cost of Production –Reported production cost of Limestone is 500/Tonnes which is very high. 2. Reported Ex mine Price is high for year 2019-20. 3. Lease no details are not correct. <u>Monthly returns:</u> 1. Part-II, details of consignee including registration no. shall be furnished in the returns
47	The holder of a mining lease shall send intimation in Form I of the Schedule to the authorised officer, within fifteen days after the commencement the sinking of borehole to a depth exceeding ten meters from the surface but intimation not sent to authrorised officer.
48	The holder of a mining lease shall keep a record in Form-J of all boreholes and shall retain such records and preserve the samples of the strata passed through for a period of not less than twelve months after the completion of the work or abandonment thereof. But during inspection Form-J of all boreholes was not found.

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operation can be suspended as per rule 11(2) in case of non-compliance of any Rule/sub-rule of 11 of MCDR 2017.
4. Advise the State Government to order suspension of all mining operation in the mine as per provision of Rule 45(7), in case incomplete or wrong or false information has been furnished in statutory returns or fails to submit statutory returns under rule 45.
5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.

भवदीय Yours faithfully,

01.02.2021

(दामोदर प्रसाद शर्मा /D P Sharma)

सहायक खान नियंत्रक /Assistant Controller of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक /Assistant Controller of Mines