



भारत सरकार Government of India  
खान मंत्रालय Ministry of Mines  
भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines  
100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखंड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001  
TEL- 0135-2676350 / 2671896, E-mail – [ro.dehradun@ibm.gov.in](mailto:ro.dehradun@ibm.gov.in)



फाईल संख्या File No: HP/SRM/LST-41

Mine Code: 38HPR10035

दिनांक, 01.02-2021

सेवा में To : Shri Deepak Chawla  
S/o Late S.C Chawla  
43-Gandhi Road  
99/3-3 Ganga Vihar  
Dehradun-248001 (Uttarakhand)

E-mail: [chawla\\_sidh@rediffmail.com](mailto:chawla_sidh@rediffmail.com)

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Banour Limestone Mine, Mining Lease over an area of 4.75 ha located near Village: Banour Tehsil: Paonta Sahib, District-Sirmour, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 14.01.2021 in the presence of Shri R C Malik, Mine Manger.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining operation were not carried out in accordance with the approved modified mining plan with PMCP vide letter no 614(2)/76- DDN dated 10.08.2015 to the following extent: (i) Chapter -2 page no 30 the height of benches in limestone was proposed 6 meter but during the inspection benches height was found more than 6 meter which is not maintained as per proposals.
33	The holder of a mining lease shall, on or before the 30 <sup>th</sup> day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. However, the lessee has not submitted the copies of the plans and sections as per rule for the year 2019-20.
45(7)	The holder of a mining lease has submitted incomplete or wrong information as follows: <u>Annual Return:</u> 1. Part- IV Consumption of Explosive-Quantity of explosive consumption is very low which is not correct in r/o of production quantity. 2. Reported Ex mine Price is not correct of year 2019-20. 3. Part-VII Cost of Production –Reported production cost of Limestone is Rs.490/Tonnes which is very high. <u>Monthly Return:</u> 1. Part-II, details of consignee including registration no. shall be furnished in the returns.

- In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- Mining operation can be suspended as per rule 11(2) in case of non-compliance of any Rule/sub-rule of 11 of MCDR 2017.
- Advise the State Government to order suspension of all mining operation in the mine as per provision of Rule 45(7), in case incomplete or wrong or false information has been furnished in statutory returns or fails to submit statutory returns under rule 45.
- You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.

भवदीय Yours faithfully,

(दामोदर प्रसाद शर्मा /D P Sharma)

सहायक खान नियंत्रक /Assistant Controller of Mines  
-भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुरा। (zo.udaipur@ibm.gov.in)
- निदेशक उद्योग निदेशालय, हि० प्र० सरकार, उद्योग भवन, शिमला (हि० प्र०)। (geologicalwing@gmail.com)
- गार्ड फाइल

सहायक खान नियंत्रक /Assistant Controller of Mines