

**Speed post /तीव्र डाक**

भारतसरकार  
खानमंत्रालय  
भारतीय खानब्यूरो  
क्षेत्रीय खाननियंत्रक कार्यालय  
माखपुराओद्योगिक क्षेत्र अजमेर 305002  
ई-मेल: ro.ajmer@ibm.gov.in

**Violation letter /उल्लंघन पत्र**

Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of Mines.  
Makhapura Industrial Area, Ajmer- 305002  
Ph-145-2695165 / 2695476 Fax-2695202

संख्या : RAJ/Bad-18/Selenite-11

दिनांक: 13 /04/2022

प्रेषित : खान एजेन्ट,  
थोब- II सेलेनाईट खान,  
मेसर्स आर. एस. एम. एम. लिमिटेड,  
4-गांधीनगर स्कीम,  
जिला -बीकानेर,  
राजस्थान - 334 001  
[info.rsmml@rajasthan.gov.in](mailto:info.rsmml@rajasthan.gov.in) , [akjaiswal.rsmml@rajasthan.gov.in](mailto:akjaiswal.rsmml@rajasthan.gov.in)

विषय: Violation of provision of Mineral Conservation and development rule 2017 in respect of your Thob-II Selenite Mine in Barmer district of Rajasthan State.

महोदय,

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found violated in your above said mine during inspection on 23/03/2022 by undersign in presence of Sri P. Leela Kumar, Manager Survey, Sri Imran Ali, Manager Geology and Sri Bhanwar Singh Rathod, Assistant Manager of your company:

Rule	Status and extent of violation
11(1)	Mining operations have not been carried out in accordance to Review of Mining Plan approved on 23/08/2017 to the extent given below for the year 2020-21: (1) A total of 15 number of prospecting pits proposed during the year 2018-19 has not been carried out. (2) The recovery of Selenite Mineral from ROM has been proposed 50%. However, as per production figures furnished in annual return for the year 2020-21, the recovery of Selenite Mineral from ROM has been achieved 100%. (3) An area of 3.20 hectare with 500 numbers of plants was proposed to plant within lease area during the year 2020-21. However, plantation as proposed has not been carried out in the lease area.
12(4)	As per rule detailed exploration (G1 level) over the entire potentially mineralised area under the mining lease shall be carried out within a period of five years from the date of commencement of MCDR, 2017. However, it is observed that exploration as mentioned in the rule has not been carried out.
26(2)	The yearly report on extent of protective and rehabilitative works carried out as specified in the rule has not been submitted to the Regional Controller of Mines (competent authority) for the year 2020-21.
55	As per rule every holder of mining lease shall employ a Mining Engineer and Geologist. However, it is observed that Mining Engineer and Geologist have not been appointed.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

- आपकी खदान की सारी सक्रियाएं बंद की जा सकती है।
- आपके विरुद्ध अभियोग दायर किया जा सकता है।
- राज्य सरकार को खनन पट्टे की समिति की सिफारिश।

03. इस संबंध में आपका ध्यान आकर्षित किया जाता है कि नियम 12(4) एवं 55 के उल्लंघन के लिए खनिज संरक्षण एवं विकास (संशोधन) नियम 2021 की अनुसूची-III के प्रावधान लागू होंगे।

04. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैंतालिस) दिनों के भीतर इस कार्यालय को सूचित करें।

भूवदीय  
०८/१३/०४/२०२२

(दिलीप जैन)

वरिष्ठ खनन भूविज्ञानी  
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, बाड़मेर (राजस्थान)
- 4 रक्षित पत्रावली।

०८/१३/०४/२०२२

वरिष्ठ खनन भूविज्ञानी  
भारतीय खान ब्यूरो