

संख्या: राज/राजी/चुनापत्थर-01/ खानकोड 38RAJ21001 दिनांक : 19-09-2022

सेवामें,

श्री संदीप कुमार सिंह, खान एजेंट, मेसर्स अंबुजा सीमेंट लिमिटेड, रास चुनापत्थर खान, पोस्ट राबरियावास, तहसील-जैतारण पाली-306709

विषय: राजस्थान राज्य के पाली जिले के जैतारण तहसील के राम गांव में स्थित आपकी राम-2 चुनापत्थर ख़ान में

खनिज संरक्षण एंव विकास नियमावली, 2017 के नियमों का उल्लंघन

महोदय,

अद्योहस्ताक्षरी द्वारा दिनांक 03.08.2022 को आपकी उपस्थिती में उपरोक्त खान का निरीक्षण किया गया था और खनिज संरक्षण एंव विकास नियमावली, 2017 के निम्निलिखित नियमों का उल्लंघन पाया गया है ।

नियम	
	उल्लंघन के प्रकार का विस्तृत व्योरा उल्लंघन के प्रकार का विस्तृत व्योरा The mining operations in the lease area are not carried out as per modified mining plan approved vide letter No. 584(4)(3)(1877)/2021 RCOM Ajmer dated 16.08.2021 and following deviations are observed during inspection. (a) It was planned & proposed to work in Northern Western Ridge, Sub Western Ridge, Western Ridge, Eastern Ridge and temple hill to achieve 35,99,700t ROM limestone production. It is observed during inspection and from submitted drone image that development & production in between grid lines N3300-3400 on temple hill, N2500-2900 in eastern ridge not carried out and total ROM production during the year was 25,37,074t only. The achieved production was 30% lesser than the target due to purchase of 3,46,910t minor mineral limestone from the various traders/dealers and the limestone is sourced from the nearby minor mineral lease holders. The achieved production during last 5-6 years was less than 40% of the target in these years. (b) It was planned & proposed to dump the IB waste by advancing W2 between gridline N3800-N4200 and by advancing W3 from gridline N5780-N5880 during the years 2021-22. It is observed during inspection, updated plan & sections and
	drone image that dump W2 and W3 are not advanced at the proposed location. The IB waste material has been dumped over existing dumps indeviation of the proposals.
32(1)(b)	 a) The updated geological plan as on 31st March 2022 is not showing the exploration carried out during the year 2021-22; although proposed 13 boreholes during the year are reported as completed.
32(5)(b)	a) The updated environment plan as on 31 st March 2022 is not showing the constructed retaining wall and garland drain during the year 2021-22; although proposed 440m and 425m garland drain during the year are reported as completed by constructing 450m retaining wall & 425m garland drain. The work done under progressive mine closure plan during the year is reported zero for the year 2021-22 in item-12 of Part-I in the annual return.

- 45(5)(b) Following deficiencies are observed in the annual returns of the mines submitted for the year 2021-22 in Form-G-1.
 (a) The cost of electricity generated, tyres, drill rods is reported zero in Part-III.
 (b) Total quantity of Overburden/Waste removed during the year is reported zero in Part-V Item 4.2(C), altjough interburden waste removed & dumped.
 - (c) The pulverization details in table 3 of Part-VI is not filled; although crushing activity is carried out within lease area and screen reject is also reported.
 - (d) The cost of pulverization is reported ₹ 0.00 per tonne in Part-VI item 3(ii) and not separately shown in the cost of production.

03. उपरोक्त नियम का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अन्तर्गत दंडनीय अपराध है और खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 45(7)(a) के अन्तर्गत खान में खनन प्रचालनों और प्रेषणो को निलंबित का आदेश भी जारी किया जा सकता है ।

04. अत: आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघन का अतिशीघ्र सुधार करें एंव इसके सुधार की स्थिती की जानकारी इस पत्र के जारी होने की दिनांक से 45 (पैतालीस) दिनों के भीतर इस कार्यालय को सूचित करें ।

भवदीय 19,09,20 गेरीश कुंमार जांगिड) क्षैत्रीय खान नियत्रंक