

मेल/त्वरित डाक द्वारा



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं. KNT/BLR/Fe-52/BNG

दिनांक: 27.01.2021

सेवा में

Shri. P V Prakash,
Nominated Owner,
M/s P.Balasubba Setty & Son,
D.No:2078, P.B.No-03, 22nd ward,
J.P.Nagar, Bellary Road, Hosapete
Karnataka-583201

विषय/Sub : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Karadikolla (Suresh) Iron Ore Mine (ML-2502) over an area of 42.10 Ha located in Karadikolla Village, Sandur Taluk, Bellary District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. Y.V.RamaKrishna Reddy, Manager Mining, Shri. J. Vijay Narasihulu, Mining Engineer and Shri.N.Sivaprasad, Geologist on 09.12.2020

Rule	Nature of violations observed
11(1)	<p>Modification to the approved RMP was approved vide letter no.279/125/89/BNG dated 13.07.2018 for a period of 2018-19 to 2022-2023. The deviation observed in mining operation vis-a-vis approved document are given below</p> <p>(i) It was observed that about 40,000 Tons of finished product (Lumps) was stocked in location N15° 13'41.3" & E 76° 25' 49.8" in 807 mRL which was proposed for excavation in the current plan period causing hindrance for the movement of benches & production.</p> <p>(ii) It was observed that 960 mts of Retaining wall & Garland drain were constructed against the proposal of 1000 mts.</p>

45 (7)	In part VI, Sec. 2 of the annual returns, Production from the dump workings is shown as nil thereby mismatch in the opening & Closing stock.
--------	--

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुण कुमार)
उप खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ/ Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

उप खान नियंत्रक
भारतीय खान ब्यूरो