

भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय/ MINISTRY OF MINES

भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमक्र रोड,

गोरग्ंटापाल्या येशवंतप्र,

बेंगल्र -560022

दूरभाष: 080-23371027 / 23375366/67 Email ID: ro. bangalore@ibm.gov.in.

दिनांक:03.02.2021

सं. KNT/GLB/Lst-52/BNG

सेवा में

Shri. Mahendra Kumar Garg, Agent Mines,Shree Cement Ltd., P.B. No. 33, Bangur Nagar, P.O. Beawar, Dist: Ajmer, Rajasthan—305901

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Kodla Limestone Mine (ML No. 2673/2674) over an area of 517.61 Ha located in Kodla & Benkanhalli Village, Sedam Taluk ,Kalaburagi District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. Kiran Naidu, Manager Mining, Shri. Saddique Basha, Mining Engineer and Shri. G.N.S. Rangarao, Geologist on 11.12.2020

Rule	Nature of violations observed
11(1)	Modified RMP including PMCP was approved vide letter no. 279/1043/2009/BNG dated 06/03/2020 for a period of 2019-20 to 2021-22. The deviation observed in mining operation vis-a-vis approved document are given below
	It was proposed to develop one main pit and two rain water harvesting pits. During the site inspection it was observed that only one rain water harvesting no.1 has been developed. Clarification sought for not developing the Rain Water Harvesting pit 2.

26(1)	Retaining wall of 300 mts in OB dump No.1, 230 mts in OB dump no.2 & 450 mts in OB dump no.3 was proposed. It was observed that only 100 mts in OB dump No.1, 80 mts in OB dump no.2 & no retaining wall in OB dump no.3 was constructed.
35 (2)	Every holder of a mining lease shall monitor his mining and allied activities as per the notified template of star rating in the format prescribed in this behalf by the Indian Bureau of Mines from time to time, and shall submit online its self assessment report before the 1st day of July every year.
	Online self assessment template of Star Rating has not been sent to this office so far.

- 02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.
- 03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुण कुमार) उप खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ'/Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

उप खान नियंत्रक भारतीय खान ब्यूरो