

मेल/त्वरित डाक द्वारा



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं. KNT/BLR/Fe-397/BNG

दिनांक:03.02.2021

सेवा में

Shri. Sanjeev Sahi,
Agent -Mines,
NMDC Limited,
P.O. Donimalai Township,
Dist. Bellary,
Pin-583118
Karnataka.

विषय/Sub : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Kumarswamy Iron Ore Mine (ML-1111) over an area of 647.50 Ha located in Kammathuru Village, Sandur Taluk ,Bellary District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. Dhiren Bhushan, Manager Mining, Shri. R. K. Tekam, Excavation In-charge and Dr. D.N.Subramanyam, Geologist on 08.12.2020

Rule	Nature of violations observed
11(1)	<p>Modification to the approved RMP was approved vide letter no.279/290/91/BNG dated 13.12.2019 for a period of 2020-21 to 2021-2022.The deviation observed in mining operation vis-a-vis approved document are given below</p> <p>Development of faces was proposed in between cross sections C/ 21 ¹/₄ & C/ 21 ⁷/₈ (1018 & 1024 mRL), C/ 18 ³/₄ to C/ 19 ³/₈(1042 mRL) & C/ 11 ³/₈ to C/ 12 ¹/₂ (1030 & 1036 mRL) in pit 1 of C Block. It was observed during the inspection that the extent of development proposed in between these section lines were short by 30-40 mtrs.</p>

45(7)	In Part V, Sec 3 of the annual returns, only 29 Tons, 21 Tons & 20 Tons have been furnished under probable mineral reserves (121), Feasibility mineral resources (211) & Inferred mineral resources (333) respectively which is not aligned with the reserves & resources furnished in the approved document.
-------	---

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुण कुमार)

उप खान नियंत्रक

भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ/ Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

उप खान नियंत्रक

भारतीय खान ब्यूरो