

मेल/त्वरित डाक द्वारा



भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं. KNT/GLB/Lst-7/BNG

दिनांक:03.02.2021

सेवा में

Shri. Seetharamulu Chittanuru,
Agent Mines,
ACC Limited, Wadi
Taluk: Chittapur,
Dist.Gulbarga,
Karnataka-585225

विषय/Sub : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Wadi Cement Works Limestone Mine (ML-2641) over an area of 471.03 Ha located in Ingalgi & Ravoora Village, Chittapur Taluk ,Kalaburagi District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. Vikram Singh, Manager Mining, Shri. B N Prasadrao, Mining Engineer and Shri. Jagadish K Madival, Geologist on 10.12.2020

| Rule | Nature of violations observed |
|-------|---|
| 11(1) | Modified RMP including PMCP was approved vide letter no. 279/116/89/BNG dated 09.09.2020 for a period of 2020-21 to 2022-23.The deviation observed in mining operation vis-a-vis approved document are given below During the year 2019-20, only 6, 44,333 Tons of overburden was handled against the proposal of 7,15,034 tons. |

| | |
|-------|--|
| 13(1) | <p>In open cast workings, the benches formed shall be so arranged that the benches in ore or mineral and overburden are separate so as to avoid mixing of waste with the ore or minerals.</p> <p>It was observed that the advancement of OB bench in between section line 11-11' to 13-13' in the western side of the pit was not carried out, thereby mixing of the waste/OB bench with limestone bench</p> |
|-------|--|

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुण कुमार)

उप खान नियंत्रक

भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ/ Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhan, R.C. Road, Bangalore-560 001

Sd/-

उप खान नियंत्रक

भारतीय खान ब्यूरो