



भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
माखपुरा औद्योगिक क्षेत्र, अजमेर
305002



स्पीड पोस्ट
GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES OFFICE
OF REGIONAL CONTROLLER OF
MINES
Makhapura Ind. Area, Ajmer – 305002

संख्या: राज/पाली-113/चुनापत्थर-03/ खानकोड 38RAJ21003 दिनांक : 29-12-2022

प्रेषिती: श्री महेंद्र कुमार गर्ग, खान एजेंट,
मेसर्स श्री सीमेंट लिमिटेड,
निंबेति चुनापत्थर खान, पोस्ट रास,
तहसील जैतारण, पाली-

विषय: राजस्थान राज्य के पाली जिले के जैतारण तहसील के निंबेति-रास गांव में स्थित आपकी निंबेति चुनापत्थर खान (750.00 हेक्टेयर) में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन महोदय,

अद्योहस्ताक्षरी द्वारा दिनांक 12.12.2022 को श्री पंकज अग्रवाल, खान प्रबन्धक एवं श्री राजेंद्र सिंह राजपुरोहित, खनन भूविज्ञानी की उपस्थिति में उपरोक्त खान का निरीक्षण किया गया था और खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्निलिखित नियमों का उल्लंघन पाया गया है।

नियम	उल्लंघन के प्रकार का विस्तृत ब्योरा
11(1)	The mining operations in the lease area are not carried out as per review of mining plan approved vide letter No. 584(4)(3)(1806)/2019-RCOM Ajmer dated 03.12.2019 and following deviations are observed during inspection. (a) It was planned & proposed to produce 25.30 million tonnes of ROM production every year; however it is observed 16.62 million tonnes & 15.47 million tonnes production achieved during the year 2020-21 & 2021-22 respectively, which is almost 40% lesser than targets. The production achieved upto Nov 2022 during 2022-23 is also in similar range with deviation of almost 40% lesser than targets and continuous difference in achieved production from the targets during last three years has reached to a stage of more than one year backlog in development & production planning. Thereby, lateral & vertical extent of development & waste management in not possible to validate on yearly basis and purpose of referring the RMP for systematic & scientific mining got defeated.
45(5)(b)	Following deficiencies are observed in the monthly returns of the mines submitted in Form F-1. (a) The opening & closing stock of ROM quantity is always reported as zero in Part-II; although ROM stock is maintained within lease area near crusher-4 and a stock of almost 1.5 lacs tonnes was observed during inspection of the mine. (b) The Ex. Mine price of Rs.303/- in the month of April 2022 is too much on higher side compared to previous and after months in 2021-22 & 2022-23; which was in the range of Rs.200 to Rs.240. (c) The sales & dispatch table is showing four rows of cement grade limestone to the consignee 'Shree Cement Limited'; however purpose of reporting four separate records without any difference in consignee name is not correct & justified, since consignee is having 8 cement units in Ras & two cement units in Andheri-Deori.
45(5)(c)	Following deficiencies are observed in the annual returns of the mines submitted for the year 2021-22 in Form-G-1. (a) The quantity & cost of electricity generated is reported zero in Part-III. (b) Total quantity of Overburden/Waste removed during the year is reported zero in Part-V Item 4.2(C), although its dumped quantity of 5847655t is mentioned. (c) The pulverization detail in table 3 of Part-VI is not filled; although crushing & stacking in piles activity is carried out within lease area. (d) ROM mineral is beneficiated through screens/wobler; however screen reject is



भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
माखपुरा औद्योगिक क्षेत्र, अजमेर
305002



स्पीड पोस्ट
GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES OFFICE
OF REGIONAL CONTROLLER OF
MINES
Makhupura Ind. Area, Ajmer – 305002

not reported separately in the AR. It was discussed during inspection and reported that grade of screen reject is less than threshold limit and therefore, considered & reported in waste generated.

(e) The cost of pulverization (Beneficiation-Mechanical only) is reported Rs.0.00 per tonne in Part-VI item 3(ii) and not separately shown in the cost of production.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियम का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियम के उल्लंघन की अनुपालन नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत:
- (क) आपकी खान की सारी संक्रियाएं बंद की जा सकती हैं।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
(ग) राज्य सरकार को खनन पट्टे की निलंबित का आदेश की सिफारिश जा सकती है।
03. अतः आपको सलाह दी जाती है कि आप उपरोक्त नियम के उल्लंघन का अतिशीघ्र सुधार करें एवं सुधार की स्थिति कि सूचना इस पत्र के जारी होने कि दिनांक से 45 (पैंतालीस) दिनों के भीतर इस कार्यालय को सूचित करें।

भवदीय

(गिरीश कुमार जांगिड)
क्षेत्रीय खान नियंत्रक

प्रतिलिपी सूचनार्थ :

1. खान नियंत्रक (उ. आ.) भारतीय खान ब्यूरो, उदयपुर
2. सहायक खनि अभियंता, खान एवं भूविज्ञान विभाग, सोजत, जिला-पाली 303108

(गिरीश कुमार जांगिड)
क्षेत्रीय खान नियंत्रक