



भारत सरकार /Govt of India  
खान मंत्रालय /Ministry of Mines  
भारतीय खान ब्यूरो / Indian Bureau of Mines  
हैदराबाद क्षेत्रीय कार्यालय / Hyderabad Regional Office



Phone No. : (040)-29555603/29554603  
E-mail: ro.hyderabad@ibm.gov.in  
No. AP/RR/LST-3/HYD.

Room No.603, 6th Floor,  
CGO Towers, Kavadiguda,  
Secunderabad – 500 080  
Date: 22.12.2020

To,

The Nominated Owner/ Agent  
Sangamkalan Limestone Mine-I  
The India Cements Ltd.,  
Sangamkalan Village, Tandur Mandal,  
Vikarabad District,  
Telangana State – 501158.

Sub: Violation of provision of Mineral Conservation and Development Rules, 2017 in respect Sangamkalan Limestone Mine-I (38APR23002) of The India Cements Ltd over an extent of 112.80 ha. in Sangamkalan village and Tandur Mandal in Vikarabad district of Telangana state.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the inspection on 11.12.2020 in the presence of Shri. Mallikarjun Reddy, Mine Manager.

Rule No.	Nature of Violations observed
11 (1)	No holder of a mining lease shall commence or carry out mining Operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines. Your Modification of Mining Plan document was approved vide letter No.AP/RR/MP/LST-7/HYD dated 02/02/2018 and following deviations have been observed: i. It was proposed to plant 500 Nos. of saplings along the sides of haul road and lease boundary during the year 2020-21. However during inspection it was noticed that no plantation done as per the proposal.
31 (4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule of rule 55, and within twelve months in the case of any other mine. The plans and sections required under these rules have not been maintained up to date.
36 (1)	Every holder of a prospecting licence, prospecting license-cum-mining lease or a mining lease shall, wherever top soil exists and is to be excavated for prospecting or mining operations, remove it separately. The topsoil existing in the working area is not being excavated separately.
45(7)	Following deficiencies were observed in the Annual Returns submitted for the year 2019-20 : The details of DMF and NMET have not been furnished in Part-III, Sl.No.5 and in the cost of production table of Part-VII.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of MCDR, 2017. Further, inability to comply the provision of Rule 11(1) is liable for suspension of mining operations under 11(2), 45(7)(a)(i) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

(Madhu Sudhan Yadav. M)  
Assistant Controller of Mines

Copy for information:

1. खान नियंत्रक (दक्षिण क्षेत्र), भारतीय खान ब्यूरो, बेंगलोर.
2. The Director, Department of Mines & Geology, Government of Telangana.
3. The Assistant Director of Mines & Geology, Tandur, Vikarabad district, Government of Telangana.

मधु सुधन यादव . एम (Madhu Sudhan Yadav M.)  
I gk; d [kku fu; ¢d/ Assistant Controller of Mines