



GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
NAGPUR REGIONAL OFFICE

6<sup>TH</sup> Floor, 'B' & 'C' Block  
Indira Bhavan, Civil Lines  
Nagpur- 440102  
Telephone%2562794,  
2565089 (Tel/fax)

Regd.

No. MAH/YTL/Lst-43/NGP/Vol-II Mine Code 38MSH26013

21  
Date 17.09.2021

To

M/s ACC Limited  
Chanda Cement Works,  
P.O. Cement Nagar,  
Chandrapur-442502  
Maharashtra

Sub: Violations of provisions of Mineral Conservation and Development Rules-2017 in respect of your **Govari Limestone Mines (Area -558.90 Ha, Mine Code-38MSH26013)** situated in District- Yawatmal of Maharashtra State

Sir,

This is with reference to the MCDR inspection carried out by undersigned on dated 08.09.2021 of aforesaid lease and upon examination of this office records. The following provisions of Mineral Conservation and Development Rules, 2017, amended vide notification of GSR 169(E), dated 27.02.2017 are found violated in respect of your above referred mine:-

Rule	Nature of Violations observed
37(2)	<p>The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods.</p> <p><i>However during inspection it was observed that dumps have achieved almost its ultimate heights and plantation has not been done over the slopes and other areas of dumps for its stability. Retaining wall has also been constructed only for 100 metre length of dumps whereas whole length of</i></p>

	<i>dump has not been secured by retaining wall to arrest run off/wash off.</i>
41	<p>Every holder of prospecting license, prospecting licence, prospecting licence cum mining lease or mining lease shall take all possible precautions to prevent or reduce the discharge of toxic and objectionable liquid effluents from mine, workshop, beneficiation or metallurgical plants, tailing ponds into surface water bodies, ground water and usable lands , to a minimum .</p> <p><i>However during inspection it was observed that ETP installed at workshop was not in operation and untreated water was discharged outside.</i></p>

- (2) In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- (3) You are advised to rectify the above violations immediately and intimate the position in this office within (Forty Five Days) from the date of issue of this letter.

Yours faithfully,




(Chandresh Bohra)

Deputy Controller of Mines  
Nagpur Regional office

Copy to :

1. The Controller of Mines(CZ), Indian Bureau of Mines, Nagpur
2. The Director, Directorate of Geology and Mining, Government of Maharashtra, Khaniz Bhawan,27, Shivaji Nagar, Cement Road, Nagpur-440010(Maharashtra)

  
(Chandresh Bohra)  
Deputy Controller of Mines  
Nagpur Regional Office