# INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

#### Review and updation of Mining Plan REPORT

#### Chennai regional office

Mine file No: TN/TNL/LST-79.MDS Mine code: 38TMN15084

(i) Name of the Inspecting : AQ42 ) A.S.SANJEEVA RAO

Officer and ID No.

(ii) Designation : Junior Mining Geologist

(iii) Accompaning mine : Mr S.Murali, Lessee &Mr Suresh, Rep of QP.

Official with Designation

(iv) Date of Inspection : 21/10/2022
(v) Prev.inspection date : 31/07/2018

PART-I : GENERAL INFORMATION

. (a) Mine Name : PANDAPULI(4.095HA)

(b) Registration NO. : IBM/5363/2011

(c) Category : A Other than Fully Mech.

(d) Type of Working : Opencast

(e) Postal address

(f)

State : TAMIL NADU

District : TIRUNELVELI

Village : PANDAPULI

Taluka : SANKARANKOVIL

Post office : PANDAPULI

Pin Code : 626117

FAX No. : 9443380293

E-mail : muralilimestone@yahoo.co.ii

Phone : 9443380293

Police Station : Pandapuli

(g) First opening date : 14/12/1998

(h) Weekly day of rest : SUN

2. Address for : Mr. S A MURALI,

correspondance 100/1, ALAGAI NAGARRAJAPALAYAM,

RAJAPALAYAM-626117

3. (a) Lease Number : TMN0644

(b) Lease area(c) Period of lease20

(d) Date of Expiry : 13/12/2018

4. Mineral worked : LIMESTONE Main

PAGE: 2

5. Name and Address of the

Lessee : M/S.MURALI ENTERPRISES

100/1, ALAGAI NAGAR, RAJAPALAYAM TIRUNELVELI

TAMIL NADU Phone:
FAX:

Owner : M/S.MURALI ENTERPRISES

100/1, ALAGAI NAGAR, RAJAPALAYAM TIRUNELVELI

TAMIL NADU Phone:
FAX:

6. Date of approval of Mining : Mining Scheme rule 12 MCDR1988

Plan/Scheme of Mining

: Mining Scheme rule 12 MCDR1988 26/04/2012 Mining Scheme rule 12 MCDR1988 14/01/2015 MP review under 17(1) MCR 2016 27/08/2018

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

## Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	6 no of core drills.	Not carried out.	Mine dicontinued operations since 2018 for want of EC.
1b	Exploration over lease area for geological axis 1 or 2		G-1	Nil.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Not specified.	Nil.	Nil.
1d	Balance area to be explored to bring Geological axis in 1 or 2	Nil.	Nil.	Nil.
1e	Balance reserve as on 01/04/20	356,017.50Ts	356,017.50Ts	As on 1.4.2022.
1f	General remarks of inspecting officers on geology, exploration etc		ML area has been proved upto 25m as per approved ROMP.	<del>-</del>

# Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	Between N1032300- N1032350 and E0780120- E0780170	Mine not worked in the year 2021-22.	Nil.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	benches	Separate benches proposed: Topsoil &OB- 1 Ore -1	Nil.
2c	Stripping ratio or ore to OB ratio	1:0.42	Not worked in the year 2021-22.	Mining operations discontinued since 2018 for want of EC.
2d	Quantity of topsoil generation in m3	Nil.	Nil.	Nil.

2e	Quantity of overburden generation in m3	Nil.	Nil.	Nil.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc		Mine not worked in the year 2021-22.	Twop existing pits length ranging 90m-60m and width ranging from 15mto 80m and depth 6m-8m.

## Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	One.	Not worked during the year 2021-22.	Mine discontinued operations since 2018.
3d	Quantity of mineral reject generation	7131Ts	Nil.	Nil.
3e	Grade of mineral rejects generation and threshold value declared.	Not specified.	Nil.	Mine not worked during the year 2021-22.
3f	Quantity of sub grade mineral generation.	No generation of sub grade.	Nil.	Nil.
3g	Grade of sub grade mineral generation	No generation of sub grade.	Nil.	Nil.
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanized	Mine not in operation.	Nil.
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No.	Nil.	Nil.
3j	Provision of drilling and blasting in mineral benches	Proposed ,drilling by using compressor and Jack hamaer combination for blasting.	Mine not worked in 2021-22.	Nil.

3k	Provision of mining machineries in mineral benches	Yes, with 6m height and 6m width.	Maintained as proposed.	Mine not worked in 2021-22.
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Yes.	Over burden layer is thin 1m-2m range.	Nil.
3m	Total area covered under excavation/pits	1.15ha	1.15ha	Nil.
3n	Ore to OB ratio for the pit/mine during the year.	1:0.42	Mine not worked in 2021-22.	Nil.
30	Total area put in use under different heads at the end of year	1.91ha.	1.91ha.	Nil.
3р	Production of ROM mineral during the last five year period as applicable	2017-18- 14820Ts 2018- 19:14820Ts 2019- 20;23400Ts 2020- 21:23850Ts 20201- 22:23770Ts	2017-18-0Ts 2018-19:0Ts 2019-20;0Ts 2020-21:0Ts 20201-22:0Ts	Mine not woking for want of EC.
3q	General remarks of inspecting officers on method of mining etc.		Mine not woking for want of EC since 2018.	

#### Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Yes.	No mining operations during 2021-22.	Nil.
4b	Location of topsoil, OB and mineral reject dumps	N1032350- N1032250 and E0780200- E0780300	No mining operations during 2021-22.	Nil.

4c	Number of dumps within lease area and outside of lease area	Within lease - 1 dump.	One dump.	Nil.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	On non-mineralised area.	Non-mineralised area.	Nil.
4e	Number of active and alive dumps.	One.	One.	Nil.
4f	Number of dead dumps.	Nil.	Nil.	Nil.
4g	Number of dumps established.	Nil.	Nil.	Nil.
4h	Whether Retaining wall or garland drain all along dumps are there.	Nil.	Nil.	Nil.
4i	Length of Retaining wall or garland drain all along dumps	No proposal.	Nil.	Mine not in operation during 2021-22.
4j	Number of settling ponds	Nil.	Nil.	Nil.
4k	Specific comments of inspecting officer on waste dump management		One dump maintained in lease area.	Mining operations discontinued since 2018 for want of EC.

### Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal.	Nil.	Mine not reached ultimate level.
5b	Area under backfilling of mined out area	No proposal.	Nil.	Nil.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposal.	Nil.	Nil.

5d	Total area fully reclaimed and rehabilitated	Nil.	Nil.	Nil.
5e	General remarks of inspecting officers on backfilling and reclamation etc.		Mine has not reached ultimate level.	Nil.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Nil.	Nil.	Mining operations discontinued since 2018 for want of EC.
6b	Area available for rehabilitation (ha).	No proposal.	Nil.	Nil.
6c	afforestation done (ha).	No proposal.	Nil.	Nil.
6d	No. of saplings planted during the year	50nos.	50nos.	Nil.
бе	Cumulative no .of plants	150 plantation.	100 plantation.	Nil.
6f	Any other method of rehabilitation	No proposal.	Nil.	Nil.
6g	Cost incurred on watch and care during the year	6000/-	1000/-	Nil.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	No proposal.	Nil.	
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No proposal.	Nil.	Nil.

6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No proposal.	Nil.	Nil.
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No proposal.	Nil.	Nil.
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No proposal.	Nil.	Nil.
бm	Compliance of rehabilitation of waste land within lease (i)afforestation	No proposal.	Nil.	Nil.
6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	No proposal.	Nil.	Nil.
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	No proposal.	Nil.	Nil.
6p	Compliance of environmental monitoring (core zone and buffer zone)	Yes.	Nil.	Mining operations discontinued since 2018 for want of EC.
6q 	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.		No proposal for reclamation and rehabilitation for the year 2021- 22.	Mining operations discontinued since 2018 for want of EC.

### Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks

7a	ROM Mineral dispatch or grade-wise sorting within lease area		No mining operation during 2021-22.	Nil.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Mechanical.	Nil.	No mining operations during 2021-22.
7c	Different grade of mineral sorted out at mines.		No mining operation during 2021-22.	Nil.
7d	Any beneficiation process at mines .	No proposal.	Nil.	Nil.
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues		No mining operations during 2021-22.	No mineral conservation problem in the mine.

#### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	No proposal.	No mining operations during 2021-22.	Nil.
8b	Concurrent use or storage of topsoil	No proposal.	Nil.	Nil.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Yes.	No mining operations during 2021-22.	Nil.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposal.	Nil.	Nil.

8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No proposal.	Nil.	Nil.
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	120 plantation.	120 plantation.	Nil.
8g	Survival rate	70%	About 50%	Nil.
8h	Water sprinkling on roads to control airborne dust	Yes.	No mining operations during 2021-22.	Nil.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area		Plantation has been done on the lease boundaries.	Nil.

# Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Returns are submitted.	Nil returns are being submitted. AR for 2021-22 also submitted.	Mine is not working for want of EC since November 2018.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mr K.BALASUBRAMAN IAN,Manager.	As per Part - I of AR 2021-22.	Mine is not working for want of EC since November 2018.
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	current (0/C) Workings- 2.04ha;Used for waste	Furnished under Part - I of 11.	Nil.

9d	Scrutiny of Annual return on afforestation	under Part	NII.	Plantation along the lease boundary.
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	under Part - V		Mine not in operation for want of EC.
9f	Scrutiny of Annual return on ROM stock and/or graded ore	per Part - VI	Nil.	Mine not in operation since 2018 for want of EC.
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost		Nil.	Mine not in operation since 2018 for want of EC.
9h	Scrutiny of Annual return on fixed assets		Nil.	Explained to lessee to furnish details .
9k	Scrutiny of Annual return on mining machineries	-	Nil.	Mine not in operation since 2018 for want of EC.

# Details of violations observed during current inspection and compliance position of violation pointed out

Violation	n observed	Show co	ouse position
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on
MCDR17 Rule 11(1)	01/11/2022		

Date :

(A.S.SANJEEVA RAO)

Indian Bureau of Mines