



भारत सरकार / Govt of India
खान मंत्रालय / Ministry of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines
हैदराबाद क्षेत्रीय कार्यालय / Hyderabad Regional Office



)-29555603/29554603

E-mail: ro.hyderabad@ibm.gov.in

No. AP/CDP/LST-22/HYD

Room No.603, 6th Floor,
CGO Towers, Kavadiiguda,
Secunderabad – 500 080.
Date: 23.02.2021

To

Nominated Owner/Agent
Bharathi Cement Limestone Mine
M/s. Bharathi Cement Corporation Limited,
8-2-626, Reliance Majestic, Road No-10,
Banjara Hills, Rangareddy Dist,
Tengana-500034.

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Bharathi Cement Limestone Mine (38APR04015) over an area of 632.278 ha in Sunkesula & Tippalur of Yerraguntla Mandal and Nallalingayapalli, Turkapalli, Sadipiralla, Jamdapur of Kamalapuram Mandal, YSR Kadapa district, Andhra Pradesh.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 20.02.2021 in the presence of Shri.K.Sudhakar, Mine Manager and Shri. V.Vijaya Bhaskar, Geologist.

Rule No.	Nature of Violations observed
11 (1)	<p>No holder of a mining lease shall commence or carry out mining Operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines.</p> <p>Your Review of Mining Plan document was approved vide letter No. 659(549)/LST/2006/HYD dated 28/05/2020 and following deviations have been observed:</p> <p>i. It was proposed to excavate top soil and stock separately in the southern side of the working pit i.e, at location E5663-N10007, E5711-N10150, E5650-N10150 & E5600-N10077 during the year 2020-21. However during inspection it was noticed that top soil has been stacked on the 1st bench in the western side of the working pit.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of MCDR, 2017. Further, inability to comply the provision of Rule 11(1) is liable for suspension of mining operations under 11(2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

(Madhu Sudhan Yadav. M)
Assistant Controller of Mines

Copy for information:

1. खान नियंत्रक (दक्षिण क्षेत्र), भारतीय खान ब्यूरो, बैंगलोर.
2. The Director, Department of Mines & Geology, Government of A.P.
3. The Assistant Director of Mines & Geology, Yerraguntla, YSR Kadapa district, Government of A.P.

□□□ □□□□ □□□□ . ए म (Madhu Sudhan Yadav M.)
सहायक खान नियंत्रक/ Assistant Controller of Mines