



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय



OFFICE OF REGIONAL CONTROLLER OF MINES

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर
बेंगलुरु -560022

दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

सं/No.: KNT/RCH/G-1/BNG

Mine-code: 27KAR16001

दिनांक/Dated: 03/08/2022

To,
Sri. M. Prakash,
Executive Director (I/C),
M/s The Hutti Gold Mines Co. Ltd.,
Hutti Camp, Hutti
Taluka-Lingasugur,
Dist.- Raichur-584115.
Karnataka

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Hutti Gold Mine, ML 2671 over an extent of 528.35 ha(as per lease deed), in Hutti Village, Lingasugur Taluk , Raichur District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 19.07.2022 by the undersigned along with Shri K. Srinivas, JMG in presence of Dr. S. K. Solankar, Geologist, Sri A. Ghosh, Mine Manager, Sri A. Suryavanshi, Mining Engineer and other mine officials:

Rules	Nature of Violations observed
11 (1)	<p>The Modifications to the approved Review and updation of Mining Plan was approved by IBM vide letter no. 279/356/92/BNG/442 dated 30/09/2020, for the period 2020-21 to 2022-23. The deviations observed in mining operation vis-à-vis approved document are given below.</p> <p>i) It was observed that against the total proposed development of 8966 m (4669 m on lode & 4297 m off lode development) only 3765 m (1013 m off lode & 2752 m on lode) actual development has been carried out which is 58 % less than the approved proposal for the year 2021-22.</p> <p>ii) It was observed that only 44,761 tonnes of waste have been generated against the proposed waste generation of 2, 02,860 tonnes for the year 2021-22 which is 78 % less than the approved proposal.</p> <p>iii) The filling was proposed in stope blocks, RP-5 & 6(1500 to 1700 level, Strike Reef H/w), M7-2 block (1500 to 1600 level, Middle Reef) & R-2-R2 Extn(1000 level to 13 Interlevel, Strike Reef Hang wall) against which actual filling have been carried out in RP-5 & 6(1500 to 1700 level, Strike Reef H/w), S-1,S-2 & S-3 block(16th Inter level to 18th inter level, Zone-I Reef) & 7P & 8P block(1700 level to 1900 level ,Oakley's</p>

	<p>reef). Also against the proposed filling quantity of 2, 11,200 tons (including Black Rock & Hydraulic stowing) only 54,340 tons (Hydraulic stowing) have been carried out.</p> <p>iv) It was observed during inspection that Retaining wall of 1100 m is proposed for the year 2021-22 between tailing dumps D-2 & D-3, against which no work has been carried out.</p> <p>v) 2000 nos. of saplings plantation were proposed in the area near active tailing dump D-3 for the year 2021-22 against which only 1000 nos. of sapling plantations have been carried out. Also the plantation along 7.5 m safety zone of the mine lease, along the active tailing dump-D-3 has not been maintained.</p>
--	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.
3. Sri T. Ravikumar, Agent, The Hutti Gold Mines Co. Ltd., Hutti Camp, Hutti Taluka- Lingasugur, Dist.- Raichur-584115- tn.ravikumar@ka.gov.in

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines