

## भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय



## OFFICE OF REGIONAL CONTROLLER OF MINES

दूरभाष: (080) 39505368 / 29720499 Email ID: ro. bangalore@ibm.gov.in 29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड, गोरगुंटापाल्या येशवंतपुर,

बंगल्र -560022

No. KNT/BLR/Mn/ 39A /BNG

Mine Code 40KAR03014

Date: 30/09/2022

To,

M/s.The Sandur Manganese & Iron Ores Ltd., Deogiri (Post)-583 112, Sandur (Taluk), Bellary (District), Karnataka.

shridharhegde@sandurgroup.com, eps@sandurgroup.com

Subject: Violation of provisions of MCDR 2017 in respect of your in respect of your Ramgad Manganese & Iron Ore Mine (ML No. 2679)over an area of 139.20 Ha having mine code 40KAR03014 in Deogiri village, Sandur Taluk, Ballari District, Karnataka state.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 13.09.2022 by the undersigned along with Shri. Gangadhar Bhakat, AME in the presence of Shri B Sahu, General Manager Mines, Bharath Kumar, Manager & Mining Engineer and other officials of your mine.

Rules
11 (1)

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

SD/-(Dr. Omkesha Murthy. M.G.) Regional Mining Geologist

## Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-Regional Mining Geologist Indian Bureau of Mines