



भारत सरकार/ GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बंगलुरु -560022

सं.KNT/BLR/FE/414/BNG-Vol-II दिनांक: 16/09/2022

सेवामें/To,
Sri. K.S.VINAYAK, (Nominated Owner)
M/s. VeerabhadrappaSangappa & Company,
No.2/138, VESCO HOUSE, Ballari Road,
Sandur-583 119,
Ballari District, Karnataka State.
vescopd028@gmail.com / smandal078@gmail.com

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Ramanamalai Iron ore Mine (ML No. 2296) having Mine code: (30KAR03138,)** over an area of **53.16 Ha** (as per CEC) in RM Block village, Sandur Taluk, Ballari District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by the undersigned along with Sri. H.M.Shivakumar-Assistant Mining Engineer in presence of Sri. Shanmukhappa Mandal, Sr. Manager & Mining Geologist and Sri. Nandakumar H.M - Mines Manager on 24/08/2022.

Rule	Nature of violations observed
11 (1)	<p>The Mining operations are required to be carried out in accordance with the approved Mining Plan document vide letter no. 279/478/95/BNG dated 11/12/2020, However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>(i) For the Year 2021-22- It was proposed for Development work with 4,16,230 Tonnes of waste removal. However only 3, 33,400 Tonnes of Wasteremoval (Development) is achieved during the year with - 20 % deviations from the proposed quantityof Development.</p> <p>(ii) It is also observed for small workings in safety zone in North Eastern Part of the lease boundary between sections 4P-4P'.</p> <p>(iii)As per the aforesaid approved document, it is proposed to construct Garland drain of 75 mts length all along the dump. However the same has not been constructed so far.</p>

Rule 45(7)	<p>(i) As part -III-5 of the Annual Returns, Taxes and Cesses: the Amount of DMF and NMET contributions made during the year should be reflected under “(iii) (c) –others-specify”. Accordingly part VII for Cost of Production per tonne be corrected including Royalty, DMF & NMET.</p> <p>(ii) Part - V: General Geology & Mining (Sec 1/2 for Iron Ore): Under 4.2 (C) open cast Mining operations during the year: Total quantity of Overburden/Waste removed during the year (tones) is shown as ‘0’ is incorrect.</p> <p>(iii) As per part VII of the Annual Returns submitted, DMF & NMET paid details have not been furnished and accounted for arriving at the cost of Production.</p>
-------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

04. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(सुरेश प्रसाद/Suresh Prasad)

क्षेत्रीयखाननियंत्रक/Regional Controller of Mines
भारतीयखानब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ/ Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

(सुरेश प्रसाद/Suresh Prasad)

क्षेत्रीयखाननियंत्रक/Regional Controller of Mines
भारतीयखानब्यूरो/Indian Bureau of Mines