



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.KNT/BLR/FE/455/BNG/VOL-I Mine-code:30KAR03160दिनांक/Dated:09/02/2023

To,
Shri Syed Ahmed,
Nominated Owner & Managing Partner
Ramgad Iron ore Mine
M/s. Zeenath Transport Company.
Zeenath House, Cowl Bazar
Ballari District, Karnataka-583 102
Email id-ztco2000@yahoo.com

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of yourRamgad Iron ore Mine, ML 2547 of M/s.Zeenath Transport Company over an extent of 49.73ha, in Ramgad Village, SandurTaluk, Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 18.01.2023by undersignedin presence of ShriJ. Srikanth, Mine Manager& Mining Engineer, Shri Rashmi Ranjan Sahu, Geologist and other mining officials:

Rules	Nature of Violations observed
11 (1)	<p>Review and updation of Mining Plan was approved by IBM vide letter no. 279/419/94/BNG dated 08/11/2016, for the period 2017-18 to 2021-22& 279/419/94/BNG dated 03/01/2022 for the period 2022-23 to 2026-27.The deviations observed in mining operation vis-à-vis approved document are given below.</p> <p>i)Mineral stacks were found at sec G-G' (N- 1668137, E- 660646) which is not the proposed location for mineral stacking. Further development of benches systematically from 974mRL to 959 mRL at Section G-G',as proposed for year 2022-23have not been carried out as per proposal.</p>

34A.(2)	The satellite image has not been submitted in accordance with the Standard Operating Procedures under sub rule (2) of rule 34A of MCDR, 2017 for submission of Satellite Imageries. The submitted image resolution is 1.6 m which is not as per the SOP. Also, the establishment of Ground Control points, Data output and formats, Output data submission form for satellite image for the year, have not been done in accordance with the SOP.
----------------	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines