



भारत सरकार  
GOVERNMENT OF INDIA  
खान मंत्रालय  
MINISTRY OF MINES  
भारतीय खान ब्यूरो  
INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय  
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,  
गोरगुटापाल्या येशवंतपुर,  
बेंगलुरु -560022

No. KNT/BLR/FE/ 492 /BNG Vol-II

Mine Code 30KAR03183

Date: 11/11/2022

सेवामें/To,

M/s.JSW Steel Limited,  
JSW Mining office,  
Near Yalur Cross, Vidyanagar Works  
P.O. Vidyanagar -583 275, Bellary (District),  
Karnataka,

[jayant.acharya@jsw.in](mailto:jayant.acharya@jsw.in), [sunil.singh@jsw.in](mailto:sunil.singh@jsw.in), [nataraja.belegere@jsw.in](mailto:nataraja.belegere@jsw.in)

Subject: Violation of provisions of MCDR 2017 in respect of in respect of 'DEVADARI IRON ORE MINE' (ML. No 006) of M/s.JSW Steel Limited over an extent of 100.54 Ha having mine code of 30KAR03183 located in Lakshmeepura Village, Sandur Taluk, Bellary District of Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 20.10.2022 by the undersigned in the presence of S/shri Nishant Kumar Sharma (Mine Manager), Vivek G (Mine Geologist), Sridhar B. (Mine Surveyor), B P Umapati (Mining Engineer) and Nataraja BD- Manager (Geology) and other officials of your mine.


Rules	Nature of Violations observed				
34(A)	In the Digital Aerial Images submitted under Rule 34(A), it is observed that the processed Drone survey output data submitted to Indian Bureau of Mines does not meet the parameters specified in the SOP for submission of Digital Aerial Images under the said Rule. The deviations in the data submitted is as follows:				
	Sl. No.	Data type	Check Point parameters as per SOP	Submitted in proper format (Yes/No)	Remarks
	1	Orthomosaic image of lease area including 100m buffer zone.	Resolution 5cm	No	Resolution 6cm.
	2	Digital Elevation Model (3D) – DTM	Resolution 15cm	No	Resolution 30cm.
	3	GCPs data	.shp in GCS WGS 1984	No	submitted in PCS
		GCPs data	No. of GCPs	5	1. GCP_03 is outside the lease bounde 2. The details of permament GCPs considered have not been submitted

					either is excel sheet or in .shp file.
		c)Subgrade dump,	.shp (UTM in WGS 84)	No	Not submitted
	4	f)Backfilled, reclaimed and rehabilitated area	.shp (UTM in WGS 84)	No	Not submitted

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.


03. Further, violation of Rule 34(A), you are advised to rectify the above violations immediately and re-submit the data to this office and also to Chief Mining Geologist, Indian Bureau of Mines, Nagpur **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

  
(Dr. Omkesh Murthy. M.G.)  
Regional Mining Geologist

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

  
Regional Mining Geologist  
Indian Bureau of Mines