



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines

Show Cause Notice
By Speed Post



o/c

Phone No.: (0651) - 2242889
Fax No. : (0651) - 2242903
E-Mail : ro.ranchi@ibm.gov.in

318/B, Road No-3,
Ashok Nagar, Ranchi,
Jharkhand - 834 002

No. BIH/ROH/LST/346/RRO

38BHR22015

Date: - 02.03.2022

To,
Shri. Sanjay Kumar Singh (HOD-Mines),
M/s. Dalmia DSP Ltd (Formerly:- Kalyanpur Cements Ltd),
P.O.Banjari,
Rohtas District, Bihar - 821 303

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of Murlipahari Limestone Mine, over an extent of 53.378 hectares situated in Murlipahari Village, Rohtas District, Bihar State - Reg.

Ref:- 1) Violation Lr.No. BIH/ROH/LST/346/RRO dated 03/01/2022
2) Your Reply Lr. No. Nil dated 16/02/2022

Sir,

Undersigned inspected your above mine on **01.12.2021** along with Shri. B.L. Kisku, AME, IBM, Ranchi in presence of the mine officials Shri. Sanjay Kumar Singh (HOD-Mines) and this office Violation letter number BIH/ROH/LST/346/RRO dated 03/01/2022 was issued under Mineral Conservation & Development Rules, 2017.

Rule No.	Nature of Violations observed
11(1)	<p>The mining operations in the Lease area are not carried out as per the approved Review of mining plan letter no. RAN/ROH/LST/MP-01/2018-19 dated 16.05.2018.</p> <p>a) There is no proposal to work on the eastern side of the lease area during this approved plan period, whereas during inspection it has noticed that working has carried out in un-proposed area nearer to Borehole M-6, M-7, NM-7 & NM-3. It has been noticed that dump has been re-handled near to the Borehole M-6 & M-7, which is not in proposal.</p> <p>b) It is proposed to keep all the benches of height 6m each, whereas in the field it is observed to be more than the proposed height of 6m.</p> <p>c) There is no proposal to form new dump on SE side (near to Borehole M-8 & NM-13) of lease area, against that dump has been formed.</p> <p>d) It is proposed to work at 143m RL nearer to Borehole NM-4 during 2021-2022, whereas during inspection it was working at 120m RL.</p>

भेजित
ISSUED

[Handwritten signature]
3/3/22

1. Your reply vide letter No. Nil dated 16/02/2022 received in this office has been examined and reply given for compliance of Rule 31(4) of MCDR 2017 is found satisfactory. However, it has been found that even after lapse of **45 (Forty Five) days** from the issue of violation letter, the violations for the **Rule 11(1) of MCDR-2017, remain to be continued.** Hence the following violation stands.
2. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under **Rule 62** of MCDR, 2017.
3. The Mining operations can be suspended under **Rule 11(2)**, if compliance of Rule 11(1) is not found satisfactory.
4. You are therefore, directed to show cause within a period of **30 (Thirty) days** as to why you should not be prosecuted for the above offence and/or why mining operations shall not be suspended as per provision of MCDR, 2017.
5. Please note that no further notice will be given to you in this regard.

Yours faithfully



2/3/22

G.S.Kannan
Senior Mining Geologist

o/c

Copy for information to:

1. **The Director (Mines)**, Department of Mines & Geology, Govt of Bihar, 1st floor, Vikas Bhavan, Patna – 800 015.
2. **The Controller of Mines (EZ)**, Indian Bureau of Mines, Block-CP, Plot No.13, Salt Lake, Sector-V, Kolkata- 700 091.



2/3/22

G.S.Kannan
Senior Mining Geologist

o/c