



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.: KNT/BLR/Fe/491/BNG/Vol-I Mine-code: 30KAR03182

दिनांक/Dated: 1/03/2021

To,
Dr. Vinod Nowal,
Nominated Owner, Nandi Iron ore Mine
M/s JSW Steel Ltd,
JSW Mining Office, Near Talur Cross
Vidyanagar (Post), Toranagallu, Sandur Taluk
Bellary Dist, Karnataka-583275

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Nandi Iron ore Mine, ML 0005 of M/s JSW Steel Ltd over an extent of 21.03 ha (as per lease deed), in Malagolla Village, Sandur Taluk , Bellary District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 17.02.2021 by undersigned in presence of Shri Vinodh Kumar NR, Mine Manager & Mining Engineer, Shri Brajesh Kumar, AGM Mines, Shri Nataraja B, Geologist and other mining officials:

Rules	Nature of Violations observed
11 (1)	Mining plan was approved by IBM vide letter no. 279/1089/2017/BNG/417 dated 16/02/2017, for the period 2018-19 to 2022-23. The deviations observed in mining operation vis-à-vis approved document are given below. i) Total 20,000 nos. saplings to be planted in Greenbelt development & area under encroachment against which only 1160 nos. of total saplings are planted for the year 2019-20.
28(1)	It was reported during inspection that the Mine was not in operation since Dec-2019. The notice of temporary discontinuance of work in mines has not been sent as per the provision of this rule in Form-E.
29	It was reported during inspection that mine is under operation after temporary discontinuance on 17.02.2021. The intimation of reopening of mine after temporary discontinuance in Form-C has to be submitted as per the provision of this rule.
55	A whole time 'Geologist' has not been appointed as per the provision of this rule.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines